DeKalb County RECEIVED BEOR CLAR RECEIVED Clark Harrison Building 330 W. Ponce de Leon Ave Decatur, GA 30030
By Rachel Bragg at 9:55 am, Mar 29, 2021
Chief Executive Officer DEPARTMENT OF PLANNING & SUSTAINABILITY Director Michael Thurmond Andrew A Paleon ALCE Andrew A Paleon ALCE
Application for Certificate of Appropriateness
Date Received: Application No.:
Address of Subject Property: 1207 Oakdale Rd NE Atlanta GA 30307
Applicant: Harold - Linda Jensen E-Mail: hmarkjenseneme.com
Applicant Mailing Address:
Applicant Phone(s): 678 469 554 Fax:
Applicant's relationship to the owner: Owner Architect: Contractor/Builder Other
Owner(s): Harold Mark Jensen E-Mail: hmarkjenseneme.com
Linda Jensen E-Mail: Genseal carrotate partners
Atlanta GA 30307
Owner(s) Telephone Number: 678 469 5541
Approximate age or date of construction of the primary structure on the property and any secondary structures affected by this project:
Nature of work (check all that apply):
New construction □ Demolition □ Addition Moving a building □ Other building changes □ New accessory building ★ Landscaping Fence/Wall ← Other environmental changes □ Sign installation or replacement □ Other □
Description of Work: Repair + Restore Main house structure to required building codes, Replace bumpout on right side with a tiered double bump out Restore landscape w/ specified plantings aligned to druid hills/ Dekalb + State guildelines. Plant 3 new canopy trees in trant
Yard, Kestore Bridge and stove fireplace,

This form must be completed in its entirety and be accompanied by supporting documents, such as plans, list of materials, color samples, photographs, etc. All documents should be in PDF format, except for photographs, which may be in JPEG format. Email the application and supporting material to <u>piansustain@dekalbcountyga.gov</u> An incomplete application will not be accepted.

H Mart Signature of Applicant/Date Revised 10/5/2020



Chief Executive Officer	DEPARTMENT OF PLANNIN	G & SUSTAINABILITY	Director
Michael Thurmond			Andrew A. Baker, AICP
	Application for Certificate	e of Appropriateness	
Date Received:	Application No	.:	
Address of Subject Property:	1207 Oakdale Re	LNE Atlanta	GA 30307
Applicant: Harold?	Linda Jensen	E-Mail: hmarkje	enseneme, com
Applicant Mailing Address:			
Applicant Phone(s):78	3 469 554	Fax:	
Applicant's relationship to the	owner: Owner 🖉 Architect: 🗆 Cont	actor/Builder 🗆 Other 🗆	
Owner(s): Harold	Mark Jensen	E-Mail: <u>hmark</u>	<u>Jensen@me.com</u>
Linda	Jensen	E-Mail: Gensee	e carrotake partners
Owner(s) Mailing Address:	1207 Oakdale Rd Atlanta GA 30	NE 307	
Owner(s) Telephone Number	678 469 5541		
Approximate age or date of co project:93	Distruction of the primary structure on the structure of	he property and any secondary	structures affected by this
Nature of work (check all that	apply):		
New construction Dem New accessory building Sign installation or replacement	olition □ Addition Moving a b Landscaping Fence/Wall ent □ Other □	uilding Other building cha Other environmental changes	nges □ □
Description of Work: <u>Repair + Restor</u> <u>Replace bumpa</u> <u>Restore lands</u> <u>Dekalb + Stat</u> <u>Vard. Resto</u>	e Main house struct out on right side W cape W/ specified p e guillelines. Plant: e Bridge and stone	ure to required b ith a tiered du lantings aligned to 3 new canopy tre fireplice,	vilding codes, ble bomp out o druid hills/ ges in trant

This form must be completed in its entirety and be accompanied by supporting documents, such as plans, list of materials, color samples, photographs, etc. All documents should be in PDF format, except for photographs, which may be in JPEG format. Email the application and supporting material to <u>plansustain@dekalbcount+ga.gov</u> An incomplete application will not be accepted.

Val Signature of Applicant/Date Revised 10/5/2020

Letter from the Owners of 1207 Oakdale RD, Atlanta, GA 30307

As owners of the property at 1207 Oakdale, we would like to restate our intent to restore our historical home to required building codes while making it a safe place to raise our family.

We have consulted numerous professionals, including architects, engineers, and building contractors over the past two years. These professionals have highlighted significant structural issues with the foundation of this home and have proposed potential solutions to rebuild the damaged foundation.

Additionally, we will rehabilitate our landscape aligned to Olmstead's vision, with plantings of native species with careful environmental, sustainable and renewable practices. We want to restore the house and gardens to the original French influenced design. We both have an appreciation for the wooded property and consider it a slice of nature in the city.

In order to properly correct the structural items identified by licensed engineers and building contractors the house will need to be carefully supported and lifted by a professional historic house lifting company.

The recommendation of the engineers and contractors are to lift and move the house 6 feet forward and raise it at least 1 foot given the current condition and placement on the property. We have removed this request to ease the application process but please consider adding this flexibility to the approval notes of the application given the recommendations.

- 2 different structural engineering reports are presented. The reports were generated based on visual inspection. Both engineers state they cannot confirm the condition for what they do not see without performing some form of destructive testing.
- Their conclusion was very similar....." the house is unsafe, and when the required building codes and repairs are completed to the house very little to none of the existing house will remain".
- The landscape of my house was ruined by a contractor and we are in legal litigation due to the mishandling and the damage that was caused.
- The exterior brick of the house had original limewashing applied to help create a "French influence" as was stated in original documentation of the house. Since then, it was improperly painted 3 times. This has sealed in moisture and caused other damaging effects to the house.
- We have presented a house plan striving to keep the original structure, scale and style aligned with the original house and similar houses in the druid hills neighborhood.

Items Confirmed NOT ORIGINAL

- 1. Exterior Brick was not originally painted but now has 3 coats of paint covering the entire exterior brick.
- 2. Front of house Stoop, railings, steps, door and walkway
- 3. At the right side, basement level, modern siding had been used for the exterior wall covering.
- 4. Front facing and right-side facing windows on right side bump
- 5. Front Shutters on main floor
- 6. The addition bump out at the right rear main floor
- 7. The retaining wall at the right side of front house
- 8. Rear stairway and left rear patio
- 9. Slate roof was replaced with poor quality asphalt shingles
- 10. Front stone walkway
- 11. Main floor windows on left side rear
- 12. All basement windows and doors
- 13. Basement wall in rear and side covered rear facing basement door and 2md floor window
- 14. Cement wall near driveway, creek and left rear of house
- 15. Left side rear windows main floor kitchen were removed, and wall was bricked up with different brick

Example of a restored house using known limewashed Brick in Atlanta in the 1930's

https://www.spitzmillerandnorris.com/old-buckhead-estate





03/03/2021

Mr. Mark Jensen Carrot Cake Partners LLC 815 Southern Shore Drive Peachtree City, GA 30269

RE: 1207 Oakdale Rd NE, Atlanta Ga 30307

Dear Mr. Jensen.

Upon your request we have reviewed the following reports and observations made from different consultants, and trades with respect to the subject property.

- Keystone Structural Engineering Dated 3/1/2021
- Construction Services, Inc (CCSi): forensic Dated 02/02/2021
- OnCall Electric: electrical Dated 01/25/2021
- VItalAir Service: HVAC Dated 01/25/2021
- Enviroprobe, LLC: Asbesto & Lead Dated 01/07/2021
- Property Disclosure Statement Dated 02/19/2019

Furthermore, I conducted a site visit on February 25th, 2021 to verify first-hand the condition of the existing building and validate or not the observations made by other parties. Now, considering the current state of the home and proposed scope of work I find the subject property to be beyond repair. In fact, I believe that any attempt made to restore the property will pose a great risk to the safety and well-being of my crew, and trade partners. There not only serious structural matters present that make the home unsound but any attempt in disturbing the current condition of home could potential release unwanted asbestos, lead, and spores into the dwelling that might be entrapped in on-tested cavities or concealed in different areas creating a health hazard to any person.

Please feel free to contact me if you any questions or concerns

Luis Imery Owner 770-294-1010 limery@imerygroup.com www.imerygroup.com

Construction Consulting Services, inc.

(Xi

O | 770.475.1027 ccsiengr@bellsouth.net 565 Laurel Oaks Lane Suite B100 Milton, GA 30004 Structural Engineering Forensic Studies Building Code Analysis Inspections Building Sciences

www.ccsiengineers.com

February 2, 2021

Mark Jensen Carrot Cake Partners LLC Via email only

Re: 1207 Oakdale Road

Mr. Jensen:

At your request observations were made this past January 28th, 2021, of the property listed above.

The observations are limited to what could be visually inspected. Destructive or invasive testing was not performed. The mechanical, electrical and plumbing systems are not part of this report. The observations focused primarily on the items noted in this report. Other items may exist that are defects or code violations.

Any references to a position or place for the house are to be taken as standing at the street facing the house. This is for exterior and interior references.

References

- 1) 2018 International Residential Code with State of Georgia Amendments (IRC)
- 2) 2018 International Residential Code with State of Georgia Amendments (IBC)
- 3) 2015 International Energy Code (IEC) with State of Georgia Amendments (IEC)
- 4) Georgia Department of Community Affairs Website
- 5) Residential Construction Performance Guidelines, National Association of Homebuilders
- 6) National Design Specification for Wood Construction. American Forest Products Association
- 7) Residential and Light Commercial Construction Standards
- 8) Brick Industry Association Technical Bulletins

Building Codes

The building codes are administered by the State of Georgia Department of Community Affairs. Under the rules and laws by the state, minimum standards or codes are established for construction. The enforcement of those codes is delegated to local jurisdictions. Those jurisdictions cannot reduce the requirements of the code they can only make the codes more restrictive. Any changes to the code by a local jurisdiction must be submitted to the DCA. The contractor, builder or owner must comply with the requirements of the code regardless of the local jurisdiction enforcement.

The IRC does not address repairs to damaged buildings as to when the existing structure must be upgraded to the current code requirements. The IRC does state that for items not addressed in the IRC that the IBC will be the governing code.

The IBC requires that when a "system" is repaired or changed, and the value of the construction exceeds 50% of the value of the existing system then all of the system must be upgraded to the current code. The IBC requirement is listed below.

3401.7 Existing system conformance. The extent to which the existing mechanical, electrical, plumbing and life safety systems shall be made to conform to the requirements of the State Minimum Standard Codes for new construction shall be as follows unless otherwise required by this section: 1. When the estimated cost of the new work is less than fifty percent (50%) of the replacement cost of the existing system, the new work shall be brought in to conformance with the requirements of the State Minimum Standard Codes for new construction. 2. When the estimated cost of the replacement cost of the existing system, the new work is equal to or greater than fifty percent (50%) of the replacement cost of the existing system, the entire system shall be made to conform to the requirements of the State Minimum Standard Codes for new construction. 3. For essential service facilities Occupancy Category IV type buildings as defined by Table 1604.5, when the estimated cost of the new work is equal to or greater than thirty percent (30%) of the replacement cost of the new work is equal to or greater than thirty percent (30%) of the replacement cost of the new work is equal to or greater than thirty percent (30%) of the replacement cost of the existing system, the entire system shall be made to conform to the requirements of the State Minimum Standard Codes for new construction. (Effective January 1, 2020)

The IEC requires that when a wall cavity is opened that the insulation must be upgraded to the current requirements. The same applies to the attic insulation. Once any work is done to the attic insulation all of the insulation must be graded to the current requirements.

Existing Conditions

Listed below is my understanding of the history of the house.

- 1. The original construction was completed in 1931.
- 2. The house has been unoccupied for some time.

Listed below are items that are of concern for the house.

<u>Basement</u>

- 1. There was structural damage to the slab near the HVAC equipment. Repair is needed for the slab. All of the openings in the slab should be sealed.
- 2. The foundation wall was damaged where a steel beam had been installed as a header. The beam had corroded, which in turn caused the brick to spall.
- 3. Decay for the following items was observed.
 - a. Several beams supporting the first floor.
 - b. The exterior band of the house
 - c. More than 40% of the floor joists had decay, splits, termite, or other damage and require repair or preferably replacement.
 - d. The floor decking had splits, structural damage, termite damage or water damage for approximately 30% of the decking.
- 4. Wood that was non-decay was in contact with the foundation and slab. Some of the plates and beam had decay due to contact with water and moisture.
- 5. The steel columns supporting the structure had been supported below the slab. The columns had extensive corrosion at their base.
- 6. At the right side of the house 2x6 floor joists were used to support the first floor. The joists were over span and need to be replaced or upgraded to meet the minimum span requirements of the IRC.
- 7. Termite damage was observed at the following locations.
 - a. Stairs from the basement to first floor]
 - b. Floor decking
 - c. House band at the foundation
 - d. Joists and beams throughout the first-floor framing system
 - e. Exterior wood walls
- 8. A basement was excavated to within three to four feet of the exterior foundation wall. The shear cut was supported by unreinforced 4" CMU (concrete block). The following items were observed.
 - a. The 4" CMU wall was failing. The wall had bowed and displaced at several locations.
 - b. The 4" CMU wall was not adequate to support the earth pressure and the pressure from the house footings. The wall did not have sufficient width, grout or reinforcing.
 - c. The shear cut had undermined the exterior foundation system and individual column footings.

- 9. A portion of the foundation system had been damaged at the right side of the house and requires repair.
- 10. Steel beams and their bearing plates had corroded, which in turn damaged the masonry that they bear on.
- 11. Interior walls, just inside the foundation walls, had decayed and will require replacement.
- 12. Both concrete and wood headers at the foundation walls had deterioration.
- 13. The masonry foundation had deterioration at many locations. The brick had spalled, eroded, and cracked.
- 14. Brick was missing from the foundation walls at critical corners.
- 15. The stairs from the basement to the first floor were not safe.
 - a. The stairs had winder treads that do not comply with the code.
 - b. The stairs were too narrow and do not meet the 36" width requirement.
 - c. The riser heights exceed the 3/8" tolerance within a flight of stairs.
 - d. The stairs lack any handrails.
 - e. The riser heights exceed the code requirement.
 - f. The stair system will have to be replaced. This in turn will require major modifications to the first-floor walls, floor framing and room layout.
 - g. Some of the stair components were not structurally adequate. This includes the stringers and the landing.
 - h. The stairs lack any wall covering for fire protection.
- 16. At many locations, the 2x4 ledge for the support of floor joists had cracked.
- 17. The HVAC ductwork, returns and some supply lines, were not insulated.
- 18. HVAC ductwork was in contact with the ground.
- 19. The thermostat for the HVAC system had been mounted to a decayed stud that leans against the ductwork.
- 20. Some of the plumbing appeared to be recent (within the last 20 years) and some of the original plumbing was in place.
- 21. Plumbing pipes had been terminated but not sealed.
- 22. Most likely the paint on the bottom of the floor system contains lead. Due to the obstructions of the HVAC, electrical, and plumbing systems it would be nearly impossible to abate.
- 23. The foundation walls and floor system lacked any insulation.
- 24. The electrical panel had exposure to soil and moisture.
- 25. The electrical system can be best described as a jumble of wiring. Both recent and what is believed to be original wiring was being used. It is my opinion the electrical system is not safe.
- 26. Some of the wiring was draped on the ground.
- 27. Many electrical junction boxes were open.
- 28. Receptable boxes were open and lack a plate.
- 29. Wiring for the switches were open and lack a plate.
- 30. The basement had experienced water infiltration. Most likely the foundation walls lack a footing drain and waterproofing system.
- 31. There were openings in the slab that would allow vermin, insects, radon, and water to enter the basement.
- 32. There was evidence of mold on the gypsum board paper surface.

<u>First Floor</u>

- 33. The stairs from the first floor to the second floor had many issues.
 - a. The stairs did not have the minimum 36" width.
 - b. The winders did not comply with the code requirement.
 - c. The guardrail did not comply with the code with regard to its height.
 - d. The stairs did not provide the minimum 80" headroom at the hallway from the foyer to the kitchen.
- 34. At the vast majority of the doors (interior and exterior) and windows diagonal cracks were present. This indicates settlement of the foundation system or the wood structure had decay or other damage causing compression of the wood.
- 35. The floors had the right side of the house had a noticeable deflection.
- 36. Water damage was found at several locations in the walls.
- 37. Electrical fixtures had exposed wiring. The wiring appeared to be original wiring.
- 38. The kitchen and breakfast room floors had noticeable deflections.
- 39. There was water damage at the breakfast room door.
- 40. Most likely the lead is contained in the paint.
- 41. Most likely there are building components in the walls and ceilings, and possibly the floor covering, that have asbestos.

Second Floor

- 42. Similar to the first floor all of the window and door (interior and exterior) openings had diagonal cracks that indicate movement of the structure.
- 43. The guardrails at the upper foyer were less than 36" high and are a danger to the occupants.
- 44. Most likely there are building components in the walls and ceilings, and possibly the floor covering, that have asbestos.
- 45. The floors had noticeable deflections for most of the rooms. This was an indication the structure had issues.

Attic and Roof System

- 46. The ceiling joists had what appeared to be original decking placed on top of them for a storage floor. The ceiling system was not adequate to support storage of items.
- 47. The flat roof structure had many issues.
 - a. The beam supporting the flat roof was not adequate.
 - b. The flat rafters did not have a ledge or metal connector to provide an adequate bearing surface.
 - c. The beams supporting the flat roof did not have a support system of posts and ceiling beams.
 - d. The ends of the sloped rafters framing into the beam had end cuts larger than the beam depth.
 - e. The ends of the hip rafters were not supported.
- 48. The dormers were not properly supported. Some of the rafters at the dormers had no support at their ends.
- 49. The attic was not vented.
- 50. The ceiling was not properly insulated.
- 51. There was evidence of rodent activity.
- 52. The floor decking had gaps that created trip and fall hazards.
- 53. Many of the rafters had splits from being exposed to excessive heat.
- 54. The rafters did not have intermediate supports and were over span at the right side of the house.

<u>Exterior</u>

- 55. The retaining wall at the driveway, left side, was failing. The wall had tilted and bowed. The retaining wall will require replacement.
- 56. The driveway did not have the proper clearance from the basement slab to prevent water from entering the basement area.
- 57. The driveway had numerous settlement and displacement issues.
- 58. The grade at the right side of the house appears to be above the foundation wall and it does not slope away from the house.
- 59. The exterior brick veneer had settlement cracks at several locations.
- 60. The exterior brick veneer did not have a drainage system. Most likely the wood structure has water damage due to the lack of a drainage system.
- 61. Window frames, both original and replacements, had extensive water damage and decay.
- 62. The landing and steps at the front door do not comply with the code requirements with regard to landing size, step riser heights and step riser variance.
- 63. The stairs at the rear of the house have issues.
 - a. The stairs do not have the minimum width.
 - b. A landing is missing at the door and at the bottom of the stair flight that complies with the IRC.
 - c. The riser height exceeds the code requirements.
- 64. The retaining wall for the patio at the rear of the house was failing and will have to be replaced.
- 65. The steps and pavers for the patio had deteriorated.

Historic Features

As with any house this age numerous modifications and changes have been made. The following items for the exterior had been replaced with more modern materials and finishes.

- 1. At the right side, basement level, modern siding had been used for the exterior wall covering.
- 2. Also, at the right side, the windows and doors are not original. They are a more modern manufacture.
- 3. The addition at the right rear was not part of the original construction.
- 4. The retaining wall at the right side was not original construction.
- 5. The patio at the left rear was not original construction.
- 6. The brick veneer had been painted.
- 7. Replacement windows had been installed at the right front and sides.

Economic Value of the Building

The house has numerous deficiencies, code issues and safety considerations. A general scope of work is listed below to correct the deficiencies, code violations and to render the building safe to occupy. This is not a complete scope of work and only lists major items.

- 1. A new plumbing system would be required for the entire residence.
- 2. A new electrical system including devices, service and fixtures would be required.
- 3. A new HVAC system would be required.
- 4. New foundation walls would be required to replace the 4" CMU sub walls in basement. Compacted backfill would be replaced behind the new walls. A vapor barrier would then be required for the exposed earth portion of the basement.
- 5. All of the basement doors and windows would have to be replaced due to deterioration from water and termites.
- 6. The foundation walls would require repair.
- 7. A waterproofing system along with foundation drains would be required. This would involve removal of landscaping, trees, porches and sidewalks.
- 8. All of the steel posts would require removal and replacement at the basement.
- 9. Remediation of mold and other biological growth in the basement, first floor, second floor and attic would be required.
- 10. All decayed and damaged wood components would have to be replaced. This would involve extensive shoring.
- 11. Floor joists and beams for the first floor would require repairs and replacement.
- 12. Decking for the first and second floor would require replacement due to code requirements, damage, and insect damage.
- 13. Bracing and a weather resistant membrane would be required for all exterior walls.
- 14. All damaged, bowed, notched, decayed and damaged wall studs would have to be replaced.

- 15. Structural components such as beams would have to be replaced due to lack of structural capacity to support the minimum loads as defined by the applicable building code.
- 16. Existing windows do not meet current energy code requirements for the basement, first and second floors.
- 17. Insulation was missing for basement walls and most likely for the, first and second exterior walls. Insulation for the attic was also inadequate.
- 18. All interior finishes including but not limited to walls, floors, plumbing fixtures, cabinets, and trim are missing and would have to be replaced.
- 19. All of the fireplaces would require flue inspections, flue repairs and repair to the chimney, foundations, fireboxes and hearths as required.
- 20. All interior load bearing walls would require adequate structural support.
- 21. Repairs to the second-floor joists and beams may be required.
- 22. The split rafters would have to be replaced or repaired.
- 23. The flat roof requires extensive structural repairs.
- 24. The attic decking requires repairs.
- 25. The brick veneer would have to be removed due to the following reasons.
 - a. A weather resistant envelope cannot be installed unless the exterior sides of the wood walls are accessible.
 - b. Installation of wall sheathing, especially in the areas where the sheathing was missing or damaged.
 - c. To install a drainage, weep and flashing system for the veneer.
- 26. The exterior grade would require modifications to prevent ponding of water next to the house and to prevent decay of the wood structure.
- 27. The rear patio would require replacement.
- 28. The concrete stairs at the kitchen door would require replacement.
- 29. The retaining wall at the right front of the house would require replacement.
- 30. The driveway would require replacement.

Conclusion

Once these repairs are made very little of the existing construction would remain. Given the scope of repairs, safety of workers, cost and time for repairs the most economical and practical solution would be to demolish the house and replace it with a new house. It has been a pleasure to assist you in this matter and if you should have any questions, please feel free to contact me.

Regards,

ZW Hophin

Jerry W. Hopkins, Pres. Construction Consulting Services, Inc. Georgia Licensed Professional Engineer, 13519 Attachments:





Photo 01: View of the front of the house



Photo 02: View of the right side of the house. Note the leaning retaining wall.



Photo 03: HVAC ductwork that was not insulated and in poor condition. Some of the ductwork had been replaced.



Photo 04: Typical decay and deterioration of a main beam for the first floor.



Photo 05: Damage to a main beam for the first floor.



Photo 06: Damaged concrete and wood header at basement window



Photo 07: Decayed wood at window.



Photo 08: Deterioration of foundation wall that is part of the crawl space. Note the decayed wood plate on top of the wall.



Photo 09: Decayed plate and studs. Typical throughout the basement.



Photo 10: The electrical panel was next to the earth cut, supported by a failing retaining wall and decayed studs.



Photo 11: Retaining wall constructed of unreinforced 4" CMU that is close to the exterior foundation walls.



Photo 12: Poorly maintained HVAC ductwork, and the ducts are resting on the exposed earth.



Photo 13: A jumble of electrical wiring.



Photo 14: Another jumble of electrical wiring touching the copper plumbing pipes.



Photo 15: The stairs from the basement to the first floor. All of the stair components do not meet the IRC requirements.



Photo 16: Open switch boxes



Photo 17: Corroded support posts.



Photo 18: Missing brick for part of the foundation system.



Photo 19: Damaged foundation wall.



Photo 20: Failing 4" CMU retaining wall near the front foundation wall.



Photo 21: Typical Cracking and water damage at all of the first floor windows and door openings.



Photo 22: Cracks and water damage in first floor closet.



Photo 23: The stairs do not have the required 80" headroom clearance in the hallway from the foyer to the kitchen.



Photo 24: Original wiring for the house.



Photo 25: The guardrails do not have the minimum 36" height as required by the code and they are a safety hazard.



Photo 26: Typical cracks at the windows and doors for the second floor indicating movement of the structure.



Photo 27: The flat roof is missing posts, adequate perimeter beam, connections for the flat rafters and the sloped rafter end cuts are greater than the ridge.



Photo 28: Missing decking that is a fall hazard.



Photo 29: Inadequate ceiling insulation.



Photo 30: Typical splits in rafters caused by age and heat in the attic.



Photo 31: Failing retaining wall at the right side of the house.



Photo 32: The driveway was placed too high exposing the basement to water infiltration. Note the modern siding and doors.



Photo 33: The patio had many issues such as settlement and paver deterioration.



Photo 34: The patio retaining wall is failing.



Photo 35: The stairs at the rear of the house do not have an adequate landing at the top and bottom of the stair flight. The risers are too high.



Photo 36: At the left side, the grade slopes toward the house and it appears to be above the foundation wall.



Photo 37: Typical window that has decay at the frames and sill.



Photo 38: The landing at the front door does not comply with the code requirements for depth. The bottom step has deteriorated.



Professional Consultants

March 1st, 2021

Mr. Mark Jensen Carrot Cake Partners LLC 815 Southern Shore Drive Peachtree City, GA, 30269

Project Name: 1207 Oakdale Dr

Keystone Structural Engineering, P.C. Project Number: 21-126

RE: Observation Report for 1207 Oakdale Dr, Atlanta, GA 30307

Dear Mr. Jensen,

I performed visual observations of the single-family home at 1207 Oakdale Dr, Atlanta, GA 30307 on February 25th, 2021. During my observations, the following was noted. This report does not include structural analysis or testing. As much of the structure was concealed at the time of the observation, the report only addresses those areas that were visible.

Based on my observations, in combination with the field verified items outlined in the report prepared by Construction Services, Inc., dated February 2nd, 2021, there are major deficiencies in all structural systems outlined below of the subject property.

- Gravity load foundation system.
- Lateral soil load resisting foundation system.
- Lateral soil load resisting site retaining wall system.
- Gravity load floor framing system.
- Gravity load roof framing system.
- Lateral load resisting framing systems.

Given the structural deficiencies observed and previously documented, failure of any of the structural systems outlined above is imminent, resulting in partial or full collapse, if any of the 2018 International Residential Code with State of Georgia Amendments (IRC) prescribed design loads, including but not limited to, dead loads, live loads, roof loads, flood loads, snow loads, soil loads, wind loads, and seismic loads are fully achieved.

Given the scope of repairs required, very little to none of the existing construction would remain. I recommend the existing house be demolished and replaced it with a new house, designed and

constructed in full compliance with requirements of the current 2018 International Residential Code with State of Georgia Amendments (IRC)

Contact Keystone Structural Engineering, P.C. if you have any questions or concerns,

Sincerely,

Brendan F. Growbuy, P.E.

Brendan F. Crowley, P.E. Georgia License # 30737





Building Advisory Green Programs Certifications EarthCraft, ENERGY STAR, NGBS Green LEED, Enterprise Green Communities

01/26/2021

Mark Jensen 1207 Oakdale Rd NE Atlanta, GA 30307

Ref: Exterior Envelope / Brick Assessment on existing property.

Dear Mr. Jensen.

Thank you for the opportunity to provide you with building advisory services for your property located at 1207 Oakdale Rd NE, Atlanta, GA. Based on several conversations, and emails exchanged you asked us to do an assessment on the condition of the exterior cladding and wall assemblies of the existing home located in the property, and its viability to accommodate a future expansion or addition to the home while delivering a healthy, durable, and efficient environment for the entire dwelling. Furthermore, you shared some conceptual plans which included the existing home as part of the new build.

On January 18th we came to the property to make field observations on the condition of the brick and exterior walls and everything in between, in other words the full wall assembly. Most of the exterior surface of the "original" home was cladded with the original brick, while later addition to the side had wood siding. Interior walls are covered with plaster and based on partial observation from the basement we assume that there is no exterior sheathing or insulation, perhaps 1x6 spaced as sheathing as this were common practices when home was originally built. Most windows are single pane and looked original while others seemed to have been added later. The exterior cladding (brick & siding) showed evidence of multiple oil base paint coats.

Under a building science perspective oil base paint tend to be vapor impermeable. They have a very low perm rate when compared with exposed brick or latex paint. Although painting exterior brick is a common practice it is common to create unwanted conditions on an existing home, especially on a healthy environment point of view. Traditionally a wall assemble needs to be vapor open allowing vapor to migrate from exterior or interior and in both directions to avoid trapping water. When 2 or 3 coats of paint are applied to the exterior then it's ability to dry out is severely hampered.

Big picture moisture that is naturally found in the air, or when it precipitates from the sky or even ground is trapped inside the brick due to pour roof and window flashing, or simply intrusion through cracks on mortar or poor bulk water management techniques cannot evaporate its "pull" to the interior of the home by vapor diffusion. The sun heats up the exterior brick surface making it really hot so by radiation the water vapor is force through the wall assembly into the interior of the home. This is particular important as the home's other components had been "modernized" at one time like adding an HVAC unit making the condition worst as vapor goes from hot to cold.

Although no destructive testing was conducted there was evidence of mold and mildew in the bottom plates and basement of the home indicating that condensation is happening inside the well cavity. Furthermore, they were signs of blistering of the paint indicating the potential of trapped moisture in this wall.

Trying to remove the oil-based paint will require sand blasting the existing coats of paints which will then create another serious of problems. The process of sand blasting is very aggressive which will ultimate remove of damage the natural "fire coat" outer layer of brick affecting dramatically it's durability moving forward.

There is simple no easy way of addressing moisture migration into the walls other than removing the exterior cladding and starting from scratch. At that moment then a proper weather resistive barrier could be installed over a structural sound exterior sheathing which then would allow to insulate walls. The effort involved in doing this work would render this approach economically unfeasible as a "new construction" alternatives will be more cost effective and eliminate the risk factors of not knowing what is behind the walls of the areas not improved.

On an energy efficiency point of view, it is very likely that the home has no insulation on walls, and the attic insulation is marginal. Pour insulation coupled with pour HVAC system and single pane windows would create another undo economic burden on a monthly basis, and in perpetuity.

Luis Imery Owner 770-294-1010 limery@imerygroup.com Full Tree Inventory was performed, and the house has SIGNIFICANTLY MORE DBH than required by county code this should help clarify any potential misinformation.

Tree Lo. # Tree Location Species EX. D.B.H. CR2 S.F. CRZ Dist. S.F. CRZ Dist. % Action Designation DBH Cr 1 setback pine 28 2462 2462 100.0% remove protected 0 2 buildable area magnolia 24 1809 1809 100.0% remove protected 0 3 setback pine 24 1809 100.0% remove protected 0 4 setback oak 30 2826 0 0.0% save specimen 30 5 setback oak 24 1809 0 0.0% save protected 24 6 buildable area holly 18 1017 1017 100.0% remove non-protected 0 7 setback oak 24 1809 1800 100.0% remove declining 0 10 setback oak	Tree Inventory & Impact Analysis											
1 setback pine 28 2462 2462 100.0% remove protected 0 2 buildable area magnolia 24 1809 1809 100.0% remove protected 0 3 setback oak 30 2826 0 0.0% save specimen 30 5 setback oak 24 1809 0 0.0% save specimen 30 6 buildable area holly 18 1017 1017 100.0% remove non-protected 24 6 buildable area magnolia 10 314 314 100.0% remove protected 24 7 setback oak 24 1809 312 17.3% save protected 24 10 setback oak 24 1809 180.0% remove decd 0 11 buildable area pine 30 <t< th=""><th>n DBH Credit</th><th>Designation</th><th>Action</th><th>CRZ Dist. %</th><th>CRZ Dist. S.F.</th><th>CRZ S.F.</th><th>EX. D.B.H.</th><th>Species</th><th>Tree Location</th><th>Tree I.D. #</th></t<>	n DBH Credit	Designation	Action	CRZ Dist. %	CRZ Dist. S.F.	CRZ S.F.	EX. D.B.H.	Species	Tree Location	Tree I.D. #		
2 buildable area magnolia 24 1809 1809 100.0% remove protected 0 3 setback pine 24 1809 1809 100.0% remove protected 0 4 setback oak 30 2826 0 0.0% save specimen 30 5 setback oak 24 1809 0 0.0% save protected 24 6 buildable area holly 18 1017 100.7% remove non-protected 0 7 setback oak 24 1809 1809 100.0% remove protected 0 9 buildable area poplar 24 1809 1809 100.0% remove dead 0 11 buildable area redtip 7 154 154 100.0% remove dead 0 12 buildable area poplar 36	0	protected	remove	100.0%	2462	2462	28	pine	setback	1		
3 setback pine 24 1809 1809 100.0% remove protected 0 4 setback oak 30 2826 0 0.0% save specimen 30 5 setback oak 24 1809 0 0.0% save protected 24 6 buildable area holly 18 1017 100.0% remove non-protected 0 7 setback oak 24 1809 1809 100.0% remove declining 0 8 buildable area magnolia 10 314 314 100.0% remove protected 0 9 buildable area poplar 24 1809 1809 100.0% remove dead 0 11 buildable area redtip 7 154 154 100.1% remove declining 0 12 buildable area pine 30	0	protected	remove	100.0%	1809	1809	24	magnolia	buildable area	2		
4setbackoak30282600.0%savespecimen305setbackoak24180900.0%saveprotected246buildable areaholly1810171017100.0%removenon-protected07setbackoak2418091809100.0%removedeclining08buildable areamagnolia10314314100.0%removeprotected2410setbackoak24180931217.3%saveprotected2410setbackoak241809100.0%removedecad011buildable areapoplar2418091809100.0%removenon-protected012buildable areapine2012561256100.0%removedecad013buildable areapine3028262826100.0%savespecimen3614bufferpoplar36406900.0%savespecimen3815buildable areamagnolia1031400.0%savespecimen3816buildable areamagnolia1031400.0%savespecimen3816buildable areamagnolia1031400.0%savespecimen3817	0	protected	remove	100.0%	1809	1809	24	pine	setback	3		
5setbackoak24180900.0%saveprotected246buildable areaholly1810171017100.0%removenon-protected07setbackoak2418091809100.0%removedeclining08buildable areamagnolia10314314100.0%removedeclining09buildable areapoplar24180931217.3%saveprotected2410setbackoak2418091809100.0%removedead011buildable areapiple7154154100.0%removedead012buildable areapine2012561256100.0%removedead014bufferpoplar36406900.0%savespecimen3615buildable areamaple1245200.0%saveprotected1016buildable areamagnolia1031400.0%savespecimen3818bufferhardwood38453400.0%savespecimen3419bufferpine24180900.0%savespecimen3420bufferpine24180900.0%savespecimen3421buffer	30	specimen	save	0.0%	0	2826	30	oak	setback	4		
6buildable areaholly1810171017100.0%removenon-protected07setbackoak2418091809100.0%removedeclining08buildable areamagnolia10314314100.0%removeprotected09buildable areapoplar24180931217.3%saveprotected2410setbackoak2418091809100.0%removedead011buildable areaprole2012561256100.0%removedead012buildable areapine3028262826100.0%removedeclining014bufferpoplar36406900.0%savespecimen3615buildable areamaple1245200.0%savespecimen3816buildable areamaple1245200.0%savespecimen3815buildable areamaple1245200.0%savespecimen3816buildable areamaple1245200.0%savespecimen3818bufferhardwood38453400.0%savespecimen3419bufferpine24180900.0%savespecimen3420 <td>24</td> <td>protected</td> <td>save</td> <td>0.0%</td> <td>0</td> <td>1809</td> <td>24</td> <td>oak</td> <td>setback</td> <td>5</td>	24	protected	save	0.0%	0	1809	24	oak	setback	5		
7 setback oak 24 1809 1809 100.0% remove declining 0 8 buildable area magnolia 10 314 314 100.0% remove protected 0 9 buildable area poplar 24 1809 312 17.3% save protected 24 10 setback oak 24 1809 1809 100.0% remove dead 0 11 buildable area redtip 7 154 154 100.0% remove dead 0 12 buildable area pine 20 1256 100.0% remove declining 0 14 buffer poplar 36 4069 0 0.0% save specimen 36 15 buildable area magnolia 10 314 0 0.0% save specimen 38 16 buildable area magnolia 10 <td>ed O</td> <td>non-protected</td> <td>remove</td> <td>100.0%</td> <td>1017</td> <td>1017</td> <td>18</td> <td>holly</td> <td>buildable area</td> <td>6</td>	ed O	non-protected	remove	100.0%	1017	1017	18	holly	buildable area	6		
8buildable areamagnolia10314314100.0%removeprotected09buildable areapoplar24180931217.3%saveprotected2410setbackoak2418091809100.0%removedead011buildable arearedtip7154154100.1%removedead012buildable areapine2012561256100.0%removedead013buildable areapine3028262826100.0%removedeclining014bufferpoplar36406900.0%savespecimen3615buildable areamaple1245200.0%savespecimen3816buildable areamagnolia1031400.0%savespecimen3818bufferhardwood48723500.0%savespecimen4419bufferpine24180900.0%savespecimen3422bunfferpine24180900.0%savespecimen3423bufferpine24180900.0%savespecimen3424bufferpine24180900.0%savespecimen3425boundry treepin	0	declining	remove	100.0%	1809	1809	24	oak	setback	7		
9buildable areapoplar24180931217.3%saveprotected2410setbackoak2418091809100.0%removedead011buildable arearedtip7154154100.1%removedead012buildable areapine2012561256100.0%removedead013buildable areapine3028262826100.0%removedeclining014bufferpoplar36406900.0%savespecimen3615buildable areamaple1245200.0%savespecimen3816buildable areamagnolia1031400.0%savespecimen3818bufferhardwood48723500.0%savespecimen4819bufferpine24180900.0%savespecimen3422boundry treepine24180900.0%savespecimen3423boundry treepine22152000.0%savespecimen3424buildable areahardwood20125600.0%savespecimen3424buildable areahardwood20125600.0%savespecimen3425boun	0	protected	remove	100.0%	314	314	10	magnolia	buildable area	8		
10 setback oak 24 1809 1809 100.0% remove dead 0 11 buildable area redtip 7 154 154 100.0% remove non-protected 0 12 buildable area pine 20 1256 1256 100.0% remove dead 0 13 buildable area pine 30 2826 2826 100.0% remove dead 0 14 buffer poplar 36 4069 0 0.0% save specimen 36 15 buildable area maple 12 452 0 0.0% save protected 12 16 buildable area magnolia 10 314 0 0.0% save specimen 38 18 buffer hardwood 48 7235 0 0.0% save specimen 34 20 buffer pine 24<	24	protected	save	17.3%	312	1809	24	poplar	buildable area	9		
11buildable arearedtip7154154100.1%removenon-protected012buildable areapine2012561256100.0%removedead013buildable areapine3028262826100.0%removedead014bufferpoplar36406900.0%savespecimen3615buildable areamaple1245200.0%saveprotected1216buildable areamagnolia1031400.0%saveprotected1217bufferhardwood38453400.0%savespecimen3818bufferhardwood48723500.0%savespecimen4819bufferpine24180900.0%savespecimen3420bufferpine24180900.0%savespecimen3421bufferpine34363000.0%savespecimen3422boundry treepine32152000.0%savespecimen3423boundry treehardwood30282600.0%savespecimen3424boundry treepine32152000.0%savespecimen3434boundry treepi	0	dead	remove	100.0%	1809	1809	24	oak	setback	10		
12buildable areapine2012561256100.0%removedead013buildable areapine3028262826100.0%removedeclining014bufferpoplar3640690 0.0% savespecimen3615buildable areamaple124520 0.0% saveprotected1216buildable areamagnolia103140 0.0% saveprotected1017bufferhardwood3845340 0.0% savespecimen3818bufferhardwood4872350 0.0% savespecimen4819bufferpine2418090 0.0% savespecimen3420bufferpine3436300 0.0% savespecimen3421bufferpine3215200 0.0% savespecimen3422boundry treepine3215200 0.0% savespecimen3423boundry treehardwood3028260 0.0% savespecimen3024buildable areahardwood2012560 0.0% saveprotected2025setbackpine1810170 0.0% saveprotected1826bui	ed 0	non-protected	remove	100.1%	154	154	7	redtip	buildable area	11		
13 buildable area pine 30 2826 2826 100.0% remove declining 0 14 buffer poplar 36 4069 0 0.0% save specimen 36 15 buildable area maple 12 452 0 0.0% save protected 12 16 buildable area magnolia 10 314 0 0.0% save protected 10 17 buffer hardwood 38 4534 0 0.0% save specimen 38 18 buffer hardwood 48 7235 0 0.0% save specimen 48 19 buffer pine 24 1809 0 0.0% save protected 24 20 buffer pine 34 3630 0 0.0% save specimen 34 21 buffer pine 34 36	0	dead	remove	100.0%	1256	1256	20	pine	buildable area	12		
14 buffer poplar 36 4069 0 0.0% save specimen 36 15 buildable area maple 12 452 0 0.0% save protected 12 16 buildable area magnolia 10 314 0 0.0% save protected 10 17 buffer hardwood 38 4534 0 0.0% save specimen 38 18 buffer hardwood 48 7235 0 0.0% save specimen 48 19 buffer pine 24 1809 0 0.0% save protected 24 20 buffer pine 24 1809 0 0.0% save protected 24 21 buffer pine 34 3630 0 0.0% save specimen 34 22 boundry tree hardwood 30 2826 </th <th>0</th> <th>declining</th> <th>remove</th> <th>100.0%</th> <th>2826</th> <th>2826</th> <th>30</th> <th>pine</th> <th>buildable area</th> <th>13</th>	0	declining	remove	100.0%	2826	2826	30	pine	buildable area	13		
15 buildable area maple 12 452 0 0.0% save protected 12 16 buildable area magnolia 10 314 0 0.0% save protected 10 17 buffer hardwood 38 4534 0 0.0% save specimen 38 18 buffer hardwood 48 7235 0 0.0% save specimen 48 19 buffer pine 24 1809 0 0.0% save protected 24 20 buffer pine 24 1809 0 0.0% save protected 24 21 buffer pine 34 3630 0 0.0% save protected 22 23 boundry tree pine 22 1520 0 0.0% save specimen 30 24 buildable area hardwood 20 <td< td=""><td>36</td><td>specimen</td><td>save</td><td>0.0%</td><td>0</td><td>4069</td><td>36</td><td>poplar</td><td>buffer</td><td>14</td></td<>	36	specimen	save	0.0%	0	4069	36	poplar	buffer	14		
16 buildable area magnolia 10 314 0 0.0% save protected 10 17 buffer hardwood 38 4534 0 0.0% save specimen 38 18 buffer hardwood 48 7235 0 0.0% save specimen 48 19 buffer pine 24 1809 0 0.0% save protected 24 20 buffer pine 24 1809 0 0.0% save protected 24 21 buffer pine 34 3630 0 0.0% save specimen 34 22 boundry tree pine 22 1520 0 0.0% save protected 22 23 boundry tree hardwood 30 2826 0 0.0% save specimen 30 24 buildable area hardwood 20 <t< td=""><td>12</td><td>protected</td><td>save</td><td>0.0%</td><td>0</td><td>452</td><td>12</td><td>maple</td><td>buildable area</td><td>15</td></t<>	12	protected	save	0.0%	0	452	12	maple	buildable area	15		
17 buffer hardwood 38 4534 0 0.0% save specimen 38 18 buffer hardwood 48 7235 0 0.0% save specimen 48 19 buffer pine 24 1809 0 0.0% save specimen 48 20 buffer pine 24 1809 0 0.0% save protected 24 20 buffer pine 24 1809 0 0.0% save protected 24 21 buffer pine 34 3630 0 0.0% save specimen 34 22 boundry tree pine 22 1520 0 0.0% save specimen 32 23 boundry tree hardwood 30 2826 0 0.0% save specimen 30 24 buildable area hardwood 20 1256	10	protected	save	0.0%	0	314	10	magnolia	buildable area	16		
18 buffer hardwood 48 7235 0 0.0% save specimen 48 19 buffer pine 24 1809 0 0.0% save specimen 48 20 buffer pine 24 1809 0 0.0% save protected 24 20 buffer pine 24 1809 0 0.0% save protected 24 21 buffer pine 34 3630 0 0.0% save specimen 34 22 boundry tree pine 32 1520 0 0.0% save specimen 34 23 boundry tree hardwood 30 2826 0 0.0% save specimen 30 24 buildable area hardwood 20 1256 0 0.0% save protected 20 25 setback pine 18 1017	38	specimen	save	0.0%	0	4534	38	hardwood	buffer	17		
19 buffer pine 24 1809 0 0.0% save protected 24 20 buffer pine 24 1809 0 0.0% save protected 24 20 buffer pine 24 1809 0 0.0% save protected 24 21 buffer pine 34 3630 0 0.0% save specimen 34 22 boundry tree pine 22 1520 0 0.0% save protected 22 23 boundry tree hardwood 30 2826 0 0.0% save specimen 30 24 buildable area hardwood 20 1256 0 0.0% save protected 20 25 setback pine 18 1017 0 0.0% save protected 18 26 buildable area hardwood 24 18	48	specimen	save	0.0%	0	7235	48	hardwood	buffer	18		
20 buffer pine 24 1809 0 0.0% save protected 24 20 buffer pine 24 1809 0 0.0% save protected 24 21 buffer pine 34 3630 0 0.0% save specimen 34 22 boundry tree pine 22 1520 0 0.0% save specimen 34 23 boundry tree hardwood 30 2826 0 0.0% save specimen 30 24 buildable area hardwood 20 1256 0 0.0% save protected 20 25 setback pine 18 1017 0 0.0% save protected 18 26 buildable area hardwood 24 1809 0 0.0% save protected 24	24	protected	save	0.0%	0	1809	24	nine	buffer	19		
21 buffer pine 34 3630 0 0.0% save specimen 34 22 boundry tree pine 22 1520 0 0.0% save specimen 34 22 boundry tree pine 22 1520 0 0.0% save specimen 30 23 boundry tree hardwood 30 2826 0 0.0% save specimen 30 24 buildable area hardwood 20 1256 0 0.0% save protected 20 25 setback pine 18 1017 0 0.0% save protected 18 26 buildable area hardwood 24 1809 0 0.0% save protected 24	24	protected	save	0.0%	0	1809	24	nine	buffer	20		
22 boundry tree pine 22 1520 0 0.0% save protected 22 23 boundry tree hardwood 30 2826 0 0.0% save specimen 30 24 buildable area hardwood 20 1256 0 0.0% save protected 20 25 setback pine 18 1017 0 0.0% save protected 18 26 buildable area hardwood 24 1809 0 0.0% save protected 24	34	specimen	save	0.0%	0	3630	34	nine	buffer	20		
23 boundry tree processed 22 boundry tree processed 22 23 boundry tree hardwood 30 2826 0 0.0% save specimen 30 24 buildable area hardwood 20 1256 0 0.0% save protected 20 25 setback pine 18 1017 0 0.0% save protected 18 26 buildable area hardwood 24 1809 0 0.0% save protected 24	22	protected	save	0.0%	0	1520	22	nine	boundry tree	22		
24 buildable area hardwood 20 125 0 0.0% save spectrum 33 24 buildable area hardwood 20 1256 0 0.0% save protected 20 25 setback pine 18 1017 0 0.0% save protected 18 26 buildable area hardwood 24 1809 0 0.0% save protected 24	30	specimen	5340	0.0%	0	2826	30	bardwood	boundry tree	22		
25 setback pine 18 1017 0 0.0% save protected 20 25 setback pine 18 1017 0 0.0% save protected 18 26 buildable area hardwood 24 1809 0 0.0% save protected 24	20	protected	5340	0.0%	0	1256	20	hardwood	buildable area	23		
25 Second C price 16 1017 0 0.0% Save protected 16 26 buildable area hardwood 24 1809 0 0.0% save protected 24	18	protected	5340	0.0%	0	1017	18	nine	setback	25		
	24	protected	5340	0.0%	0	1900	24	bardwood	buildable area	25		
27 buildable area bardwood 24 1809 0 0.00% save protected 24	24	protected	save	0.0%	0	1909	24	hardwood	buildable area	20		
27 buildable area hardwood 24 1009 0 0.0% save protected 24	24	protected	save	0.0%	0	1500	24	hardwood	buildable area	27		
28 buildable area inardwood 22 1120 0 0.0% save protected 22	22	protected	save	0.0%	0	1900	24	nine	boundry tree	20		
29 boundry tree prime 24 1805 0 0.0% save protected 24	19	protected	save	0.0%	0	1017	10	pine	boundry tree	29		
30 boundry tree price 16 1017 0 0.0% save protected 16 31 boundry tree bardwood 30 2826 0 0.0% save specimen 30	30	specimen	save	0.0%	0	2826	30	hardwood	boundry tree	31		
32 buildable area hardwood 32 3215 0 0.0% save specimen 32	32	specimen	save	0.0%	0	3215	32	hardwood	buildable area	32		
33 boundry tree hardwood 16 804 0 0.0% save protected 16	16	protected	save	0.0%	0	804	16	hardwood	boundry tree	33		
34 boundry tree hardwood 36 4069 0 0.0% save specimen 36	36	specimen	save	0.0%	0	4069	36	hardwood	boundry tree	34		
35 boundry tree hardwood 10 314 0 0.0% save protected 10 36 houndry tree hardwood 60 11304 0 0.0% save specimen 60		specimen	save	0.0%	0	314 11304	60	hardwood	boundry tree	35		
37 buildable area hardwood 80 20096 0 0.0.0% save specimen 80	80	specimen	save	0.0%	0	20096	80	hardwood	buildable area	37		
38 buildable area pine 30 2826 0 0.0% save specimen 30	30	specimen	save	0.0%	0	2826	30	pine	buildable area	38		
39 buildable area pine 24 1809 0 0.0% save protected 24	24	protected	save	0.0%	0	1809	24	pine	buildable area	39		
40 buildable area magnolia 12 452 0 0.0% save protected 12	12	protected	save	0.0%	0	452	12	magnolia	buildable area	40		
41 buildable area pine 24 1809 0 0.0% save protected 24	24	protected	save	0.0%	0	1809	24	pine	buildable area	41		
42 buildable area hardwood 12 452 0 0.0% save protected 12	12	protected	save	0.0%	0	452	12	hardwood	buildable area	42		
43 setback hardwood 24 1809 0 0.0% save protected 24	24	protected	save	0.0%	0	1809	24	hardwood	setback	43		
44 setback pine 30 2826 0 0.0% save specimen 30		specimen	save	0.0%	0	2826	30	pine	setback	44		
45 setback hardwood 18 1017 0 0.0% save protected 18	18	protected	save	0.0%	0	1017	18	hardwood	setback	45		
		├ ──── │					 					
45 Total Existing Trees		├ ──── │					ļļ	rees	Total Existing Tr	45		
1153 Total Existing DBH		├ ──── │					↓	BH	Total Existing D	1153		
10 Total Trees Removed							ļ	noved	Total Trees Rem	10		
35 Total Trees Saved								ed	Total Trees Save	35		
209 Total DBH Removed								oved	209			
944 Total DBH Saved		<u> </u>						14 Total DBH Saved				
643 Inches Per Acre Residual Tree Density							Density	Residual Tree [Inches Per Acre	643		

Notes:

1. Trees that are in shaded blocks have been removed

2. Trees in *bold italics* were removed due to decline or tree was dead.

3. Trees #6 & #11 do not meet the definition of a tree based on species of plant (#6 was a holly & #11 was a redtip photinia)

4. Trees #1, #2, #3 & #8 were met the definition of healthy trees and owner reserves the right to remove those trees under the

provisions afforded in the document, "Dekalb County Homeowner Guide For Tree Removal"

5. Trees #7, #10, #12, & #13 were either dead or in severe decline









.













PROPOSED RIGHT ELEVATION SCALE 1/8=1'0"



Proposed Green house design:





Please see some updated pics. **For the fireplace.** Restoration of stone and mantle will be the steps performed along with a pergola style wooden overhead to match where previous metal anchors are represented in the structure. We will utilize timber intended to be from that period.





















Photos showing proximity to neighbor's wall (to the left of the property) and driveway (to the right of the property):











