


## EXHIBIT 4 Site Photos

## Appendix –Photos (Existing condition)

<b>Client Name:</b> DeKalb County, Department of Watershed Management	<b>Site Location:</b> Scott Candler WTP Electrical Building # 2	<b>Contact / Task No.</b>
--	--	---------------------------

<b>Photo No.</b> 1	<b>Date:</b>	
<b>Description:</b> Exterior of South Wall showing Precast Panel Separation at Expansion Joint.		

<b>Photo No.</b> 2	<b>Date:</b>	
<b>Description:</b> Exterior of South Wall showing Precast Panel Separation at Expansion Joint.		

**Appendix –Photos  
(Existing condition)**

**Client Name:**  
DeKalb County, Department of  
Watershed Management

**Site Location:**  
Scott Candler WTP Electrical Building # 2

**Contact / Task No.**

<b>Photo No.</b> 3	<b>Date:</b>
<b>Description:</b> Masonry Door Jamb cracking at double door (South Wall).	



<b>Photo No.</b> 4	<b>Date:</b>
<b>Description:</b> Masonry Door Jamb cracking at double door (South Wall).	



**Appendix –Photos  
(Existing condition)**

<b>Client Name:</b> DeKalb County, Department of Watershed Management	<b>Site Location:</b> Scott Candler WTP Electrical Building # 2	<b>Contact / Task No.</b>
--	--	---------------------------

<b>Photo No.</b> 5	<b>Date:</b>
<b>Description:</b> Gable End (South Wall) Masonry cracking.	



<b>Photo No.</b> 6	<b>Date:</b>
<b>Description:</b> Gable End (South Wall) Masonry cracking.	





**Appendix –Photos  
(Existing condition)**

**Client Name:**  
DeKalb County, Department of  
Watershed Management

**Site Location:**  
Scott Candler WTP Electrical Building # 2

**Contact / Task No.**

<b>Photo No.</b> 7	<b>Date:</b>
<b>Description:</b> Damaged Truss Bearing at East Wall.	



<b>Photo No.</b> 8	<b>Date:</b>
<b>Description:</b> Temporary roof support and Damaged Truss Bearing at East Wall.	



**Appendix –Photos  
(Existing condition)**

**Client Name:**  
DeKalb County, Department of  
Watershed Management

**Site Location:**  
Scott Candler WTP Electrical Building # 2

**Contact / Task No.**

<b>Photo No.</b> 9	<b>Date:</b>
<b>Description:</b> Damaged Truss Bearing at East Wall.	



<b>Photo No.</b> 10	<b>Date:</b>
<b>Description:</b> Damaged Truss Bearing at East Wall and damaged interior non-load bearing partition wall.	





**Appendix –Photos  
(Existing condition)**

**Client Name:**  
DeKalb County, Department of  
Watershed Management

**Site Location:**  
Scott Candler WTP Electrical Building # 2

**Contact / Task No.**

<b>Photo No.</b> 11	<b>Date:</b>
<b>Description:</b> Existing Truss Bearing shows gap at top of masonry wall.	





<b>Photo No.</b> 12	<b>Date:</b>
<b>Description:</b> Damaged interior non-load bearing partition wall.	



**Appendix –Photos  
(Existing condition)**

<b>Client Name:</b> DeKalb County, Department of Watershed Management	<b>Site Location:</b> Scott Candler WTP Electrical Building # 2	<b>Contact / Task No.</b>
--	--	---------------------------

<b>Photo No.</b> 13	<b>Date:</b>	 A photograph showing a corner of a room with a light-colored cinder block wall. A significant vertical crack runs down the wall, starting from the top and extending to the floor. A grey metal pipe runs vertically along the wall. To the right, a grey door is partially visible. The floor is concrete and shows some staining.
<b>Description:</b> Damaged interior non-load bearing partition wall.		

<b>Photo No.</b> 14	<b>Date:</b>	 A photograph of an electrical room. The wall is made of light-colored cinder blocks and shows signs of damage, including a crack and a hole. Several white pipes run vertically along the wall. A black telephone is mounted on the wall. In the background, there are large grey electrical cabinets. On the right side of the image, a tall grey electrical panel is visible with various switches and indicators. The floor is concrete and appears worn.
<b>Description:</b> Damaged interior non-load bearing partition wall.		

**Appendix –Photos  
(Existing condition)**

**Client Name:**  
DeKalb County, Department of  
Watershed Management

**Site Location:**  
Scott Candler WTP Electrical Building # 2

**Contact / Task No.**

**Photo No.**  
15

**Date:**

**Description:**  
Damaged interior non-load  
bearing partition wall at East Wall  
Junction.

