| | | | | | | | | | (| Spills that Entered Waters of the US/State 2nd Qua | | | | | 2nd Quarter 2014 | | | | | | |
|---------|-------------------------------|-------------------------------|-----------|-------------|--------------------------|----------------------------|-----------|------------------------------|------------|--|---|----------------------------------|-----------|------------------|------------------|---|----------------|--------------|---|---|--|
| | Date/ | Time | I | ype & V | olume | Location | n | MH/Lir | ine Cause/ | | se/Source | Water Body | | | | Flow Restoration | | Notification | Dates | Update Comments | |
| SSO NO. | Date Spill Reported to DWM | Time Spill Reported to DWM | Fish Kill | Major Spill | Estimated Quantity, gals | Address of Spill | City | Manhole/Structure# | Pipe Size | Cause | Source | Receiving Stream or Waterbody | Tributary | Restoration Date | Restoration Time | Flow Restoration Action | 24 hour Notice | 5 Day Letter | Additional Follow-up | Comments | |
| 33 | 4/2/2014 | 8:45 | n | | 1,250 | 2801 North Decatur Road | Decatur | 048-s025 | 8 | GR | Grease blocked main. | South fork Peachtree Creek | С | 4/2/2014 | 9:35 | Rodded 200 feet unsuccessfully and pressure washed 367 feet to remove blockage at 156 feet upstream. | 04/02/14 | 04/04/14 | CCTV 345 feet and found 6 cracks in the line with PACP score of 3. | | |
| 34 | 4/4/2014 | 18:03 | n | | 7,075 | 476 Jointer Avenue | Scottdale | 046-s085 | 8 | GR | Grease blocked main. | Indian Creek | | 4/4/2014 | 22:46 | Rodded 53 feet and could not unstop. Pressure washed 310 feet to remove blockage at 50 feet and restore flow. | 04/05/14 | 04/07/14 | CCTV 225 feet and found no other issues. | Updated volume from 8.075 to correct volume of 7,075. | |
| 35 | 4/5/2014 | 11:43 | n | | 1,440 | 2724 Clairmont Road | Atlanta | 158-s013 | 10 | GR | Grease blocked main. | North Fork Peachtree Creek | U | 4/5/2014 | 12:15 | Rodded 10 inch main 50 feet to clear blockage followed by pressure washing 225 feet. | 04/05/14 | 04/07/14 | CCTV 10 inch main 260 feet and found no other issues. Manhole inspection shows no issues. | Updated volume from 1,600 to correct volume of 1,440. | |
| 36 | 4/7/2014 | 7:50 | n | Yes | 69,800 | 1942 East Starmont Way | Decatur | 172-s045 | 8 | STORM | 4 to 6 inches of rain inundated area and caused overflow. | Doolittle Creek | | 4/7/2014 | 19:28 | Storm event passed. | 04/08/14 | 04/08/14 | CCTV 15 inch main 201 feet and found no defects. | | |
| 37 | 4/7/2014 | 8:31 | n | | 4,550 | 101 Green Street | Decatur | 214-s013 | 8 | STORM | 4 to 6 inches of rain inundated area and caused overflow. | Shoal Creek | WES T | 4/7/2014 | 10:02 | Storm event passed. | 04/07/14 | 04/08/14 | CCTV 8 inch main 744 feet and found no issues. | Area under investigation for rain induced spills. | |
| 38 | 4/7/2014 | 9:24 | n | Yes | 23,200 | 1701 Childerlee Lane | Atlanta | 157-s026 | 10 | STORM | 4 to 6 inches of rain inundated area and caused overflow. | North Fork Peachtree Creek | U | 4/7/2014 | 13:16 | Storm event passed. Pressure washed 300 feet of main. | 04/07/14 | 04/08/14 | CCTV 10 inch main 412 feet to find and remove grease by pressure washing. | | |
| 39 | 4/7/2014 | 10:12 | n | | 4,950 | 2052 Grand Prix Drive | Atlanta | 193-s086 | 8 | STORM | 4 to 6 inches of rain inundated area and caused overflow. | North Fork Peachtree Creek | D-2 | 4/7/2014 | 13:30 | Storm event passed. | 04/07/14 | 04/09/14 | CCTV and pressure washed 105 feet to find no issues. | | |
| 40 | 4/8/2014 | 10:05 | n | | 3,325 | 302 Perimeter Center North | Dunwoody | TBD | 8 | GR | Grease blocked main. | North Fork Nancy Creek | U | 4/8/2014 | 12:18 | Pressure washed 8 inch main 289 feet to clear blockage at 127 feet and restore flow. | 04/09/14 | 04/09/14 | CCTV of 150 feet found line broken 10 feet outside of 350-s071. | | |
| 41 | 4/8/2014 | 10:40 | n | | 7,500 | 4159 Church Street | Clarkston | 120-s208 and 120- s010 | 8 | GR | Grease blocked main. | Snapfinger Creek | С | 4/8/2014 | 12:20 | Pressure washed main 300 feet to clear blockage at 150 feet and restore flow. | 04/09/14 | 04/09/14 | CCTV 250 feet to find and remove sand by pressure washing. Manhole infiltration by creek was repaired on 4- 10-14 | | |
| 42 | 4/9/2014 | 11:33 | n | | 900 | 7788 Covington Highway | Lithonia | 152-s022 | 8 | GR | Grease blocked main. | Honey Creek | | 4/9/2014 | 12:18 | Rodded upstream from 152-s019 to clear blockage at 40 feet followed by 400 feet of pressure washing. | 04/09/14 | 04/10/14 | CCTV and pressure washed 140 feet to find and remove rocks. Rip-rapped area around manhole to prevent erosion problems. | | |
| 43 | 4/9/2014 | 16:01 | n | | 2,480 | 437 Annie Street | Scottdale | 047-s056 | 8 | GR | Grease blocked 8 inch main. | South Fork Peachtree Creek | U-C | 1/9/2014 | 17:03 | Rodded main 30 feet to remove blockage and restore flow followed by 451 feet of pressure washing. | 04/10/14 | 04/10/14 | CCTV 8 inch main 445 feet which showed a belly outside 047-s091 and 047-s056 and added to CARL list on 4-10-2014 for annual cleaning. FOG inspect grease trap upstream and found no current issues. | | |
| 44 | 4/10/2014 | 11:54 | n | | 2,525 | 3233 Rehoboth Drive | Decatur | 117-s020 | 8 | GR | Grease blocked 8 inch main. | South Fork Peachtree Creek | U | 4/10/2014 | 13:35 | Rodded 54 feet and removed blockage at 34 feet to restore flow. | 04/10/14 | 04/11/14 | CCTV 8 inch main 54 feet and found no defects. Found creek crossing dripping upon further inspection. Made temporary repair to contain spill pending final point repair. | Initial field gallons updated after review in office. | |
| 45 | 4/11/2014 | 12:47 | n | | 5,355 | 1046 McCornell Drive | Decatur | 104-s056 | 8 | GR | Grease blocked 8 inch main. | South Fork Peachtree Creek | U | 4/11/2014 | 13:50 | After attempting to rod without success the line was pressure washed 100 feet to clear blockage at 25 feet and restore flow. | 04/11/14 | 04/14/14 | CCTV 310 feet and found 1 offset joint not associated with the spill and corrected on July 3, 2014. | | |
| 46 | 4/11/2014 | 15:43 | n | | 3,200 | 2975 Medinah Court | Atlanta | 264-s205 | 8 | RT | Roots blocked 8 inch main. | Peachtree Branch | U | 4/11/2014 | 18:23 | After attempting to rod the main without success the line was pressure washed 100 feet to clear the root blockage. Root cutter got stuck and was removed. | 04/12/14 | 04/14/14 | Additional review showed need to replace 200 feet of line when CCTV crew was setting up to do inspection and second spill occurred. | | |
| 47 | 4/13/2014 | 20:12 | n | | 700 | 1127 Cleavemark Drive | Clarkston | 095-s200 | 8 | DB | Debris (rags, rock and sand) blocked 8 inch main. | Snapfinger Creek | С | 4/13/2014 | 20:40 | Pressure washed main 250 feet to remove blockage at 100 feet. | 04/14/14 | 04/14/14 | CCTV 251 feet and found no defects. | | |

| | | | | | | | | | (| Spills that | Entered Wat | ers of the US/ | Sta | te 2nd (| Quarte | r 2014 | | | | |
|--------|------------------------|----------------------------|-----------|-------------|--------------------------|--------------------------|----------------|---------------------|--------------|-------------|--|----------------------------------|-----------|------------------|------------------|---|----------------|--------------|--|---|
| | Date | e/Time | | Type & V | olume | Location | n | MH/Lir | MH/Line Caus | | se/Source | Water Body | | | | Flow Restoration | | Notification | Dates | Update Comments |
| ON COO | Date Spill Reported to | Time Spill Reported to DWM | Fish Kill | Major Spill | Estimated Quantity, gals | Address of Spill | City | Manhole/Structure # | Pipe Size | Cause | Source | Receiving Stream or Waterbody | Tributary | Restoration Date | Restoration Time | Flow Restoration Action | 24 hour Notice | 5 Day Letter | Additional Follow-up | Comments |
| 4 | 8 4/19/201 | 4 16:58 | 3 n | | 1,275 | 2357 North Peachtree Way | Dunwoody | 310-s085 | 8 | GR | Grease blocked 8 inch main. | Northeast Creek | Y | 4/19/2014 | 17:49 | Pressure washed main 400 feet to clear blockage at 162 feet and restore flow. | 04/19/14 | 04/21/14 | CCTV 775 feet and found corrosion between 310-s090 and s089. OSARP score of 3 so no further action required at this time. | |
| 4 | 9 4/22/201 | 4 12:00 |) n | Yes | 50,300 | 2961 Medinah Court | Atlanta | 264-s205 | 10 | BRK LN/STR | Broken 10 inch main | Peachtree Branch | U | 4/22/2014 | 20:23 | Set up bypass pump on 4-22-14 to restore flow and pending sewer main repair completed on May 2, 2014 | 04/22/14 | 04/24/14 | Re-laid 200 feet of 10 in DIP main, followed by CCTV to find and remove rocks in line. | Updated volume, line size, cause and time when made available. |
| 5 | 0 4/24/201 | 4 10:40 |) n | | 5,725 | 7619 Union Grove Road | Lithonia | 200-s005 | 12 | 17:10 | Grease blocked 12 inch main | Tom George Creek | | 4/24/2014 | 14:29 | After building berm to contain spill, rodded 12 inch PVC line 50 feet to clear blockage at 2 feet and restore flow. Added 3 buckets of degreaser to the line at spilling manhole. | 04/24/14 | 04/25/14 | Pole camera inspection of area did not show issues. CCTV access was very limited. | |
| 5 | 1 4/25/201 | 9:47 | n | | 2,520 | 4104 Tahoe Court | Stone Mountain | 014-s074 | 8 | | Grease and rags blocked line. | Snapfinger Creek | | 4/25/2014 | 10:50 | Pressure washed main 230 feet and cleared blockage at 180 feet to restore flow. | 04/25/14 | 04/28/14 | CCTV 400 feet of main and found belly in line at 360 to 397 feet by the creek crossing. Placed on CARL list for annual cleaning. Sealed manhole on 6-30-14. | |
| 5 | 2 4/27/201 | 4 10:27 | n | | 5,895 | 3559 Santa Fe Trail | Doraville | 312-s026 | 10 | GR | Grease blocked sewer main. | North Fork Peachtree Creek | U- T1 | 4/27/2014 | 12:38 | Rodded 10 inch main 72 feet to clear blockage and restore flow. Pressure washed 300 feet. | 04/27/14 | 04/28/14 | Call came as water leak to start with. CCTV 366 feet and found and removed debris composed of rocks. | Added correct notification time, Water Body Name from initial report and updated spill volume in 5 day letter. |
| 5 | 3 4/29/201 | 4 15:15 | 5 n | | 1,475 | 1666 Cody Circle | Tucker | 166-s015 | 8 | GR | Grease blocked sewer main. | South Fork Peachtree Creek | U | 4/29/2014 | 16:14 | Pressure washed 265 feet upstream from 166- s030 to clear the blockage at 190 feet and restore flow. | 04/29/14 | 04/30/14 | CCTV 489 feet and found infiltration at the joint 2 feet down from 166-s009. Sealed the joint to correct issue. | |
| 5 | 4 5/3/2014 | 20:21 | n | | 7,080 | 4323 Winters Chapel Road | Doraville | 340-s012 | 8 | GRDB | Grease and paper towels blocked main | Nancy Creek | 2 | 5/3/2014 | 23:18 | Rodded main downstream 36 feet to remove blockage and restore flow. | 05/04/14 | 05/05/14 | CCTV 700 feet and found no defects. | |
| 5 | 5 5/5/2014 | 11:33 | 3 n | | 5,200 | 3471 Elgin Drive | Decatur | 166-s016 | 8 | GR | Grease blocked 8 inch main. | Cobb Creek | U | 5/5/2014 | 13:43 | Rodded main downstream 90 feet to clear blockage and restore flow followed by 472 feet of pressure washing. | 05/05/14 | 05/05/14 | CCTV 452 feet of line to find and remove grease by pressure washing. | |
| 5 | 6 5/6/2014 | 12:33 | 3 n | | 96 | 2452 Nancy Lane | Atlanta | 233-s060 | 8 | | Manhole leaking liquid sewage from invert ioint. | North Fork Peachtree Creek | U | 5/6/2014 | 15:45 | Built a berm to contain sewage and direct back in manhole. Repaired leak with hydraulic cement. | 05/06/14 | 05/07/14 | CCTV 114 feet of main and found no other defects. | |
| 5 | 7 5/9/2014 | 9:19 | n | | 6,600 | 2774 North Decatur Road | Decatur | 048-s026 | 8 | | | South Fork Peachtree Creek | С | 5/9/2014 | 10:25 | Attempted to rod 150 feet without success. Pressure washed 370 feet to clear blockage at 200 feet. | 05/09/14 | 05/12/14 | Letter sent to DeKalb Medical regarding medical waste. Health Department notified and FOG group inspected grease traps. | Updated call in time to time water call came in and adjusted volume also based on time. |
| 5 | 8 5/14/201 | 4 10:19 | n | | 1,200 | 1192 Clarendon Avenue | Avondale | 217-p031 | 8 | BRK LN/STR | 3 inch lateral broken at 8 inch main. | Cobb Creek | | 5/14/2014 | 12:34 | Pumped down 217-p031 to stop spill after attempting to rod and pressure wash 42 feet. Line was between private manhole at high school and main in street. | 05/14/14 | 05/15/14 | CCTV 147 feet and found lateral broken at main. | |
| 5 | 9 5/19/201 | 4 12:07 | 'n | | 2,560 | 1064 Baltic Way | Lithonia | 163-S045 | 8 | GR | Grease blocked main. | Swift Creek | | 5/19/2014 | 13:11 | Rodded main 3 feet from spilling manhole to restore flow followed by 300 feet of pressure washing. | 05/20/14 | 05/20/14 | CCTV 8 inch main 320 feet and found no defects. Removed grease by pressure washing. | |
| 6 | 0 5/19/201 | 4 15:18 | 3 n | | 2,280 | 1676 Briarcliff Road | Atlanta | 057-s021 | 8 | | Grease blocked main causing spill from buried manhole. | South Fork Peachtree Creek | | 5/19/2014 | 16:15 | Pressure washed main upstream from 057- s030 284 feet to remove blockage at 280 feet and restore flow. | 05/20/14 | 05/20/14 | CCTV 8 inch main 288 feet to find and remove roots. | |
| 6 | 1 5/19/201 | 4 18:55 | 5 n | | 2,300 | 3388 Garden Mill Lane | Ellenwood | 038-s081 | 8 | GR | Grease blocked the main. | Conley Creek | U | 5/19/2014 | 19:41 | Rodded downstream from spilling manhole 75 feet to restore flow followed by 125 feet of pressure washing. | 05/20/14 | 05/20/14 | CCTV 8 inch main 336 feet to find and remove grease and roots. | |
| 6 | 2 5/27/201 | 4 13:56 | S n | | 44 | 3183 Buford Highway | Brookhaven | 198-s106 | 18 | отн | Improperly abandoned 18 inch main leaking. | | U | 5/27/2014 | 17:34 | Contained spill in 5 gallon bucket until abandoned main properly sealed with concrete. | 05/28/14 | 05/28/14 | CCTV 322 feet downstream from 198- s049 and found no issues. | |
| 6 | 3 5/29/201 | 4 8:48 | n | Yes | 17,150 | 3045 Buford Highway | Brookhaven | 156-s010 | 18 | DB | 18 inch line blocked with rags and paper towels. | North Fork Peachtree Creek | | 5/29/2014 | 11:59 | Pressure washed line 577 feet from 156-s011 to clear blockage at 547 feet and restore flow. | 05/30/14 | 05/30/14 | CCTV 429 feet from 156- s009 to find more rocks and rags. Cleaning contract to finish area including this line. | |

| Spills that Entered Waters of the US/State 2nd Quarter 2014 | | | | | | | | | | | | | | | | | | | | |
|---|-------------------------------|-------------------------------|-----------|-------------|--------------------------|-----------------------------|----------------|--------------------|-----------|-------|--|--|-----------|------------------|------------------|--|----------------|--------------|--|---|
| | Date/1 | ime | 1 | Гуре & \ | olume | Location | n | MH/Lir | ne | Cau | se/Source | Water Body | | | | Flow Restoration | | Notification | n Dates | Update Comments |
| SSO NO. | Date Spill Reported to DWM | Time Spill Reported to DWM | Fish Kill | Major Spill | Estimated Quantity, gals | Address of Spill | City | Manhole/Structure# | Pipe Size | Cause | Source | Receiving Stream or Waterbody | Tributary | Restoration Date | Restoration Time | Flow Restoration Action | 24 hour Notice | 5 Day Letter | Additional Follow-up | Comments |
| 64 | 5/29/2014 | 15:53 | n | | 2,000 | 1061 North Jamestown Road | Decatur | 103-s015 | 8 | GR | Grease blocked main. | Burnt Fork Creek | U | 5/29/2014 | 17:13 | Pressure washed main 250 feet to remove blockage at 240 feet and restore flow. | 05/29/14 | 05/30/14 | CCTV 610 feet to find no structural or other defects. Pressure washed line 610 feet. | |
| 65 | 6/3/2014 | 13:41 | n | | 3,700 | 977 Linsley Way | Stone Mountain | 096-s015 | 8 | GRDB | Grease and rags blocked main. | North Crooked Creek | U | 6/3/2014 | 14:55 | Unstopped main in the mouth of the invert with a stick followed by 650 feet of pressure washing. | 06/04/14 | 06/04/14 | CCTV 510 feet to locate and mark manhole 096-s014. No defects observed. | |
| 66 | 6/3/2014 | 16:23 | n | | 9,940 | 2964 Aberdeen Way | Lithonia | 054-s023 | 10 | GRDB | Grease and rags blocked main. | Pole Bridge Creek | U | 6/3/2014 | 18:45 | After unsuccessful attempt to rod up and downstream to the blockage, pressure washed main 425 feet to clear blockage at 375 feet and restore flow. | 06/03/14 | 06/04/14 | CCTV 610 feet and found no defects. Pressure washed line to remove grease. | |
| 67 | 6/4/2014 | 12:20 | n | | 4,150 | 1900 Tree Mountain Parkway | Stone Mountain | 137-s024 | 8 | GR | Grease blocked main. | Stone Mountain Creek | U | 6/4/2014 | 13:43 | Rodded main 30 feet to restore flow. | 06/04/14 | 06/05/14 | CCTV 356 feet and found no defects after cleaning line of grease 356 feet. | |
| 68 | 6/6/2014 | 19:40 | n | | 80,900 | 1313 Stone Mill Way | Stone Mountain | Lift Station | | STORM | Lightning took out power system to single phase. | Barbashela Creek | U | 6/6/2014 | 21:20 | Switched to generator power manually and scheduled repairs to main power and the ATS | 06/07/14 | 06/10/14 | Stattion systems repaired and functionality restored. | Updated on 6-9-14 to current information on this report. Updated EPD by phone also upon their call. |
| 69 | 6/12/2014 | 15:52 | n | | 5,800 | 4591 Lawrenceville Highway | Tucker | 224-s206 | 8 | GRDB | Grease and rags blocked main. | Jackson Creek | U | 6/12/2014 | 16:50 | Attempted to rod main 200 feet unsuccessfully. Vacuumed spilling manhole to contain spill, removed debris from invert and pressure washed main 197 feet to restore flow. | 06/12/14 | 06/13/14 | | Water Body Updated from report. Signs marked correctly. |
| 70 | 6/16/2014 | 15:05 | n | | 5,000 | 3556 Montreal Way | Tucker | 144-s057 | 8 | GR | Broken line leading to creek crossing revealed by grease blocked line. | South Fork Peachtree Creek | U | 6/16/2014 | 18:25 | Built a berm to stop spill while line leading to creek crossing repaired. Pressure washed 300 feet of line to remove blockage at 70 feet from 144-s080. | 06/17/14 | 06/17/14 | Removed grease from 268 feet of line from 144-s022 and 120 feet to 144-s057. | Updated report with volume when determined. |
| 71 | 6/18/2014 | 21:30 | n | | 5,460 | 1303 Stone Mill Cove | Stone Mountain | 125-s028 | 8 | GR | Grease blocked main. | Unnamed Lake Connected to Stone Mountain Creek | U | 6/18/2014 | 23:01 | Attempted to rod main 100 feet up from 125-s027 unsuccessfully. Pressure washed main 100 feet to remove blockage at 100 feet and restore flow. | 06/19/14 | 06/23/14 | After line cleared of heavy grease by degreaser and pressure washing, CCTV 446 feet and found no issues. | |
| 72 | 6/25/2014 | 15:34 | n | | 3,650 | 849 Lagoon Circle | Stone Mountain | 068-s210 | 8 | GR | Grease blocked 8 inch main. | Snapfinger Creek | С | 6/25/2014 | 18:00 | Could not find 2 downstream manholes so pressure washed from 068-s209 300 feet to clear blockage and restore flow. | 06/26/14 | 06/26/14 | CCTV 266 feet downstream from s206 to find roots | |
| 73 | 6/30/2014 | 11:31 | n | | 2,280 | 3954 Memorial College Drive | Clarkston | 068-s200 | 8 | GR | Grease blocked 8 inch main. | Snapfinger Creek | D | 6/30/2014 | 12:28 | Rodded 15 feet down from 043-s202 to clear grease blockage and restore flow followed by 300 feet of pressure washing. Added 2 buckets of degreaser at 068-s202 which is upstream of the spill. | 07/01/14 | 07/01/14 | Sealed 068-s200 ring on 7-1 14. | |
| 74 | 6/30/2014 | 13:56 | n | | 765 | 335 Ponce de Leon Place | Decatur | 246-s142 | 8 | RT | Roots blocked main and heavy rain caused overflow. | Lamont Drive Branch of Peavine Creek | | 6/30/2014 | 14:13 | Waited for rain to subside and spill stopped. Initated follow-up investigations. | 07/01/14 | 07/01/14 | CCTV 226 feet and found roots in line which caused original spill. Roots removed and full flow restored. Broken service line and main at 207 Beaumont repaired on 7-2-14. Additional investigation found problems on a construction site which required replacing 5 feet of line and sealing it to avoid issues from construction. | Connected to building back-ups B22 and B23. |

| | DeKalb County Department of Watershed Management Consent Decree SSO Tracking Sheet | | | | | | | | | | | | | | | |
|--------------------|--|----------------------------|-----------------------|----------------------------|----------------|------------|---|------------------|------------------|---|-----------------|------------------|--|---|-------------------------------------|--|
| | | - . | | | | | | ing Bacl | | port 2nd Quarter 2014 | | | | | | |
| | Date/1 | Fime g | (est.) | Location | 1 | Ca | use/Source | | | Flow Restoration | Number | | | Actions | ng or | |
| Building Back-up # | Date Spill Reported to DWM | Time Spill Reported DWM | Quantity in Gallons (| Address of Spill | City | Cause | Source/Additional Description | Restoration Date | Restoration Time | Flow Restoration Act | Service Request | Cleaning Service | Inspection Results | Additional Follow-up | Faulty Home Plumbing Not to Code | Update Comments |
| B11-14 | 04/14/14 | 18:48 | 25 | 4659 Birch Ridge Trail | Stone Mountain | ОТН | Surcharged manhole being pressure washed and sewer went in home. | 04/14/14 | 19:35 | Pressure washed line 266 feet to remove blockage of roots and rags at 67 feet and caused backflow into home from cleaning activities. | 1416062 | Yes | CCTV 401 feet to find and remove grease and roots. | | YES | Sent backwater valve letter. |
| B12-14 | 04/21/14 | 12:41 | 15 | 4152 Brownlee Drive | Tucker | RT | Roots blocked 8 inch main causing surcharged manhole and sewer to enter building. | 04/21/14 | 13:58 | Rodded main 75 feet to clear root blockage followed by pressure washing of 115 feet. | 1416987 | Yes | CCTV 115 feet and found and removed roots. | | YES | Sent backwater valve letter. |
| B13-14 | 04/23/14 | 10:58 | 3,116 | 5036 Minola Drive | Lithonia | BRK LN/STR | Broken Main caused manhole surcharge and building back-up | 04/23/14 | 11:50 | Established vacuum trucks to keep system down while point repair is made. Completed repair on May 13, 2014. | 1417272 | Yes | Bottom of main completely corroded. CCTV 402 feet of main after repair to find no issues. | Re-laid 402 feet of main and finished on 5-13-14. | YES | Backwater valve letter sent. |
| B14-14 | 05/01/14 | 15:37 | 10 | 1953 Mount Vernon Road | Dunwoody | GRRT | Grease and roots blocked main. | 05/01/14 | 18:10 | Attempted to rod main 110 feet without success. Pressure washed 315 feet to remove blockage at 165 feet and restore flow. | 1418441 | Yes | Manhole 367-s054 surcharging. CCTV 1020 feet to find roots at 47 and 58 feet which were removed. | | YES | Sent backwater valve letter on 5-2-14. |
| B15-14 | 05/03/14 | 10:02 | 50 | 4577 Village Springs Place | Dunwoody | DB | Heavy paper towels blocked line. | 05/03/14 | 11:00 | Rodded 8 inch main from 351-s118 up stream 150 feet to clear blockage followed by pressure washing 400 feet. | 1418627 | Yes | CCTV 461 feet of line to find and remove roots. | Gave customer backflow valve handout. | YES | Customer refused cleaning service. Sent backwater valve letter on 5-3-14. |
| B16-14 | 04/17/14 | 9:15 | 45 | 3586 Turner Heights Drive | Decatur | UNK | Unknown blockage in main cleared itself. | 04/17/14 | 9:40 | Pressure washed line 250 feet after it cleared itself. | 1416432 | Yes | CCTV 8 inch main 335 feet to find infiltration at 59 and 69 feet apparently from the water service wrap- around. | Backwater valve letter sent 4-18-14. | YES | |
| B17-14 | 05/27/14 | 21:22 | 80 | 1852 Vermack Court | Dunwoody | отн | Found concrete in main causing blockage | 05/27/14 | 22:50 | Pressure washed 150 feet to unstop main and restore flow after unsuccessful attempt to rod line. | 1422193 | Yes | CCTV 330 feet to find no defects. | Concrete was removed from manhole on 5-29-14. | YES | Backflow letter sent 6-2-14. |
| B18-14 | 05/29/14 | 15:53 | 200 | 1061 North Jamestown Road | Decatur | GR | Grease blocked main causing back-up out of floor drain. | 05/29/14 | 17:13 | Pressure washed 8 inch main 250 feet to clear grease blockage at 240 feet. | 1422577 | No | CCTV 248 feet and found no defects. Pressure washed 400 feet upstream to remove roots and grease. | | YES | Area was in an open storage area so sewer ran back down drain when flow restored. Owner to clean as his plumbing was faulty. |
| B19-14 | 06/04/14 | 10:30 | 1 | 1276 Kendrick Road | Brookhaven | ОТН | Pressure washing caused water to blow out toilet. | 06/04/14 | 10:40 | Stopped pressure washing. | 1423424 | No | CCTV of 6 inch lateral is clear and properly installed for 1277 and 1276. | No backwater valve present. | YES | Customer refused cleaning service. |
| B20-14 | 06/17/14 | 21:00 | 28 | 2747 Cravey Drive | Atlanta | RT | Roots blocked main. | 06/18/14 | 11:00 | Root cut main 83 feet from 247-s070 to clear blockage at 36 feet. | 1425389 | Yes | CCTV 83 feet down to find roots at 36 feet and 79 feet up to locate 247- s069 and exposed the manhole. No defects found. | | YES | No property line cleanout. |
| B21-14 | 06/23/14 | 10:04 | 55 | 3721 Sterling Ridge Court | Decatur | RT | Roots blocked main. | 06/23/14 | 10:55 | Rodded from 133-s071 downstream 56 feet to clear root blockage at 56 feet and restore flow. | 1426082 | Yes | CCTV 444 feet from 133- s070 to 133-s072 and found heavy roots and grease. Removed roots and grease from line. | Cleaned up around private cleanout. | YES | No property line cleanout. Surface spill S45-14 connected to this. |
| B22-14 | 06/24/14 | 19:38 | 40 | 335 Ponce de Leon Place | Decatur | RT | Storm with heavy rain revealed a root blocked main. | 06/24/14 | Unknown | Waited for rain to stop. | 1426545 | Yes | CCTV 226 feet from 226- s140 to locate roots at tap for 125 Beaumont Avenue. Found broken pipe at 147 feet and roots at tap. Root cut 270 feet to clear roots. | Point repair completed 7- 2-14 on both areas. | YES | No property line cleanout or backwater valve |

| | | | | | DeKalb (| County Do | epartment of W | atersh | ed Ma | nagement Consent Decre | ee SSO | Tracking | Sheet | | | |
|--------------------|-------------------------------|--------------------------------|----------------------------|-------------------------|----------|-----------|---|------------------|------------------|--------------------------|-----------------|------------------|----------------------|---------------------------|--|--|
| | | | | | | | Buildi | ng Bacl | k-up Re | eport 2nd Quarter 2014 | | | | | | |
| | Date/ | Гіте | | Location | | Ca | use/Source | | | Flow Restoration | Number | | | Actions | | |
| Building Back-up # | Date Spill Reported to DWM | Time Spill Reported to DWIM | Quantity in Gallons (est.) | Address of Spill | City | Cause | Source/Additional Description | Restoration Date | Restoration Time | Flow Restoration Action | Service Request | Cleaning Service | Inspection Results | Additional Follow-up | Faulty Home Plumbing or Not to Code | Update Comments |
| B23-14 | 06/30/14 | 13:56 | 10 | 335 Ponce de Leon Place | Decatur | | Storm with heavy rain revealed a root blocked main. | 06/24/14 | Unknown | Waited for rain to stop. | 1427413 | Yes | Avenue. Found broken | Point repair completed 7- | YES | No property line cleanout or backwater valve |

| | | | | | Overflow (| Surface Spil | ls) 2nd Quarter 2014 | | | | | | |
|------------|-------------------------------|-------------------------------|---------------------|-------------------------|----------------|--------------|---|------------------|------------------|---|-----------------|--|--|
| | Date/T | Time | | Location | | | Cause/Source | | | Flow Restoration | Number | | Results |
| Overflow # | Date Spill Reported to DWM | Time Spill Reported to DWM | Quantity in Gallons | Address of Spill | City | Cause | Source/Additional Description | Restoration Date | Restoration Time | Flow Restoration Action | Service Request | Inspection Results | Update Comments |
| S26-14 | 04/02/14 | 10:04 | 2,000 | 3643 Glenwood Road | Decatur | GR | Grease blocked main. | 04/02/14 | 11:00 | Pressure washed 8 inch main 400 feet to clear blockage at 200 feet. | 1413702 | CCTV 300 feet and found and removed grease from main. | |
| S27-14 | 04/02/14 | 19:00 | 35 | 1831 Briarcliff Circle | Atlanta | GR | Grease blocked main at multi-family complex. | 04/02/14 | 20:39 | Rodded 140 feet upstream to clear blockage. Pressure washed 530 to clean line. | 1413824 | CCTV 400 feet and found grease which was removed by pressure washing. | |
| S28-14 | 04/03/14 | 9:52 | 3,100 | 3043 Warren Road | Decatur | GRDB | Grease and rags blocked main. | 04/03/14 | 10:45 | Pressure washed main 300 feet to remove blockage caused by grease and rags at 200 feet and restore flow. | 1413951 | CCTV 484 feet to find and remove sand and rocks. | Additional cleaning assigned to cleaning contractor. |
| S29-14 | 04/03/14 | 11:46 | 2,500 | 2929 Panthersville Road | Decatur | GR | Grease blocked main. | 04/03/14 | 12:53 | Pressure washed main 595 feet to restore flow. | 1414032 | CCTV 371 feet to find and remove grease by pressure washing. | Created education follow-up for multi- family complex. Manhole repair completed on May 6, 2014 |
| S30-14 | 04/11/14 | 15:06 | 15 | 3935 LaVista Road | Tucker | GR | Grease blocked main causing spill through broken 4 inch private cleanout. | 04/11/14 | 15:55 | Pressure washed 8 inch main 150 feet to remove blockage at 50 feet. | 1415606 | Pole camera inspection of 27 manholes to map grease issues. | Inspection results given to FOG to investigate and enforce in area. Property owner advised to fix private cleanout and health department also notified. IPT is enforcing on one business for illegal discharge. Owner advised to fix cleanout and health department also notified. |
| S31-14 | 04/19/14 | 16:10 | 8,090 | 5128 Stone Mill Way | Stone Mountain | LFT STN FLR | Pumps malfunctioned from being switched to air at Stone Mill 2 LS. | 04/19/14 | 16:20 | Bled air out of pumps and re-established flow. | 1417036 | Pumps were not set back to operation by the LS cleaning crew. | |
| S32-14 | 04/23/14 | 11:00 | 50 | 1302 Mannbrook Drive | Stone Mountain | GR | While doing routine manhole inspections found 6 inch cleanout overflowing from surcharged line. | 04/23/14 | 12:00 | Pressure washed 8 inch line 415 feet to clear blockage at 250 feet. | 1417278 | CCTV 181 feet to find and remove grease. | Additional cleaning assigned to cleaning contractor. |
| S33-14 | 05/04/14 | 14:06 | 3,015 | 3315 Waldrop Trail | Decatur | GRDB | Grease and rags blocked main. | 05/04/14 | 15:13 | Rodded 071-s014 12 feet downstream to restore flow. | 1418703 | CCTV 800 feet of main to find and remove grease from line. | Added line segment to CARL list to be cleaned every 3 months. |
| S34-14 | 05/06/14 | 9:00 | 0.5 | 4150 Tilly Mill Road | Doraville | CRK BRK | Creek crossing leaking from bell with missing lead. | 05/06/14 | 16:05 | Installed red rubber and clamps to contain spill until repair made on 5-8-14. | 1419224 | CCTV creek crossing after repair and found no defects. CCTV 366 feet to find need for two point repairs at 24 feet and 54 feet. | Point repairs completed on 5-28-14. |
| S35-14 | 05/16/14 | 16:40 | 300 | 2895 Eastwood Avenue | Decatur | GR | Grease blocked 8 inch main. | 05/16/14 | 17:40 | Rodded from spilling manhole 170 feet to clear blockage followed by pressure washing 550 feet. | 1420593 | CCTV main 390 feet to find debris (tissue, condoms, rocks) and removed by pressure washing. | |
| S36-14 | 05/19/14 | 13:29 | 5 | 1891 Edinburgh Terrace | Atlanta | BRK LN/STR | Broken 6 inch lateral caused spill | 05/19/14 | 14:28 | Repaired sewer lateral with 11 feet of PVC | 1420878 | CCTV 200 feet of 8 inch main to find no other defects. | |
| S37-14 | 05/20/14 | 16:19 | 5 | 1388 Tugaloo Drive | Brookhaven | BRK LN/STR | Broken lateral caused spill | 05/20/14 | 17:50 | Built berm around break to contain spill while line repaired. | 1421120 | CCTV 8 inch main 157 feet and found bad line allowing infiltration from creek to enter. CCTV of 4 inch cleanout found issue at 14 feet. | Repaired line at creek and cleanout |
| S38-14 | 05/22/14 | 9:52 | 5 | 1597 Trailview Way | Atlanta | BRK LN/STR | Broken lateral caused blockage | 05/21/14 | | Rodded and pressure washed from cleanout and hit unknown issue at 12 feet. Point repair made on sewer lateral on May 2014 to fix root damage. Main line was clear and flowing | 1421433 | | |
| S39-14 | 05/28/14 | 10:25 | 30 | 2263 Wayside Drive | Brookhaven | GR | Grease blocked main and manhole was leaking from riser cone. | 05/28/14 | 11:11 | Pressure washed main 297 feet to clear blockage at 197 feet and restore flow. | 1422270 | | |

| | | | | | Overflow (| Surface Spil | ls) 2nd Quarter 2014 | | | | | | |
|------------|-------------------------------|-------------------------------|---------------------|-----------------------------|----------------|--------------|---|------------------|------------------|---|-----------------|--|---|
| | Date/1 | Time | | Location | | | Cause/Source | | | Flow Restoration | Number | | Results |
| Overflow # | Date Spill Reported to DWM | Time Spill Reported to DWM | Quantity in Gallons | Address of Spill | City | Cause | Source/Additional Description | Restoration Date | Restoration Time | Flow Restoration Action | Service Request | Inspection Results | Update Comments |
| S40-14 | 05/30/14 | 8:24 | 240 | 1205 West Nancy Creek Drive | Brookhaven | GR | Grease blocked 8 inch main | 05/30/14 | 9:12 | Rodded main 120 feet downstream and cleared blockage at 27 feet. | 1422580 | CCTV 8 inch main from 327-s044, located 327- s045. Cleaned line of grease 318 feet. No defects found and located buried manhole 327-s045. | |
| S41-14 | 06/02/14 | 14:23 | 2 | 1277 Kendrick Road | Brookhaven | OUTSIDE CON | Contractor damaged 8 inch concrete main. | 06/02/14 | 17:30 | Repaired sewer main by replacing 3 feet of line. | 1422907 | CCTV 385 feet. Pressure washed 418 feet of line. | |
| S42-14 | 06/05/14 | 9:26 | 1 | 4239 Long Branch Court | Brookhaven | МН | Area just below pipe penetration at invert seeping sewage | 06/05/14 | 12:00 | Sealed pipe penetration and surface with hydraulic cement. | 1423429 | | |
| S43-14 | 06/10/14 | 8:33 | 3 | 618 South Rays Road | Stone Mountain | RT | Roots blocked 4 inch lateral causing seepage at cleanout cap. | 06/10/14 | 9:50 | Rodded lateral 18 feet to clear roots and restore flow. | 1424114 | CCTV cleanout to find roots from 5 to 17 feet. | |
| S44-14 | 06/18/14 | 14:13 | 200 | 2212 Briarcliff Road | Atlanta | GR | Grease blocked line along with debris. | 06/18/14 | 15:35 | Rodded main 150 feet from unmarked manhole to remove rags and restore flow. | 1425461 | | |
| S45-14 | 06/23/14 | 10:04 | 10 | 3721 Sterling Ridge Drive | Decatur | RT | Roots blocked 8 inch main. | 06/23/14 | 10:55 | Rodded 8 inch main from 133-s071 56 feet downstream to clear roots and restore flow. | 1426082 | CCTV 444 feet from 133- s070 thru s-072 to remove grease and roots. | Building back-up B21-14 connected to this overflow. |
| S46-14 | 06/24/14 | 14:14 | 8,280 | 3340 Garden Mill Lane | Ellenwood | GR | Grease blocked 8 inch main | 06/24/14 | 16:32 | Rodded 5 feet from 038-s090 to clear grease and restore flow followed by pressure washing 600 feet via step cleaning. | 1426437 | | Originally reported in error as regular spill but no sewer entered a waterbody. |