| 3rd  | Quarter                       | 2015                          |           |             |                          |                             | DeKalb Co      | unty De             | part      |              |  | nagement Cons                    |           |                  |                  | acking Sheet   |                |              |  |  |
|--|-------------------------------|-------------------------------|-----------|-------------|--------------------------|-----------------------------|----------------|---------------------|-----------|--------------|--|----------------------------------|-----------|------------------|------------------|--|----------------|--------------|--|--|
| Spills that Entered Waters of the US/State |                               |                               |           |             |                          |                             |                |                     |           |              |  |                                  |           |                  |                  |  |                |              |  |  |
|  | Date/T                        | Date/Time                     |           |             | Volume                   | Location                    |                | MH/Line             |           | Cause/Source |  | Water Body                       |           | Flow Restoration |                  |  |                | Notification | Update Comment   |  |
| SSO NO.                                    | Date Spill Reported to<br>DWM | Time Spill Reported to<br>DWM | Fish Kill | Major Spill | Estimated Quantity, gals | Address of Spill            | City           | Manhole/Structure # | Pipe Size | Cause        | Source   | Receiving Stream or<br>Waterbody | Tributary | Restoration Date | Restoration Time | Flow Restoration Action  | 24 hour Notice | 5 Day Letter | Additional Follow-up   | Comments   |
| 14   | 7/15/2015                     | 11:43                         | n         |             | 6,060                    | 4168 Woodwin Court          | Doraville      | 336-s009            | 8         | GR           | Grease blocked main  | Nancy Creek                      | 1         | 7/15/2015        | 13:24            | Rodded line up from s024 to hit blockage at<br>150 feet but could not restore flow. Pressure<br>washed line 316 feet to remove blockage at<br>155 feet and restore flow. | 07/15/15       | 07/17/15     | CCTV 314 feet from s009 to<br>s024 to find offset joint at 27<br>feet causing grease<br>accumulation.  | Letter had address at 4108 a should have ben 4168. |
| 5  | 7/19/2015                     | 12:34                         | n         |             | 3,920                    | 7840 Old Covington Road     | Lithonia       | 200-s017            | 8         | LFT STN FLR  | Level control failed and<br>caused overflow from<br>manhole.                   | Tom George Lake                  | Lake      | 7/19/2015        | 14:12            | Technician put station in manual and made repair.  | 07/20/15       | 07/22/15     | Manhole s017 raised 8-12-<br>15.   | Letter had Highway and sho have been Road.         |
| 16   | 7/27/2015                     | 12:44                         | n         |             | 920                      | 3806 Dedee Court            | Tucker         | 228-s022            | 8         | RT           | Roots blocked main.  | Peachtree Branch                 | U         | 7/27/2015        | 13:30            | Rodded up from s022 75 feet to remove roots at 35 feet and restore flow. Pressure washed 800 feet also.  | 07/27/15       | 07/29/15     | CCTV shows root infiltration<br>at joints, small hole and<br>broken stub. Root control<br>completed 10-19-15 for 650<br>feet of line.  |  |
| 17   | 7/30/2015                     | 10:17                         | n         |             | 25                       | 2829 Osborne Road           | Atlanta        | 240-s208            | 8         | BRK LN/STR   | Leak behind damaged<br>culvert box wall<br>seeping into storm<br>drain system. | Nancy Creek                      | U         | 7/30/2015        | 15:30            | Set up vac truck to control spill while line repaired.   | 07/31/15       | 07/31/15     | CCTV from s208 to s126 for<br>152 feet to find no additional<br>defects after repair<br>completed.   |  |
| 18   | 8/2/2015                      | 10:41                         | n         |             | 3,150                    | 260 Northern Avenue         | Avondale       | 011-p035            | 15        | GR           | Grease blocked main causing private manhole to overflow.                       | Indian Creek                     | А         | 8/3/2015         | 11:51            | Pressure washed main from s050 down 225 feet to clear blockage,  | 08/03/15       | 08/04/15     | CCTV main from s050 154 feet and camera went underwater. Transfer to contractor for large line cleaning and inspection.  |  |
| 19   | 8/3/2015                      | 14:10                         | n         |             | 900                      | 5099 Rockbridge Road        | Stone Mountain | 039-s077            | 8         | GR           | Grease blocked main and customer removed stand pipe on cleanout causing spill. | Barbashela Creek                 | U         | 8/3/2015         | 14:55            | Pressure washed up from s077 103 feet to remove blockage at 60 feet and restore flow.  | 08/03/15       | 08/04/15     | CCTV from s061 to s077 to find and remove root ball at 359 feet.   |  |
| 0  | 8/5/2015                      | 12:53                         | n         |             | 1,500                    | 5987 Magnolia Ridge         | Stone Mountain | 065-s004            | 8         | GR           | Grease blocked main  | North Crooked Creek              | U         | 8/5/2015         | 14:08            | Pressure washed from s003 475 feet to clear blockage at 225 feet.  | 08/05/15       | 08/06/15     | CCTV 390 feet from s004 to<br>s003 to find and remove<br>roots.  |  |
| 1  | 8/7/2015                      | 10:13                         | n         |             | 100                      | 1506 Rochelle Drive         | Dunwoody       | 346-s024            | 8         | BRK LN/STR   | Creek crossing line had small hole in the creek bank.                          | North Fork Nancy Creek           | U         | 8/7/2015         | 12:30            | Set up vac truck to control spill while line repaired.   | 08/07/15       | 08/10/15     | CCTV 100 feet from s037 to<br>find a crack in the bell at the<br>junction between concrete<br>and DIP piping.  |  |
| 2  | 8/11/2015                     | 12:51                         | n         |             | 720                      | 4103 Wesley Club Drive      | Decatur        | 126-s013            | 8         | GRDB         | Main blocked by grease, rags and wipes.  | Cobb Creek                       | U         | 8/11/2015        | 13:27            | Rodded line to clear grease and debris 64 feet from s012 followed by pressure washing 82 feet.   | 08/12/15       | 08/12/15     | CCTV 270 feet from s013 to<br>s012 to find and remove<br>grease by pressure<br>washing.  |  |
| 3  | 8/13/2015                     | 15:57                         | n         |             | 1,080                    | 4776 Snapfinger Woods Drive | Decatur        | 008-s004            | 8         | GR           | Grease blocked main<br>near contractor<br>cleaning upstream.                   | Snapfinger Creek                 | U         | 8/13/2015        | 16:51            | Rodded 6 feet down from s003 to clear blockage and restore flow.   | 08/13/15       |              | Pole camera inspection<br>showed debris and removed<br>by cleaning contractors. Re-<br>educated cleaning<br>contractor to assure debris<br>and grease are properly<br>handled. | Corrected volume is 1,080 gallons.                 |
| 4  | 8/17/2015                     | 10:39                         | n         |             | 2,400                    | 5935 Magnolia Ridge         | Stone Mountain | 065-s500            | 8         | GR           | Grease blocked main  | North Crooked Creek              | U         | 8/17/2015        | 11:39            | Attempted to rod main from s021 for 195 feet without success. Rodded down from s500 15 feet to clear grease and restore flow.  | 08/17/15       | 08/17/15     | nandled.  CCTV 291 feet from s500 to s021 to find and remove grease by pressure washing. 54 and 50 are now in a combined follow-up   |  |

North Fork Peachtree

South Fork Peachtree

North Fork Peachtree

Burnt Fork Creek

Leaking joint at the

blockage causing

manholes.

8 BRK LN/STR Collapsed line

18 GRDB

8 GR

243-s146

104-s056

269-s047

189-s012

creek bank and rag

surcharges in several

Grease blocked main.

Grease blocked main

11:40

17:26

8/18/2015

8/22/2015

8/26/2015

8/31/2015

U

Pressure washed line 600 feet up from s046 to

emove grease and rag obstruction at 50 feet.

Rodded from s056 down to clear blockage at

Attempted rodding and pressure washing

without success. Vacuumed sewage from hole

Pressure washed line from s031 to s033 for

14:42 275 feet to remove blockage at 20 feet and

16:00 27 feet followed by 130 feet of pressure

while point repair made.

washing.

estore flow.

08/18/15

08/22/15

08/27/15

08/31/15

08/19/15

08/24/15

09/01/15

in a combined follow-up

Contractors to do line investigation in 18 inch line to determine condition and

CCTV down from s056 to s055 to find and remove

removing debris and grease from line to find no defects.

FOG group to investigate all FSE's on the line for

compliance. Added to CARL list for cleaning and

grease and roots.

CCTV 120 feet to find another area for point repair at 37 feet which had a line bored through the main.

Repairs completed on 8-26-15 and 9-2-15.

CCTV 370 feet after

cleaning needs.

grease and roots.

Chamblee

Decatur

Chamblee

Tucker

100 2748 South Bamby Lane

34 2899 Shallowford Road

1953 Crescent Centre Boulevard

8,840

1,600 1046 McConnell Drive

55

57

58

8/18/2015

8/22/2015

8/26/2015

8/31/2015

10:49

15:20

15:07

12:58

| 3      | d Quarte                                   | er 2015                    | 5         |             |                          |                             | DeKalb Co      | unty De             | part      |            |   | Management Consent Decree SSO Tracking Sheet |                  |           |                  |   |                |              |   |   |
|--------|--|----------------------------|-----------|-------------|--------------------------|-----------------------------|----------------|---------------------|-----------|------------|---|--|------------------|-----------|------------------|---|----------------|--------------|---|---|
|        | Spills that Entered Waters of the US/State |                            |           |             |                          |                             |                |                     |           |            |   |  |                  |           |                  |   |                |              |   |   |
|        | Date/Time                                  |                            |           | Type &      | Volume                   | Location                    | MH/Lir         | ne                  | Cau       | ise/Source | Water Body  |  | Flow Restoration |           |                  | Notification Dates  |                |              | Update Comments   |   |
| ON COO | Date Spill Reported to<br>DWM              | Time Spill Reported to DWM | Fish Kill | Major Spill | Estimated Quantity, gals | Address of Spill            | Gity           | Manhole/Structure # | Pipe Size | Cause      | Source  | Receiving Stream or<br>Waterbody             | Stream           |           | Restoration Time | Flow Restoration Action   | 24 hour Notice | 5 Day Letter | Additional Follow-up  | Comments  |
| 5      | 9/8/2015                                   | 8:07                       | n         |             | 3,760                    | 2567 Candler Woods Drive    | Decatur        | 119-s019            | 8         | GR         | Grease blocked main   | Doless Creek                                 | U                | 9/8/2015  | 11:15            | Pressure washed 172 feet up from s019 to remove grease blockage at 80 feet.   | 09/08/15       | 09/09/15     | CCTV 132 feet from s018 to find and remove grease.                      |   |
| 6      | 9/9/2015                                   | 16:02                      | n         |             | 5,280                    | 886 Granite Springs Lane    | Stone Mountain | 225-s028            | 8         | GRRT       | Grease and roots blocked main.  | Barbashela Creek                             | U                | 9/9/2015  | 20:26            | Pressure washed main 120 feet up from s027 to remove grease blockage at 10 feet.  | 09/10/15       | 09/10/15     | CCTV 105 feet down from s028 to find and remove grease.                 |   |
| 6      | 9/10/2015                                  | 10:59                      | n         | Yes         | 22,507                   | 2384 Spring Creek Road      | Decatur        | 113-s035            | 24        | МН         | Hole in bench and wall<br>of manhole 113-s035<br>discovered while<br>inspecting manholes. | Burnt Fork Creek                             |                  | 9/10/2015 | 15:15            | Repaired manhole with bricks and hydraulic cement after plugging line to reduce flow.   | 09/10/15       | 09/11/15     | Pole camera inspection of manhole after repair showed no other defects. |   |
| 6      | 9/10/2015                                  | 19:47                      | n         |             | 7,650                    | 1942 East Starmont Way      | Decatur        | 172-s045            | 15        | STORM      | Heavy localized rain event.   | Doolittle Creek                              |                  | 9/10/2015 | 22:20            | Attempted to rod line and found no issues. Waited for rain to subside.  | 09/11/15       | 09/11/15     |   | Will investigate a piping change in this area.  |
| 6      | 9/16/2015                                  | 13:35                      | n         |             | 2,750                    | 2201 Briarcliff Road        | Atlanta        | 109-s086            | 8         | GR         | Grease blocked main and overflowed out of unmapped manhole and not broken line.           | North Peachtree Creek                        | U                | 9/16/2015 | 22:45            | Used Vac truck to contain spill while line was cleaned when manhole exposed   | 09/17/15       | 09/17/15     |   | Hidden manhole spill site not broken line. Added to CARL list for cleaning frequency due to flat spots. |
| 6      | 9/16/2015                                  | 16:00                      | n         |             | 1,200                    | 4272 Winters Chapel Road    | Doraville      | 341-s023            | 10        | BRK LN/STR | Line broken at manhole.   | Nancy Creek                                  | 2                | 9/16/2015 | 17:00            | Built a berm to contain the spill, removed manhole at edge of creek and installed 17 feet of PVC main and rip-rapped the bank.                                      | 09/17/15       | 09/17/15     | CCTV 226 feet from s025 and found no other defects.                     |   |
| 6      | 5 9/18/2015                                | 9:10                       | n         | Yes         | 15,750                   | 1250 Meadow Lane Road       | Atlanta        | 349-s343            | 12        | GRDB       | Grease, rags and tissue blocked main.   | Nancy Creek                                  | U                | 9/18/2015 | 15:00            | Pressure washed main upstream from s071<br>400 feet to clear grease blockage at 117 feet.<br>Had to expose unmarked manhole in pavement<br>which caused some delay. | 09/18/15       | 09/21/15     | CCTV from s071 to s343 and found no defects.                            |   |
| 6      | 9/20/2015                                  | 10:51                      | n         |             | 4,180                    | 1576 Nantahalia Court       | Atlanta        | 110-s011            | 8         | BRK LN/STR | Main split at top of<br>bank from possible<br>issues with crossing<br>structure.          | North Fork Peachtree<br>Creek                | U                | 9/20/2015 | 14:20            | Plugged open end of main to stop flow and controlled with vac truck.  | 09/20/15       | 09/21/15     | CCTV not possible due to structure and pipe condition.                  |   |
| 6      | 9/21/2015                                  | 11:31                      | n         |             | 2,160                    | 2228 Snapfinger Road        | Decatur        | 126-s001            | 8         | GR         | Grease blocked main.  | Fowler Branch                                | U                | 9/21/2015 | 13:19            | Rodded up from s075 to clear blockage at 200 feet followed by 300 feet of pressure washing.   | 09/21/15       | 09/21/15     | CCTV main 205 feet from<br>s025 to find and remove<br>grease and roots. |   |
| 6      | 9/27/2015                                  | 22:27                      | n         |             | 10                       | 1576 Nantahalia Court       | Atlanta        | 110-s011            | 8         | CRK BRK    | Flange leaking from creek crossing issue. See #66.  | North Fork Peachtree<br>Creek                | U                | 9/27/2015 | 23:45            | Plugged open end of main to stop flow and controlled with vac truck.  | 09/28/15       | 09/28/15     | Made temporary repairs pending a more permanent solution.               | In process to secure contractor to make long term repair to crossing.                                   |
| 6      | 9/30/2015                                  | 12:45                      | n         |             | 3,120                    | 1551 West Nancy Creek Drive | Brookhaven     | 326-s015            | 24        | CRK BRK    | Line crossing creek had crack in bottom of pipe.  | West Nancy Creek                             | U                | 9/30/2015 | 15:21            | Built berm to contain the spill while repair was completed.   | 10/01/15       | 10/01/15     | Line repaired and bank armored 10-21-15.                                |   |

|                    | DeKalb County Department of Watershed Management Consent Decree SSO Tracking Sheet |                               |                            |  |                |       |  |                  |                  |  |                    |                  |  |   |  |   |  |
|--------------------|--|-------------------------------|----------------------------|--|----------------|-------|--|------------------|------------------|--|--------------------|------------------|--|---|--|---|--|
|                    | 3rd Quarter 2015 Building Back-up Report   |                               |                            |  |                |       |  |                  |                  |  |                    |                  |  |   |  |   |  |
|                    | Date/Time Location Cause/Source  |                               |                            |  |                |       |  |                  |                  | Flow Restoration   | Number             |                  | Actions  |   |  |   |  |
| Building Back-up # | Date Spill Reported to<br>DWM  | Time Spill Reported to<br>DWM | Quantity in Gallons (est.) | Address of Spill                               | City           | Cause | Source/Additional<br>Description   | Restoration Date | Restoration Time | Flow Restoration Action  | Service Request    | Cleaning Service | Inspection Results   | Additional Follow-up                            | Faulty Home Plumbing or<br>Not to Code | Update Comments                                   |  |
| B14-15             | 8/18/2015  | 13:43                         | 10                         | 2192 Fairway Circle                            | Atlanta        | СС    | County contractor pressure<br>washing lines for CCTV<br>caused back-up in home | 8/18/2015        | 13:45            | Stopped pressure washing.  | 1529162            | N                | Contractor error   | Contractor to address all issues with homeowner | Υ                                      | No property line cleanout                         |  |
| B15-15             | 9/2/2015   | 9:32                          | 50                         | 1700 Weatherly Drive                           | Stone Mountain | GR    | Grease blocked main  | 9/2/2015         | 11:20            | Rodded 250 feet unsuccessfully followed by 300 feet of pressure washing to remove blockage at 250 feet.              | 1530773            | Yes              | CCTV 289 feet from<br>s037 to s040 to find no<br>defects.  |   | Υ                                      | No property line cleanout.                        |  |
| B16-15             | 9/14/2015  | 16:44                         | 8                          | 3976 Gloucester Drive                          | Tucker         | GR    | Grease blocked main.   | 9/14/2015        | 18:00            | Pressure washed 300 feet from s201 to s200 to clear grease blockage at 200 feet,                                     | 1532158            | Yes              | CCTV 428 feet and<br>found a root ball at 164<br>feet and 178 feet.<br>Removed to clear main.                        |   | Υ                                      | No backwater valve                                |  |
| B17-15             | 9/15/2015  | 2:00                          | 1                          | 1700 Belle Isle Circle                         | Atlanta        | СС    | county contrator (IVIIVI&E) pressure washing caused                            | 9/15/2015        | 2:49             | Stopped pressure washing.  |                    | No               | rtomovod to olodi mam  |   |  | Customers would not allow                         |  |
| 617-15             | 9/13/2015  | 3:00                          | 1                          | 1701 Belle Isle Circle                         | Aliania        |       | interior overflow  | 3/13/2013        | 3:15             | Stopped pressure washing.  |                    | No               |  |   |  | internal investigation.                           |  |
| B18-15             | 9/18/2015  | 17:00                         | 1                          | 1691 Oak Lane                                  | Brookhaven     | CC    | County contrator (MM&E) pressure washing caused interior overflow.             | 9/18/2015        | 17:00            | Stopped pressure washing.  |                    | No               |  |   |  | Customers would not allow internal investigation. |  |
| B19-15             | 9/21/2015  | 12:33                         | 200                        | 4002 Flakes Mill Road                          | Decatur        | RT    | Roots blocked main.  | 9/21/2015        | 14:15            | Attempted to rod 150 feet followed by 500 feet of pressure washing up from s112 to remove root blockage at 300 feet. | 1533025            | Yes              | CCTV 267 feet from<br>s112 to s111 to find a<br>root ball at 189 feet.<br>Removed roots and<br>normal flow restored. |   | Υ                                      | No backwater valve                                |  |
| B20-15             | 9/30/2015  | 14:30                         | 5<br>5                     | 1419 Briarhaven Trail<br>1421 Briarhaven Trail | Brookhaven     | СС    | County Contractor Caused Building Backup                                       | 9/30/2015        | 14:35            | MM&E stopped cleaning the line. Homeowners did not allow interior inspection or clean-up.                            | 1536629<br>1536628 | No<br>No         | None   | Advised contrator to properly clean lines       | Y                                      | No backwater valve No backwater valve             |  |

|                    | DeKalb County Department of Watershed Management Consent Decree SSO Tracking Sheet |                               |                                     |                         |                |            |   |                  |                  |  |                 |  |   |  |
|--------------------|--|-------------------------------|-------------------------------------|-------------------------|----------------|------------|---|------------------|------------------|--|-----------------|--|---|--|
| 3rd Qu             | rd Quarter 2015 SSO (Surface Spills)   |                               |                                     |                         |                |            |   |                  |                  |  |                 |  |   |  |
| Date/Time Location |  |                               |                                     | Location                | Cause/Source   |            |   |                  |                  | Flow Restoration   | Number          | Results  |   |  |
| Overflow #         | Date Spill Reported<br>to DWM  | Time Spill Reported<br>to DWM | 0   $\overline{a}$   $\overline{c}$ |                         | City           | Cause      | Source/Additional<br>Description  | Restoration Date | Restoration Time | Flow Restoration<br>Action   | Service Request | Inspection<br>Results  | Update<br>Comments                          |  |
| S26-15             | 07/15/15   | 9:09                          | 200                                 | 2701 Colombia Drive     | Decatur        | BRK LN/STR | Bottom of 24 inch line deteriorated                                       | 07/15/15         | 15:30            | Built a berm to contain spill and made temporary repair 7-16-15 while seeking permanent repair to line 20 feet in the air. | 1524049         | Line deteriorated. Pole<br>camera inspection of 5<br>manholes showed no other<br>defects. Special project<br>created.                        | Seeking repair/replacement of whole segment |  |
| S27-15             | 08/07/15   | 14:38                         | 20                                  | 3183 Parkridge Crescent | Chamblee       | BRK LN/STR | Main broken down at 131 feet.   | 08/08/15         | 16:15            | Attempted to rod unsuccessfully followed by pressure washing to 131 feet which restored flow but pulled back mud.          | 1527412         | Made point repair 8-9-15 followed by CCTV of 312 feet of line to find no other defects.  |   |  |
| S28-15             | 08/25/15   | 13:01                         | 40                                  | 4217 Westbrook Court    | Tucker         | RT         | Roots blocked main  | 08/25/15         | 14:05            | Rodded line from s036 up 50 feet without success. Pressure washed 104 feet to remove blockage at 50 feet.                  |                 | CCTV 101 feet from s035 and s036 to find and remove roots at 25 feet.  |   |  |
| S29-15             | 09/02/15   | 9:32                          | 748                                 | 1700 Weatherly Drive    | Stone Mountain | GR         | Grease blocked main.  | 09/02/15         | 11:20            | Attempted to rod 250 unsuccessfully. Pressure washed line 300 feet to remove blockage at 250 feet.                         | 1530773         | CCTV 289 feet from s037 to s040 and found no defects.  |   |  |
| S30-15             | 09/10/15   | 12:00                         | 100                                 | 4664 Flat Bridge Road   | Lithonia       | BRK LN/STR | Force main separated at seem on HDPE pipe.                                | 09/10/15         | 12:20            | Repaired joint.  | 1531744         | No CCTV  |   |  |
| S31-15             | 09/14/15   | 15:48                         | 30                                  | 2015 Brian Way          | Decatur        | GR         | Grease blocked main causing surcharge and spill from side of manhole.     | 09/14/15         | 16:35            | Pressure washed main 369 feet.   | 1532145         | CCTV main 453 feet from<br>s002 to s005 to find and<br>remove grease. Invert in s003<br>repaired on 10-7-15.                                 |   |  |
| S32-15             | 09/17/15   | 8:27                          | 1,000                               | 6021 Regent Manor       | Lithonia       | DB         | Rags blocked main. Later found rock in invert causing the actual problem. | 09/17/15         | 10:26            | Rodded up from s016 to clear blockage and pressure washed 150 feet also.   | 1532567         | CCTV 238 feet from s016 to<br>s033 to find and remove a<br>large rock in the invert.   |   |  |
| S33-15             | 09/24/15   | 11:09                         | 100                                 | 1677 Ridgewood Drive    | Atlanta        | GR         | Grease blocked main   | 09/24/15         | 12:05            | Pressure washed up from s211 five feet to clear blockage.  | 1533503         | CCTV 108 feet from s208 to<br>s211 to find an offset joint at<br>103 feet and made point<br>repair on 10-6-15. Raised one<br>buried manhole. |   |  |