

**DeKalb County Department of Watershed Management Consent Decree SSO Tracking Sheet**

**Spills that Entered Waters of the US/State First Quarter 2014**

SSO NO.	Date/Time		Type & Volume			Location		MH/Line		Cause/Source		Water Body		Flow Restoration			Notification Dates			Update Comments
	Date Spill Reported to DWM	Time Spill Reported to DWM	Fish Kill	Major Spill	Estimated Quantity, gals	Address of Spill	City	Manhole/Structure #	Pipe Size	Cause	Source	Receiving Stream or Waterbody	Tributary	Restoration Date	Restoration Time	Flow Restoration Action	24 hour Notice	5 Day Letter	Additional Follow-up	Comments
1	1/1/2014	16:58	n		1,280	2004 Breckinridge Drive	Atlanta	192-s086	8	GR	Grease blocked main.	North Fork Peachtree Creek	U-D2	1/1/2014	17:30	Pressure washed main 204 feet to remove blockage at 132 feet and restore flow.	01/01/14	01/02/14	CCTV 8 inch main 473 and found heavy roots and removed by root cutting. Grease accumulation was in roots.	
2	1/7/2014	10:58	n		1,960	5159 West Mountain Street	Stone Mountain	090-s068	8	DB	Tissue and rags blocked main.	Barbashela Creek	U	1/7/2014	11:47	Rodded main 135 feet to remove blockage at 111 feet and restore flow.	01/08/14	01/08/14	CCTV 8 inch main 138 feet and found and removed a protruding stub at 73 feet which caused the tissue and rags to accumulate.	
3	1/8/2014	10:25	n		3,240	2440 Dooley Drive	Decatur	059-s030	10	RT	Roots blocked main.	Candler Lake	L	1/8/2014	11:37	Rodded main 9 feet to restore flow and root cut/cleaned 325 feet of main.	01/08/14	01/09/14	CCTV revealed some small cracks and small roots at joints. Add to root control list.	
4	1/16/2014	9:17	n		3,120	48 Dartmouth Avenue	Avondale	232-s012	8	GR	Grease blocked main.	East Fork Shoal Creek	U	1/16/2014	10:35	Pressure washed main 296 feet to remove blockage at 22 feet to restore flow.	01/16/14	01/17/14	CCTV revealed small roots and a hole in the pipe. Added to root control list.	
5	1/21/2014	11:33	n		1,880	3574 Oakvale Road	Decatur	051-s003	8	GR	Grease blocked main.	Blue Creek		1/21/2014	12:20	Pressure washed main 350 feet to remove blockage at 320 feet and restore flow.	01/21/14	01/22/14	CCTV 8 inch main and found no other defects.	
6	1/25/2014	17:58	n		4,380	4016 Natalie Trail	Decatur	029-s185	8	GR	Grease blocked main.	South River		1/25/2014	19:11	Pressure washed manhole 029s185 75 feet downstream to remove blockage at 25 feet and restored flow.	01/26/14	01/28/14	CCTV 8 inch main 500 feet to find and remove heavy grease by pressure washing. Some roots removed with root cutter.	
7	1/27/2014	13:35	n		290	604 Ponce De Leon Place	Decatur	006-s068	8	BRK LN/STR	Broken main at 30 and 90 feet caused spill and 006-s066 to surcharge.	Lamont Drive Branch of Peavine Creek		1/27/2014	18:25	Pressure washed upstream from 006s068 100 feet and cleared blockage at 90 feet to restore flow. Point repairs made on line in 2 places and to manhole.	01/28/14	01/30/14	CCTV 160 feet and found two point repairs and a manhole repair all of which were completed 2-10-14.	
8	1/31/2014	8:40	n		7,200	3577 Santa Fe Trail	Doraville	312-s015	10	GRDB	Main blocked with grease, bottles, cans and trash.	Northfork Peachtree Creek	U-1	1/31/2014	11:20	Rodded, pressure washed and root cut 198 feet of main to remove blockage at 170 feet and restore flow.	01/31/14	02/03/14	CCTV 10 inch main 350 feet to find and remove sand and rocks.	
9	2/2/2014	12:25	n		1,600	960 B Sheppard Road	Stone Mountain	N/A	8	GR	Main blocked by grease.	Barbashela Creek	U	2/2/2014	13:45	Rodded to remove blockage at 75 feet and pressure washed line 250 feet.	02/02/14	02/03/14	Contractors cleaning area for pole camera inspection.	
10	2/3/2014	8:32	n		8,100	3911 Oberlin Court	Tucker	187-s043	8	OTH	Fallen tree broke 8 inch main.	South Fork Peachtree Creek	A	2/3/2014	10:47	Customer emailed report on 2-1-14 and processed 2-3-14. Vac trucks contained spill while sewer main repaired.	02/03/14	02/04/14	Repaired PVC line with 12 1/2 feet of line while controlling flow with vac trucks.	
11	2/4/2014	10:20	n		1,500	4445 Britt Road	Tucker	289-s202	8	GRRT	Grease and roots blocked sewer main causing leak from side of manhole.	Lucky Shoals Creek	U	2/4/2014	11:35	Pressure washed main 700 feet to remove blockage at 100 feet.	02/05/14	02/05/14	CCTV 414 feet and inspection found 2 manholes for repair and an offset joint at 114 feet. Offset joint repaired 3-11-14.	
12	2/5/2014	10:03	n		5,000	2289 Snapfinger Manor	Decatur	097-s040	10	GR	Grease blocked main.	Snapfinger Creek		2/5/2014	10:53	Pressure washed 10 inch main 342 feet to remove blockage at 108 feet.	02/05/14	02/06/14		
13	2/13/2014	13:25	n		2,520	3160 Buford Highway	Atlanta	198-s034	8	GRDB	Grease and rags blocked line.	North Fork Peachtree Creek	U	2/13/2014	14:07	Rodded 72 feet to restore flow then pressure washed 705 feet of 8 inch main.	02/13/14	02/14/14	In Contractor follow-up area for CCTV and Cleaning under PASARP.	
14	2/25/2014	14:34	n		2,400	1135 Clairmont Avenue	Decatur	005-p021	8	GRRT	Grease and roots blocked the sewer main causing overflow from private manhole.	South Fork Peachtree Creek	U	2/25/2014	16:34	Rodded main which did not restore flow and pressure washed 300 feet to remove blockage at 105 feet to restore flow.	02/26/14	02/26/14	CCTV 105 feet to blockage point and determined sewer main was broken. Repaired main on 3-4-14. CCTV a total of 340 feet after repair and no other issues found.	
15	2/26/2014	7:52	n		9	4379 Autumn Hill Drive	Stone Mountain	N/A	8	CRK BRK	Broken creek crossing dripping sewage in creek.	Snapfinger Creek		2/26/2014	9:21	Flow controlled by vac truck while repair made on 2-26-14 followed by pressure washing 230 feet.	02/26/14	02/27/14		
16	2/28/2014	8:14	n		2,240	792 Jolly Avenue South	Clarkston	066-s033	8	GR	Grease blocked main.	Indian Creek		2/28/2014	9:10	Rodded 8 inch main 99 feet to clear blockage and restore flow.	02/28/14	03/03/14	CCTV 8 inch main 611 feet and removed heavy grease by pressure washing.	

DeKalb County Department of Watershed Management Consent Decree SSO Tracking Sheet

Spills that Entered Waters of the US/State First Quarter 2014

SSO NO.	Date/Time		Type & Volume			Location		MH/Line		Cause/Source		Water Body		Flow Restoration			Notification Dates			Update Comments
	Date Spill Reported to DWM	Time Spill Reported to DWM	Fish Kill	Major Spill	Estimated Quantity, gals	Address of Spill	City	Manhole/Structure #	Pipe Size	Cause	Source	Receiving Stream or Waterbody	Tributary	Restoration Date	Restoration Time	Flow Restoration Action	24 hour Notice	5 Day Letter	Additional Follow-up	Comments
17	3/1/2014	11:45	n		2,040	3892 Buford Highway	Doraville	236-s070	8	GR	Grease blocked main.	North Fork Peachtree Creek	U	3/1/2014	12:36	Pressure washed 8 inch main 50 feet to restore flow.	03/02/14	03/03/14	Part of CCTV contract area.	Clarified waterbody name.
18	3/1/2014	15:25	n		1,170	4801 Buford Highway	Chamblee	280-s042	10	GR	Grease blocked main.	North Fork Peachtree Creek	B	3/1/2014	15:51	Rodded 25 feet up from 280-s041 to restore flow followed by 50 feet of pressure washing..	03/02/14	03/03/14	Part of CCTV contract area.	
19	3/2/2014	14:09	n		1,680	2759 Chicopee Drive	Doraville	341-s068	8	GRDB	Grease and rags blocked line.	Nancy Creek	2	3/2/2014	14:57	Pressure washed 8 inch line 250 feet to clear grease and rags at 221 feet.	03/02/14	03/03/14	CCTV main 250 feet to find and remove roots. There was also a crack in the wye where the spill occurred.	
20	3/4/2014	11:11	n		189	2515 Northeast Expressway	Atlanta	205-s017	8	BRK LN/STR	Broken main caused sewer to enter storm drain.	North Fork Peachtree Creek	U	3/4/2014	14:20	Established vacuum truck to control flow while main repaired 38 feet from 205-s017.	03/05/14	03/05/14	CCTV 110 feet and inspected manhole to find no defects after repair.	
21	3/4/2014	15:12	n		2,220	3449 Glenwood Road	Decatur	169-s033	8	GR	Grease blocked main.	Shoal Creek	U	3/4/2014	15:49	Rodded main 3 feet from spilling manhole to restore flow. Pressure washed 700 feet and added degreaser to line.	03/04/14	03/05/14	CCTV 550 feet to find and remove grease and roots.	
22	3/5/2014	13:33	n		2,600	1050 Crowne Point Parkway	Dunwoody	349-s026	8	GR	Grease blocked main.	Perimeter Creek		3/5/2014	14:38	Next downstream manhole too deep for rods. Pressure washed the 8 inch line 308 feet to remove blockage at 60 feet.	03/05/14	03/06/14	CCTV 300 feet to find and remove grease.	
23	3/8/2014	17:39	n		8,800	1177 Wynterhall Lane	Dunwoody	365-s315	8	GR	Grease blocked main.	Marsh Creek		3/8/2014	21:19	Rodded main 70 feet but could not restore flow. Pressure washed main 850 feet to remove blockage at 75 feet.	03/09/14	03/10/14	CCTV 158 feet to find and remove grease. Point repair replaced 12 feet and 8 inches of line heavily blocked with grease.	
24	3/8/2014	17:48	n		3,060	3088 Rockaway Road	Atlanta	285-s050	8	GR	Grease blocked main.	Lake Louise	U	3/8/2014	18:39	Rodded 150 feet upstream without success. Pressure washed 200 feet to remove blockage at 180 feet to restore flow.	03/09/14	03/10/14	CCTV 300 feet to find and remove grease.	
25	3/9/2014	15:30	n		2,560	1552 Edinburgh Drive	Tucker	144-s207	8	GR	Grease blocked main.	Twin Brothers Lake		3/9/2014	16:34	Rodded downstream 150 feet without success. Pressure washed 600 feet to remove blockage 250 feet to restore flow.	03/09/14	03/10/14	CCTV 394 feet to find and remove roots.	Spill in LL 144
26	3/14/2014	13:29	n		335	2367 North Peachtree Way	Dunwoody	310-s085	8	UNK	Unknown blockage caused manhole overflow to storm drain.	Northeast Creek	U	3/14/2014	14:29	Used vacuum truck to control spill. Pressure washed 200 feet to remove unknown blockage at 137 feet.	03/14/14	03/17/14	CCTV 800 feet to find and remove debris (tissue) and grease.	Water Body Updated
27	3/25/2014	10:39	n		3,600	1955 Montreal Road	Tucker	190-s064	8	GR	Grease blocked main.	Burnt Fork Creek	U	3/25/2014	11:51	Pressure washed 8 inch line 200 feet to clear grease at 110 feet.	03/25/14	03/26/14	CCTV 200 feet to find and remove grease at 110 feet.	Part of larger FOG investigation.
28	3/25/2014	11:24	n		1,920	5620 Bend Creek Road	Dunwoody	379-s009	8	OUTSIDE CON	Contractor bored water line through sewer line.	Ball Mill Creek	U	3/25/2014	13:00	Rodded 8 inch main 30 feet to remove unknown blockage and restore flow.	03/25/14	03/26/14	Upon investigation found water line bored through sewer main causing partial blockage. Pressure washed 160 feet of line after repair. No other defects found.	
29	3/25/2014	13:17	n		2,680	2275 Sagamore Hills Drive	Decatur	160-s094	8	GRRT	Grease and roots blocked main.	North Fork Peachtree Creek	U	3/25/2014	14:24	Pressure washed 8 inch main 417 feet to clear blockage at 175 feet.	03/25/14	03/26/14		Corrected water body.
30	3/25/2014	18:21	n		6,060	4338 Webb Road	Tucker	260-s014	8	RTDB	Roots and rags blocked main.	Lucky Shoals Creek		3/25/2014	20:02	After attempting to rod main without success the line was pressure washed 8 inch main 350 feet to clear blockage at 31 feet.	03/25/14	03/26/14	CCTV 555 feet to find and remove roots.	
31	3/27/2014	10:03	n		2,360	3958 East Brookhaven Drive	Atlanta	240-s050	8	GRDB	Grease and rags blocked line.	Capital City Club Lake		3/27/2014	11:02	Rodded 8 inch main 110 feet upstream to clear blockage at 90 feet. Pressure washed area 1,050 feet.	03/27/14	03/28/14	CCTV 149 feet to find and remove grease in line.	
32	3/31/2014	13:14	n		1,925	5035 Vermack Road	Dunwoody	361-s111	8	GRRT	Grease, paper towels and rags blocked county main causing private un-numbered manhole to overflow.	Nancy Creek	A	3/31/2014	14:31	After rodding the 8 inch main 175 feet did not restore flow the line was pressure washed 800 feet to clear blockage at 607 feet and restore flow.	04/01/14	04/01/14	Informed school of items found that appear to be coming from their private line. FOG investigation on grease trap.	

Overflow (Surface Spills) First Quarter 2014													
Overflow #	Date/Time		Quantity in Gallons	Location		Cause/Source		Flow Restoration			Number	Results	
	Date Spill Reported to DWM	Time Spill Reported to DWM		Address of Spill	City	Cause	Source/Additional Description	Restoration Date	Restoration Time	Flow Restoration Action		Service Request	Inspection Results
S01-14	01/02/14	11:59	25	4282 East Ponce De Leon Avenue	Clarkston	BRK LN/STR	8 inch main broken and spill contained in the hole.	01/02/14	13:30	Break at 7 feet replaced with 5 feet of 8 inch PVC on 1-2-14 and manhole repaired 1-22-14.	1400257	CCTV 169 feet to find and remove minor grease by pressure washing.	Made point repair to line 7 feet out of manhole by replacing 5 feet 8 inches of line. Manhole also repaired. CCTV followed.
S02-14	01/04/14	13:01	100	1121 Church Street	Decatur	GRDB	Grease and debris (tissue) blocked main.	01/04/14	14:15	Rodded line 4 feet to restore flow and pressure washed 450 feet to clean line.	1400574	CCTV 1600 feet of 12 inch main to find and remove minor roots.	
S03-14	01/11/14	9:36	2,550	101 Green Street	Decatur	STORM	Heavy rain caused surface spill.	01/11/14	11:24	Rain inundated system and caused overflow.	1402188	Major inspection program along creek and in area.	Manholes rehabilitated to replace vented covers, seal those in creek, repaired abandoned stubs in creek and relocated a manhole to help control future spills.
S04-14	01/14/14	10:01	200	4556 Meadow Creek Path	Lithonia	GR	Grease blocked main.	01/14/14	11:00	Rodded line 240 feet to restore flow and then pressure washed 300 feet to clean line.	1402671	CCTV of 8 inch main for 315 feet found and removed minor grease.	
S05-14	01/15/14	16:31	1,000	4832 Terrace Green Trace	Stone Mountain	GR	Grease blocked main	01/16/14	12:50	Pressure washed main 240 feet to restore flow followed by an additional 300 feet of cleaning.	1403076	Mapping contractors did not call dispatch to report spill in a timely manner. Corrective action taken against them.	CCTV 8 inch main 180 feet found no defects.
S06-14	01/19/14	9:47	2,480	5101 Browns Mill Road	Lithonia	GR	Grease blocked main causing private force main to spill.	01/19/14	10:49	Pressure washed line 150 feet to remove blockage at 55 feet.	1403507		
S07-14	01/23/14	11:26	500	3575 Oakvale Road	Decatur	GRRT	Grease and roots blocked main.	01/23/14	13:00	Pressure washed main 90 feet to clear blockage in mouth of spilling manhole after rodding the line did not restore the flow.	1403999	CCTV 8 inch main to find and remove roots.	
S08-14	01/27/14	9:46	7	465 Clairmont Avenue	Decatur	GRDB	Grease and wipes blocked line.	01/27/14	10:19	Pressure washed 6 inch cleanout 40 feet to remove blockage and restore flow after excavating buried cleanout.	1404593	Repaired cleanout 2-3-14 and then inspected lateral to find no additional problems.	Cleanout is laying flat with good flow now.
S09-14	02/04/14	8:59	2	976 Viscount Court	Avondale Estates	RT	Roots blocked lateral past property line cleanout	02/04/14	10:04	Crew excavated and repaired 19.5 feet of lateral 2-4-14 to restore flow after rodding did not clear blockage.	1405802		
S10-14	02/06/14	9:04	2	791 Briar Park Court	Atlanta	UNK	Lateral blocked by unknown material.	02/06/14	10:08	Rodded lateral 6 feet and restored flow and stopped seeping from cleanout.	1406127	CCTV the 6 inch lateral and found heavy roots at 6 feet.	Point repair made 2-20-14
S11-14	01/21/14	10:14	2,500	3643 Glenwood Road	Decatur	GR	Grease blocked main	01/21/14	11:20	Pressure washed 400 feet of 8 inch main to remove blockage at 150 feet.	1403642	CCTV 8 inch main 620 feet to find and remove heavy grease and debris (Tissue) by pressure washing.	Late Reporting
S12-14	02/18/14	12:21	5	740 Sycamore Drive	Decatur	OUTSIDE CON	Lateral broken 10 feet from property line cleanout. Break caused by gas line bored through sewer main.	02/18/14	14:18	Rodded line 10 feet from property line cleanout and determined lateral was broken. Point repair made on 2-18-14.	1407128	Pressure washed the stub to remove debris.	Damage created by gas line installation through lateral.
S13-14	02/18/14	20:43	75	2741 Tryon Place	Atlanta	GR	Grease blocked main.	02/18/14	23:00	Rodded main 89 feet and pressure washed 250 feet to clear blockage at 90 feet and restore flow.	1407202	CCTV 181 feet to find and remove roots.	
S14-14	02/19/14	11:41	5	465 Clairmont Avenue	Decatur	UNK	6 inch lateral blocked by an unknown cause.	02/19/14	14:30	Rodded from 6 inch property line cleanout 24 feet to remove blockage at 12 feet. Could not determine cause.	1407285	CCTV 8 inch main 310 feet to find and remove sand and rocks coming from a stub. Main was relined previously.	
S15-14	02/19/14	13:41	1,500	4886 Wedgewood Way	Stone Mountain	GR	Grease blocked main.	02/19/14	15:00	Pressure washed main 260 feet to remove blockage at 160 feet and restore flow.	1407282	CCTV 210 feet of main and found no other defects or issues.	
S16-14	02/27/14	9:26	40	3633 Bishop Drive	Tucker	GR	Grease blocked main.	02/27/14	9:50	Pressure washed main 500 feet to clear blockage at 80 feet and restore flow.	1408571	CCTV 125 feet to find and remove roots.	
S17-14	03/03/14	9:58	80	1302 Mannbrook Drive	Stone Mountain	GR	Grease blocked main.	03/03/14	11:15	Pressure washed 8 inch main 500 feet to remove blockage at 150 feet from 194-s205	1409160	CCTV 170 feet to find debris (tissue) and removed by pressure washing.	

Overflow (Surface Spills) First Quarter 2014													
Overflow #	Date/Time		Quantity in Gallons	Location		Cause/Source		Flow Restoration			Number	Results	
	Date Spill Reported to DWM	Time Spill Reported to DWM		Address of Spill	City	Cause	Source/Additional Description	Restoration Date	Restoration Time	Flow Restoration Action	Service Request	Inspection Results	Update Comments
S18-14	02/26/14	12:40	20	3600 Donaldson Drive	Brookhaven	UNK	Grease blocked lateral	02/26/14	15:30	Rodded 4 inch property line cleanout to restore flow.	1406965	CCTV and pressure washed 250 feet of main and found no defects. CCTV of property line to determine point repair was needed at 7 feet and completed on 3-10-14	Late Reporting
S19-14	03/05/14	17:30	100	1401 North Hairston Road	Stone Mountain	GR	Grease blocked main.	03/05/14	18:10	Rodded 163 feet and could not restore flow. Pressure washed 235 feet to remove blockage at 163 to restore flow.	1409731	CCTV 115 feet to find rocks/sand which were removed.	Additional cleaning assigned to cleaning contractor.
S20-14	03/10/14	10:37	2,675	2821 Misty Water Drive	Decatur	GR	Grease blocked main.	03/10/14	12:24	Pressure washed main 209 feet to remove blockage at 42 feet from 136-s049	1410402	CCTV 228 feet to find grease and roots which were removed by pressure washing.	
S21-14	03/11/14	13:20	660	3549 Waldrop Trail	Decatur	GRDB	Grease and rags blocked main.	03/11/14	13:53	Rodded main upstream 115 feet to restore flow followed by pressure washing 225 feet.	1410607	CCTV 228 feet found and removed grease and roots with pressure washing.	
S22-14	03/12/14	12:54	20	1732 Childerlee Lane	Atlanta	RT	Crew root cutting 8 inch main had overflow event.	03/12/14	13:07	Continued root cutting to remove blockage from 8 inch line. Total footage was 20.	1410765	CCTV 250 feet after point repair completed and found no other defects.	B10-14 Building Back-up connected to this overflow.
S23-14	03/19/14	12:37	5	4445 Cowan Road	Tucker	BRK LN/STR	Broken lateral found. Call originated as a water leak.	03/19/14	14:00	Rodded 4 inch property line cleanout 44 feet to restore flow. Found mud on bit.	1411709	Stub repaired on 3-25-14.	
S24-14	03/22/14	14:50	3,660	4651 Big Valley Road	Stone Mountain	VAND	Manhole had sticks put in it to cause blockage.	03/22/14	15:51	After attempting to rod spilling manhole used pressure washer upstream to clear blockage. Removed sticks and pressure washed 160 feet of line to restore flow.	1412309	CCTV 568 feet to find and remove some grease in the line. Manhole joint was repaired on 3-31-14.	
S25-14	03/24/14	12:16	2	5201 Skyline Drive	Stone Mountain	RT	Roots blocked lateral.	03/24/14	12:55	Rodded 4 inch lateral to remove roots at 18 feet and restore flow.	1412482	CCTV 200 feet and found no defects.	

## DeKalb County Department of Watershed Management Consent Decree SSO Tracking Sheet

### Building Back-up Report First Quarter 2014

Building Back-up #	Date/Time		Quantity in Gallons (est.)	Location		Cause/Source		Flow Restoration			Number	Actions				
	Date Spill Reported to DWM	Time Spill Reported to DWM		Address of Spill	City	Cause	Source/Additional Description	Restoration Date	Restoration Time	Flow Restoration Action	Service Request	Cleaning Service	Inspection Results	Additional Follow-up	Faulty Home Plumbing or Not to Code	Update Comments
B01-14	01/08/14	16:48	15	1443 Holly Bank Circle	Dunwoody	GRRT	Grease and roots blocked main.	01/08/14	19:15	Rodded 165 feet to remove blockage followed by pressure washing 334 feet.	1401346	Yes	CCTV found 7 taps with roots.	Cleaned and root cut 300 feet of line. Will arrange for root treatment.	YES	Sent backwater valve letter.
B02-14	01/27/14	21:23	10	408 South Susan Creek Drive	Stone Mountain	GRRT	Grease and roots blocked main.	01/27/14	22:30	Rodded 8 inch main 30 feet to clear blockage and restore flow. Pressure washed 400 feet also. Manhole 013-s018.	1404855	No	Outfall line high flow is causing grease to back up in 8 inch main. CCTV, pressure washed and root cut 275 feet of main.	Requested Engineering to add to capacity review list for outfall line on April 22, 2014	YES	Customer refused cleaning service. Sent backwater valve letter
B03-14	02/01/14	16:30	8	4103 Green Oak Drive	Doraville	GR	Grease blocked line.	02/01/14	19:00	Rodded main 150 feet without success. Pressure washed main 360 feet to remove blockage at 320 feet.	1405389	No	CCTV 8 inch main 354 feet found and removed roots at 102 feet. No other defects found.		YES	Customer refused cleaning service. Sent backwater valve letter
B04-14	02/05/14	21:30	N/A	4488 Huntington Circle	Dunwoody	GRRT	Grease and roots blocked main.	02/06/14	1:00	Rodded main 130 feet to clear blockage. Pressure washed 180 feet to clean line.	1406093	No	CCTV 400 feet of main, removed some roots and found no other defects.		YES	Customer refused cleaning service and to allow inspection of interior claimed spill. Sent backwater.
B05-14	02/22/14	22:43	8	1807 Queens Way	Chamblee	RT	Roots blocked main just outside a flush tank.	02/23/14	1:30	Rodded 5 feet from flush tank to restore flow.	1407728	Yes	CCTV 305 feet, found and removed minor roots.	Roots at 13 feet in tap. Point repair completed on April 23, 2014	YES	Sent backwater valve letter.
B06-14	02/23/14	22:25	100	1287 Sunland Drive	Atlanta	RTDB	Roots and debris (rags) blocked line	02/23/14	23:45	Rodded 30 feet upstream from 241-s076 to clear blockage.	1047794	Yes	Room exposed to outside and had pre-existing heavy mold on all walls, leaves on floor and branches inside. Citizen continually delayed cleaning for several days.	CCTV of 433 feet of 8 inch main showed erosion/corrosion caused holes at the bottom of 4 stubs. Point repairs completed on April 11, 2014	YES	Sent backwater valve letter.
B07-14	02/24/14	20:25	45	1478 Biltmore Drive	Atlanta	DB	Found water cooler blocking manhole invert line.	02/24/14	22:00	Removed cooler and rodded main 21 feet downstream to an unmapped manhole to restore flow. Pressure washed 75 feet.	1408050	Yes	CCTV 8 inch main 178 feet and found sand and rocks which were removed with pressure washing.	Updated GIS maps.	YES	Damage pictures taken. Sent backwater valve letter.
B08-14	02/25/14	7:19	5	2391 Henderson Pines Court	Tucker	RT	Roots blocked main.	02/25/14	8:38	Rodded main and hit roots. Made point repair to stub.	1408061	No	Customer cleaned small amount of wastewater up.	Stub repair completed 2-25-14 to correct issue.	YES	Customer refused cleaning service and to allow inspection of interior claimed spill. Sent backwater letter.
B09-14	02/27/14	11:27	N/A	4898 Pinnacle Drive	Stone Mountain	OTH	County crew hit private lateral during water line repair.	02/27/14	11:50	Repaired 4 inch private lateral and reconnected to 6 inch property line cleanout.	1408603	Yes	CCTV 6 inch lateral after repair to verify no issues.		X	Sent backwater valve letter.
B10-14	03/12/14	17:49	50	1705 Woodcliff Drive	Atlanta	RT	Main blocked by roots causing flush tank to surcharge and enter building.	03/12/14	19:00	Root cut the 8 inch line 20 feet to clear the blockage.	1410816	Yes	Related to Surface Spill S22-14. CCTV 8 inch main 250 feet and found no other defects after repair to remove the root ball.		X	Sent backwater valve letter