Chief Executive Officer Michael L. Thurmond

Board of Commissioners

District 1
Robert Patrick

District 2 Jeff Rader

District 3 Larry Johnson

District 4 Steve Bradshaw

District 5 Mereda D. Johnson

District 6 Edward 'Ted' Terry

District 7 Lorraine Cochran-Johnson

Chief, Clean Water Branch ATTN: Ms. Sara Janovitz Water Protection Division U.S. Environmental Protection Agency - Region 4

Via Electronic Mail and U.S. Mail

61 Forsyth Street, S.W. Atlanta, GA 30303

January 30, 2021

RE: Clean Water Act Consent Decree 1:10cv 4039-WSD January 30, 2021 – 2020 4th Quarterly Report Submittal

Dear Ms. Janovitz:

As required by §IX. Reporting Requirement of the Consent Decree associated with the above referenced civil action, we are submitting the following document for your review and comment:

• January 30, 2021 - 2020 4th Quarterly Report

I certify under penalty of law that these documents and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering such information, the information submitted is, to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fines and imprisonment for knowing violations pursuant to CWA Section 309(c)(4).

If you have questions or comments regarding this submittal, please call me at 404-371-2174.

Respectfully,

Zachary L. Williams,

Chief Operating Officer and Executive Assistant

DeKalb County, Georgia

cc: Georgia EPD

Viviane Ernstes, County Attorney

Maria V. Houser, Director of Consent Decree and Environmental Compliance

Reginald D. Wells, Director, DWM

Brent Zern, Consent Decree Administrator

E. Fitzgerald Veira, Troutman Sanders

Matthew C. Welch, Deputy County Attorney

										DeKalb County Department of Watershed Managemen	nt Consent Decree S Spills	SO Tracking Sheet 4	4th Quarter R	Report 2	020			
	Date/1	ſime	Type &	Volume	Location		MH/pi	ре		Cause/Source	<u>'</u>	er Body			Flow Restoration			Notifications
	Date Spill	Time Spill Reported to		Estimated Quantity,			Manhole /				Receiving Stream or		Restoration Re	estoration				
Spill No.	Reported to DWM	DWM	Fish Kill Spill	gals	Address of Spill	City	Structure #	(in)	Cause	Source	Waterbody	Tributary	Date	Time	Flow Restoration Action	24 hour Notice	5 Day Letter	Additional Follow-up
221	10/5/2020	14:26	N N	18,975	4168 REDAN ROAD	STONE MOUNTAIN	227-S060	36	OUTSIDE CON	FOUND MANHOLE 15-227-5060 SPILLING INTO SNAPFINGER CREEK DUE TO A 12(IN) BYPASS PUMP MALFUNCTION.	SNAPFINGER CREEK	UNNAMED	10/5/2020	15:35	REPAIRED AND RESTARTED THE BYPASS PUMP TO STOP THE SPILL, WHICH RESTORED NORMAL FLOW.	10/5/2020	10/8/2020	CLEANED UP SPILL SITE. POSTED PUBLIC NOTIFICATIONS.
222	10/6/2020	14:28	N N	3,680	4491 BOWMAN INDUSTRIAL COURT	CONLEY	014-S014	8	GR	FOUND MANHOLE 15-014-S014 OVERFLOWING ON 8(IN) SEWER MAIN DUE TO A GREASE BLOCKAGE.	CONLEY CREEK	N/A	10/6/2020	16:00	PRESSURE WASHED 8(IN) SEWER MAIN FROM MANHOLE 15-014-S113 TO MANHOLE 15-014-S014 100(FT) TO REMOVE THE GREASE BLOCKAGE AT 100(FT) TO RESTORE NORMAL FLOW.	10/6/2020	10/8/2020	CCTV AND CLEANUP WORK ORDERS CREATED
223	10/8/2020	8:41	N N	2,000	5410 SANDELL COURT	DUNWOODY	N/A	8	BRK LN/STR	FOUND 8(IN) BROKEN SEWER MAIN SPILLING INTO KINGSLEY LAKE.	KINGLEY LAKE	UNNAMED	10/8/2020	10:21	REMOVED BROKEN PIPE AND REPLACE WITH 8(IN) PVC TO STOP THE SPILL, WHICH RESTORED NORMAL FLOW.	10/8/2020	10/12/2020	REPAIR AND CLEANUP WORK ORDERS CREATED.
224	10/10/2020	20:50	N Y	16,750	2089 GARDEN CIRCLE	DECATUR	N/A	4	1&1	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING 4(IN) PRIVATE CLEANOUT TO SPILL INTO DOOLITTLE CREEK.	DOOLITTLE CREEK	N/A	10/11/2020	2:25	ACTIVELY MONITORED UNTIL CONTAINMENT WAS ACHIEVED. REMOVED DEBRIS AND DISINFECTED AREA WITH LEMONEX. POSTED 6 SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/11/2020(10/16/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
225	10/10/2020	21:57(20:15)	N N	9,498	1078 BEECH HAVEN ROAD	ATLANTA	108-S007	12	181	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #18-108-5007 TO SPILL INTO SOUTH FORK PEACHTREE CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	SOUTH FORK PEACHTREE CREEK	UNNAMED	10/10/2020		REMOVED DEBRIS AND DISINFECTED THE AREA WITH LEMONEX. POSTED SPILL SIGNS FOR PUBLIC NOTIFICATIONS.	10/11/2020(10/15/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
226	10/10/2020	22:02	N Y	53,550	2804 MILLWOOD WAY	DECATUR	147-S081	21 & 24	1&1	RAIN WATER ENTERED THE SEWER SYSTEM DURING HEAVY RAIN EVENT CAUSING MANHOLE 18-147-S081 TO SPILL INTO BURNT FORK CREEK.	BURNT FORK CREEK	N/A	10/10/2020	2:00	ACTIVELY MONITORED UNTIL SPILL WAS CONTAINED. CLEANUP DEBRIS AND DISINFECTED THE AREA WITH LEMONEX. POSTED SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/11/2020(10/15/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
227	10/10/20202	22:05	N Y	33,255	1416 COBB BRANCH DRIVE	DECATUR	197-S008	10	1&1	RAIN WATER ENTERED THE SEWER SYSTEM DURING HEAVY RAIN EVENT CAUSING MANHOLE 15-197-S008 TO SPILL INTO BURNT FORK CREEK.	COBBS CREEK	N/A	10/11/2020	3:05	ACTIVELY MONITORING UNTIL SPILL IS CONTAINED. CLEANUP DEBRIS AND DISINFECTED THE AREA WITH LEMONEX. POSTED SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/11/2020(10/15/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
228	10/10/2020	22:31(21:30)	N N	6,548	2052 GRAND PRIX DRIVE	ATLANTA	193-S086	10	1&1	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #18-193-5086 TO SPILL INTO NORTH FORK PEACHTREE CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	NORTH FORK PEACHTREE CREEK	D-2	10/10/2020		REMOVED DEBRIS AND DISINFECTED THE AREA WITH LEMONEX. POSTED SPILL SIGNS FOR PUBLIC NOTIFICATIONS.	10/11/2020(10/15/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
229	10/10/2020	22:23	N Y	76,175	2610 BRIARLAKE ROAD	ATLANTA	206-S023	10	1&1	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #18-206-5023 TO SPILL INTO NORTH FORK PEACHTREE CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	NORTH FORK PEACHTREE CREEK	D-1	10/11/2020	3:00	REMOVED DEBRIS AND DISINFECTED THE AREA WITH LEMONEX. POSTED SPILL SIGNS FOR PUBLIC NOTIFICATIONS.	10/11/2020(10/15/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
230	10/10/2020	22:32	N N	3,804	234 WEST DAVIS STREET	DECATUR	214-S017	8	1&1	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #15-214-S017 TO SPILL INTO SHOAL CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	SHOAL CREEK	N/A	10/11/2020	1:00	ACTIVELY MONITORED UNTIL SPILL IS CONTAINED. REMOVED DEBRIS AND DISINFECTED THE AREA WITH LEMONEX. POSTED SPILL SIGNS FOR PUBLIC NOTIFICATIONS.	10/11/2020(10/15/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
231	10/10/2020	22:45	N Y	11,500	249 SOUTH COLUMBIA DRIVE	DECATUR	234-\$145	8	1&1	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #15-234-S145 TO SPILL INTO SHOAL CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	SHOAL CREEK	N/A	10/11/2020	3:00	ACTIVELY MONITORED UNTIL SPILL IS CONTAINED. CLEANUP DEBRIS AND DISINFECTED THE AREA WITH LEMONEX. POSTED SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/11/2020(10/15/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
232	10/10/2020	22:48	N Y	52,800	3273 PINEHILL DRIVE	DECATUR	199-S024	12	1&1	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #15-199-S024 TO SPILL INTO COBBS CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	COBBS CREEK	N/A	10/11/2020	2:00	ACTIVELY MONITORED UNTIL SPILL IS CONTAINED. CLEANUP DEBRIS AND DISINFECTED THE AREA WITH LEMONEX. POSTED SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/11/2020(10/15/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
233	10/10/2020	23:15(21:15)	N Y	13,150	608 SOUTH MCDONOUGH STREET	DECATUR	214-S013	8	1&1	RAIN WATER ENTER THE SEWER SYSTEM DURING HEAVY RAIN EVENT CAUSING MANHOLE #15-214-S013 TO SPILL INTO SHOAL CREEK.	SHOAL CREEK	WEST	10/10/2020	22:15	ACTIVELY MONITORED UNTIL CONTAINMENT WAS ACHIEVED. REMOVED DEBRIS AND DISINFECTED THE AREA WITH LEMONEX. POSTED 6 SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/11/2020(10/16/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
234	10/11/2020	01:06(20:45)	N Y	238,727	1615 MELANIE COURT	DECATUR	184-S004, S002	24	1&1	RAIN WATER ENTER THE SEWER SYSTEM DURING HEAVY RAIN EVENT CAUSING MANHOLE #15-184-S004 AND #15-184-S002 TO SPILL INTO SHOAL CREEK.	SHOAL CREEK	N/A	10/11/2020	1:30	ACTIVELY MONITORED UNTIL CONTAINMENT WAS ACHIEVED. REMOVED DEBRIS AND DISINFECTED THE AREA WITH LEMONEX. POSTED 6 SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/11/2020(10/16/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
235	10/11/2020	08:00(11:15)	N Y	4,051,320	4557 MEADOW CREEK PATH	LITHONIA	034-S090	54	1&1	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #15-034-5090 TO SPILL INTO SNAPFINGER CREEK	SNAPFINGER CREEK	N/A	10/12/2020	1:45	ACTIVELY MONITORING UNTIL CONTAINMENT IS ACHIEVED. REMOVED DEBRIS AND DISINFECTED AREA WITH LEMONEX. POSTED 10 SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/11/2020(10/16/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
236	10/11/2020	9:52	N N	4,700	1945 PONCE DE LEON AVENUE	ATLANTA	238-S205	8	DB	FOUND MANHOLE #15-238-S205 SPILLING INTO A STORM DRAIN DUE TO A DEBRIS BLOCKAGE.	PEAVINE CREEK SOUTH FORK	UNNAMED	10/11/2020	13:00	PRESSURE WASHED 8(IN) SEWER MAIN 150(FT) TO REMOVE THE DEBRIS BLOCKAGE AT 20(FT) TO RESTORE NORMAL FLOW.	10/11/2020	10/16/2020	CCTV AND RAISE MANHOLE WORK ORDERS CREATED
237	10/11/2020	10:25	N Y	20,300	3391 WARBLER DRIVE	DECATUR	091-S039	30	1&1	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #15-091-5039 TO SPILL INTO SNAPFINGER CREEK	COBBS CREEK	N/A	10/11/2020	17:11	ACTIVELY MONITORING UNTIL CONTAINMENT IS ACHIEVED. REMOVED DEBRIS AND DISINFECTED AREA WITH LEMONEX. POSTED 10 SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/11/2020(10/15/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
238	10/11/2020(10/10 /2020)	11:05:00 AM(23:00)	N Y	25,500	217 GREEN STREET	DECATUR	214-S003	8	1&1	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #15-214-S003 TO SPILL INTO SNAPFINGER CREEK	SHOAL CREEK	WEST	10/11/2020	1:50	ACTIVELY MONITORING UNTIL CONTAINMENT IS ACHIEVED. REMOVED DEBRIS AND DISINFECTED AREA WITH LEMONEX. POSTED 10 SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/11/2020(10/16/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
239	10/11/2020	12:15	N Y	30,924	4027 FLAKES MILL ROAD	DECATUR	036-S150, 162 AND 037-S081	42	1&1	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLES #15-036-5150, S162 AND #15-037-5081 TO SPILL INTO SOUTH RIVER CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	SOUTH RIVER	N/A	10/11/2020	1:15	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES. REMOVED ALL DEBRIS AND DISINFECTED THE AREA.	10/13/2020(10/15/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
240	10/11/2020	12:17:00 PM(12:15)	N Y	10,308	4124 FLAKES MILL ROAD	ELLENWOOD	030-S012	60	1.8.1	ELECTRICAL POWER LOSS CAUSING SEWER TO BACKUP IN THE TRUNK LINES, WHICH CAUSED SEWER TO ESCAPE FROM MANHOLE #15-030-5012 AND ENTER THE SOUTH RIVER.	SOUTH RIVER	N/A	10/11/2020	1:15	RESTORED THE POWER AND RESTARTED ALL THREE ILS PUMPS TO STOP THE SPILL.	10/11/2020(10/16/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
241	10/11/2020(10/10 /2020)	12:32(21:45)	N Y	388,640	1496 COUNTRY SQUIRE DRIVE	DECATUR	147-S085	24	1&1	RAIN WATER ENTERED THE SEWER SYSTEM DURING HEAVY RAIN EVENT CAUSING MANHOLE #18-147-5085 TO SPILL INTO BURNT FORK CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	BURNT FORK CREEK	UNNAMED	10/11/2020	2:00	ACTIVELY MONITORED UNTIL CONTAINMENT WAS ACHIEVED. REMOVED DEBRIS AND DISINFECTED AREA WITH LEMONEX. POSTED 6 SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/11/2020(10/16/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
242	10/11/2020(10/10 /2020)	15:08(20:30)	N Y	308,167	3087 THRASHER CIRCLE	DECATUR	136-\$801	12	1&1	RAIN WATER ENTERED THE SEWER SYSTEM DURING HEAVY RAIN EVENT CAUSING MANHOLE #15-136-S801 TO SPILL INTO SHOAL CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	SHOAL CREEK	UNNAMED	10/11/2020	3:45	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES. REMOVED ALL DEBRIS AND DISINFECTED THE AREA.	10/11/2020(10/16/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
243	10/11/2020(10/10 /2020)	17:23(10:15)	N Y	42,468	1956 EAST STARMOUNT WAY	DECATUR	172-S036	15 & 6	1&1	RAIN WATER ENTERED THE SEWER SYSTEM DURING HEAVY RAIN EVENT CAUSING MANHOLE #15-172-5036 AND THREE 6(IN) CLEANOUTS TO SPILL INTO DOOLITILE CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA FOR THE MANHOLE.	DOOLITTLE CREEK	N/A	10/11/2020		ACTIVELY MONITORING UNTIL CONTAINMENT IS ACHIEVED. REMOVED DEBRIS AND DISINFECTED AREA WITH LEMONEX. POSTED 6 SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/11/2020(10/16/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE

									DeKalb County Department of Watershed Manageme	ent Consent Decree	SSO Tracking Sheet	4th Quarter	er Report 2	020			
	Date/	Date/Time Type & Volume Location MH/pipe Cause/Source Water Body Flow Restoration											Flow Restoration			Notifications	
Spill No	Date Spill	Time Spill Reported to DWM	Major Estimated Quanti	ity, Address of Spill		Manhole / Pi	ipe Size	Cause	Source	Receiving Stream or Waterbody	Tributary	Restoration Date	Restoration Time	Flow Restoration Action	24 hour Notice	5 Day Letter	Additional Follow-up
244	10/11/2020(10/10	20:37(09:30)	N Y 121,089	2480 MIRIAM LANE			21	I&I	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #15-136-S012 AND S013 TO SPILL INTO SHOAL CREEK. THIS	SHOAL CREEK	N/A	10/10/2020	1:00	ACTIVELY MONITORING UNTIL CONTAINMENT IS ACHIEVED. REMOVED DEBRIS AND DISINFECTED AREA	10/11/2020(10/15/202	10/15/2020	CLEANED UP SPILL SITE
244	/2020)	20.37(07.30)	1 121,007	2400 WINNAW EAVE	DECATOR 130	3-3012, 3013	21	ion	INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	SHOPE GREEK	1975	10/10/2020	1.00	WITH LEMONEX. POSTED 6 SPILL SIGNS FOR PUBLIC NOTIFICATION.	0-REVISED)	10/13/2020	CELANED OF STILE STILE
245	10/11/2020	21:17	N N 9,000	308 2ND AVENUE	DECATUR 2	213-S052	8	I&I	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MH #15-213-s052 TO SPILL INTO SUGAR CREEK.	SUGAR CREEK	A	10/11/2020	1:30	ACTIVELY MONITORING UNTIL CONTAINMENT IS ACHIEVED. REMOVED DEBRIS AND DISINFECTED AREA WITH LEMONEX. POSTED 4 SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/11/2020(10/16/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
246	10/12/2020	10:21	N N 4,800	2685 MILSCOTT DRIVE	DECATUR 0	048-S001	8	l&I	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MH \$18-048-s001 TO SPILL INTO SOUTH FORK PEACHTREE CREEK.	SOUTH FORK PEACHTREE CREEK	С	10/11/2020	11:09	ACTIVELY MONITORING UNTIL CONTAINMENT IS ACHIEVED. REMOVED DEBRIS AND DISINFECTED AREA WITH LEMONEX. POSTED 4 SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/12/2020	10/15/2020	CCTV AND CLEANUP WORK ORDERS CREATED
247	10/12/2020(10/10 /2020)	13:10(20:30)	N Y 18,719	1354 WESTON DRIVE	DECATUR 197	7-S007, S013	10	1&1	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #15-197-5007 AND \$013 TO SPILL INTO COBBS CREEK THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	COBBS CREEK	N/A	10/10/2020	23:45	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES. REMOVED ALL DEBRIS AND DISINFECTED THE AREA.	10/13/2020(10/16/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
248	10/13/2020(10/10 /2020)	10:21(22:39)	N N 8,290	3924 ROMAN COURT	TUCKER 1	167-S208	8	I&I	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #18-167-S208 TO SPILL INTO SOUTH FORK PEACHTREE CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	SOUTH FORK PEACHTREE CREEK	A	10/11/2020	0:00	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES. REMOVED ALL DEBRIS AND DISINFECTED THE AREA.	10/13/2020(10/15/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
249	10/13/2020(10/10 /2020)	11:07(22:30)	N Y 927,282	3549 PANTHERSVILLE ROAD	DECATUR 073	3-S006,S010	30	1&1	RAIN WATER ENTER THE SEWER SYSTEM DURING HEAVY RAIN EVENT CAUSING MANHOLES #15-073-S006 AND #15-073-S-010 TO SPILL INTO TRIBUTARY A INTO SOUTH RIVER. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	SOUTH RIVER	А	10/11/2020	12:30	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES. REMOVED ALL DEBRIS AND DISINFECTED THE AREA.	10/13/2020(10/15/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
250	10/13/2020(10/10 /2020)	13:11(22:00)	N Y 454,307	3230 BORING ROAD	DECATUR 0	070-S016	30	I&I	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #15-070-S016 TO SPILL INTO SHOAL CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	SHOAL CREEK	N/A	10/11/2020	12:15	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES. REMOVED ALL DEBRIS AND DISINFECTED THE AREA.	10/13/2020(10/15/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
251	10/13/2020(10/10 /2020)	13:40(20:45)	N Y 34,297	2562 TILLY MILL ROAD	DORAVILLE 3	335-S027	8	1&1	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #18-335-5027 TO SPILL INTO NANCY CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	NANCY CREEK	1	10/10/2020	23:45	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES. REMOVED ALL DEBRIS AND DISINFECTED THE AREA.	10/13/2020(10/15/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
252	10/13/2020(10/10 /2020)	14:55(21:30)	N N 8,928	607 3RD AVENUE	DECATUR 2	213-S050	8	1&1	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #15-213-5050 TO SPILL INTO SUCAR CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	SUGAR CREEK	А	10/11/2020	0:15	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES. REMOVED ALL DEBRIS AND DISINFECTED THE AREA.	10/13/2020(10/16/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
253	10/13/2020(10/10 /2020)	15:35(22:30)	N Y 17,245	1440 SOWELL ESTATE	STONE MOUNTAIN 1	141-S110	8	1&1	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #18-141-5110 TO SPILL INTO SOUTH FORK PEACHTREE CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	SOUTH FORK PEACHTREE CREEK	UNNAMED	10/10/2020	23:45	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES. REMOVED ALL DEBRIS AND DISINFECTED THE AREA.	10/13/2020(10/16/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
254	10/13/2020(10/10 /2020)	16:33(20:45)	N Y 124,865	3433 BROOKFIELD LANE	DECATUR 1	187-S067	15	I&I	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #15-187-5067 TO SPILL INTO COBBS CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	COBBS CREEK	N/A	10/11/2020	3:30	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES. REMOVED ALL DEBRIS AND DISINFECTED THE AREA.	10/13/2020(10/16/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
255	10/13/2020(10/10 /2020)	16:33(21:15)	N Y 48,900	3553 BROOKFIELD LANE	DECATUR 1	187-S094	12	1&1	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #15-187-5094 TO SPILL INTO COBBS CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	COBBS CREEK	N/A	10/11/2020	1:15	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES. REMOVED ALL DEBRIS AND DISINFECTED THE AREA.	10/13/2020(10/16/202 0-REVISED)	10/15/2020	CLEANED UP SPILL SITE
256	10/15/2020	17:33	N Y 48,090	2792 MCCLAVE DRIVE	DORAVILLE	N/A	10	BRK LN/STR	FOUND 10(IN) BROKEN SEWER MAIN SPILLING INTO NORTH FORK PEACHTREE CREEK.	NORTH FORK PEACHTREE CREEK	1	10/16/2020	5:00	THE EMERGENCY RESPONSE CONTRACTORS SETUP BYPASS PUMPS TO CONTAIN THE SPILL UNTIL THE FINAL REPAIRS ARE COMPLETED.	10/16/2020(10/19/202 0-REVISED)	10/20/2020	CCTV AND REPAIR WORK ORDERS CREATED
257	10/19/2020	10:44	N N 1,500	1514 SHERIDAN ROAD	ATLANTA 1	153-S040	12	BRK LN/STR	FOUND 12(IN) BROKEN SEWER MAIN SPILLING INTO NORTH FORK PEACHTREE CREEK.	NORTH FORK PEACHTREE CREEK	UNNAMED	10/19/2020	16:30	THE CONTRACTORS REPAIRED THE BROKEN 12(IN) SEWER MAIN.	10/20/2020	10/23/2020	REPAIR WORK ORDERS CREATED
258	10/19/2020	14:20	N N 1,600	116 CLAIREMONT AVENUE		PRIVATE MANHOLE	8	GR	FOUND PRIVATE MANHOLE SPILLING INTO UNNAMED TRIBUTARY INTO PEAVINE CREEK DUE TO A GREASE BLOCKAGE IN THE 8(IN) COUNTY SEWER MAIN.	PEAVINE CREEK	UNNAMED	10/19/2020	15:40	PRESSURE WASHED THE 8(IN) SEWER MAIN 100(FT) FROM MANHOLE 15-246-S124 TO CLEAR THE GREASE BLOCKAGE AT 30(9FT), WHICH RESTORED NORMAL FLOW.	10/19/2020	10/23/2020	CCTV AND FOG WORK ORDERS CREATED
259	10/20/2020	15:28	N N 2,745	2771 MABRY ROAD	ATLANTA 2	240-S007	12	GR	FOUND MANHOLE #18-240-S007 SPILLING INTO NORTH FORK PEACHTREE CREEK DUE TO A GREASE BLOCKAGE.	NORTH FORK PEACHTREE CREEK	А	10/20/2020	16:29	PRESSURE WASHED THE 12(IN) SEWER MAIN 230(FT) FROM MANHOLE 18-240-S005 TO CLEAR THE GREASE BLOCKAGE AT 216(FT), WHICH RESTORED NORMAL FLOW.	10/20/2020	10/23/2020	CCTV AND FOG WORK ORDERS CREATED
260	10/21/2020	20:13	N N 100	2406 GLENROCK DRIVE	DECATUR	N/A	6	DB	FOUND 6(IN) ROW CLEANOUT OVERFLOWING ONTO THE SURFACE DUE TO DEBRIS BLOCKAGE. WHILE PRESSURE WASHING THE DRIVEWAY FROM THE CLEANUP SOME OF THE SEWER ENTER THE STORM DRAIN.	SHOAL CREEK	UNNAMED	10/21/2020	20:35	STOP PRESSURE WASHING THE DRIVEWAY AND CLEANED UP THE AREA WITH LEMONEX.	10/21/2020	10/26/2020	CLEANED UP SPILL SITE
261	10/24/2020	18:37	N N 4,390	2089 GARDEN CIRCLE	DECATUR	N/A	18	l&l	RAIN WATER ENTERED THE SEWER SYSTEM DURING HEAVY RAIN EVENT CAUSING 4(IN) PRIVATE CLEANOUT TO SPILL INTO DOOLITTLE CREEK.	DOOLITTLE CREEK	N/A	10/25/2020	9:15	REMOVE DEBRIS AND DISINFECTED THE AREA WITH LEMONEX. POSTED SEWER SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/25/2020(10/29/202	10/29/2020	CLEANED UP SPILL SITE
262	10/24/2020	20:35	N Y 74,500	2804 MILLWOOD WAY	DECATUR 1	147-S081 2	21 & 24	1&1	RAIN WATER ENTERED THE SEWER SYSTEM DURING HEAVY RAIN EVENT CAUSING MANHOLE 18-147-5081 TO SPILL INTO BURNT FORK CREEK.	BURNT FORK CREEK	N/A	10/25/2020	9:00	ACTIVELY MONITORED UNTIL SPILL WAS CONTAINED. CLEANUP DEBRIS AND DISINFECTED THE AREA WITH LEMONEX. POSTED SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/25/2020(10/29/202 0-REVISED)	10/29/2020	CLEANED UP SPILL SITE
263	10/26/2020	8:25	N Y 13,500	2685 MILSCOTT DRIVE	DECATUR 0	048-S001	8	1&1	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MH 18-048-9001 TO SPILL INTO SOUTH FORK PEACHTREE CREEK.	SOUTH FORK PEACHTREE CREEK	С	10/26/2020	14:19	ACTIVELY MONITORED UNTIL CONTAINMENT IS ACHIEVED. REMOVED DEBRIS AND DISINFECTED AREA WITH LEMONEX. POSTED SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/26/2020(10/29/202 0-REVISED)	10/29/2020	CLEANED UP SPILL SITE
264	10/26/2020(10/24 /2020)	12:14(19:45)	N Y 95,706	1615 MELANIE COURT	DECATUR 184	4-S004, S002	24	1&1	RAIN WATER ENTER THE SEWER SYSTEM DURING HEAVY RAIN EVENT CAUSING MANHOLE 15-184-S004, S002 TO SPILL INTO SHOAL CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	SHOAL CREEK	N/A	10/25/2020	2:00	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES. REMOVED ALL DEBRIS AND DISINFECTED THE AREA. POSTED SPILL SIGNS FOR PUBLIC NO TIFICATION.	10/26/2020(10/29/202 0-REVISED)	10/29/2020	CLEANED UP SPILL SITE
265	10/26/2020(10/24 /2020)	13:58(22:15)	N Y 1,605,240	4557 MEADOW CREEK PATH	LITHONIA C	034-S090	48	1&1	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #15-034-5090 TO SPILL INTO SNAPFINGER CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	SNAPFINGER CREEK	N/A	10/25/2020	8:45	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES. REMOVED ALL DEBRIS AND DISINFECTED THE AREA. POSTED SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/26/2020(10/29/202 0-REVISED)	10/29/2020	CLEANED UP SPILL SITE
266	10/27/2020(10/24 /2020)	09:11(19:30)	N Y 109,869	1496 COUNTRY SQUIRE DRIVE	DECATUR 1	147-S085	24	1&1	RAIN WATER ENTERED THE SEWER SYSTEM DURING HEAVY RAIN EVENT CAUSING MANHOLE 18-147-S085 TO SPILL INTO BURNT FORK CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	BURNT FORK CREEK	N/A	10/24/2020	23:00	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES. REMOVED ALL DEBRIS AND DISINFECTED THE AREA. POSTED SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/27/2020(10/29/202 0-REVISED)	10/29/2020	CLEANED UP SPILL SITE

										DeKalb County Department of Watershed Management	ent Consent Decree S Spills	SO Tracking Sheet	4th Quarter Repor	t 2020			
	Date/Tii	ne	Туре 8	& Volume	Location		MH/pi	pe		Cause/Source		er Body		Flow Restoration			Notifications
Spill No.	Date Spill Reported to DWM	Time Spill Reported to DWM	Major Fish Kill Spill	Estimated Quantity, gals	Address of Spill	City	Manhole / Structure #	Pipe Size (in)	Cause	Source	Receiving Stream or Waterbody	Tributary	Restoration Restorati	on Flow Restoration Action	24 hour Notice	5 Day Letter	Additional Follow-up
267	10/27/2020(10/24 /2020)	09:57(21:45)	N Y	13,745	1440 SOWELL ESTATE	STONE MOUNTAIN	141-S110	8	I&I	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #18-141-S110 TO SPILL INTO SOUTH FORK PEACHTREE CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	SOUTH FORK PEACHTREE CREEK	UNNAMED	10/25/2020 1:45	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES. REMOVED ALL DEBRIS AND DISINFECTED THE AREA POSTED SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/27/2020(10/29/202 0-REVISED)	10/29/2020	CLEANED UP SPILL SITE
268	10/27/2020(10/24 /2020)	12:00(19:00)	N Y	15,155	3911 ROMAN COURT	TUCKER	167-S208	8	1&1	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #18-167-5208 TO SPILL INTO SOUTH FORK PEACHTIREE CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	SOUTH FORK PEACHTREE CREEK	A	10/25/2020 1:45	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES. REMOVED ALL DEBRIS AND DISINFECTED THE AREA POSTED SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/27/2020(10/29/202 0-REVISED)	10/29/2020	CLEANED UP SPILL SITE
269	10/27/2020	13:07	N N	300	2012 GLENWOOD AVENUE	ATLANTA	180-S014	10	GR	FOUND MANHOLE #15-180-S014 SPILLING INTO SUGAR CREEK DUE TO A GREASE BLOCKAGE.	SUGAR CREEK	А	10/27/2020 14:30	PRESSURE WASHED THE 10(IN) SEWER MAIN 150(FT) TO CLEAR THE GREASE BLOCKAGE AT 100(FT), WHICH RESTORED NORMAL FLOW.	10/28/2020	10/29/2020	CCTV AND FOG WORK ORDERS CREATED
270	10/29/2020	13:41 (09:00)	N Y	112,875	4710 BROWNS MILL ROAD	LITHONIA	251-S010, S012, S041	36	ОТН	FOUND THREE MANHOLES SPILLING INTO POLE BRIDGE CREEK DUE TO A POWER FAILURE AT POLE BRIDGE TREATMENT PLANT FROM HURRICANE DELTA.	POLE BRIDGE CREEK	N/A	10/29/2020 14:15	THE POWER WAS RESTORED AT POLE BRIDGE TREATMENT AND THE MANHOLES STOP OVERFLOWING.	10/29/2020(11/03/202 0-REVISED)	11/3/2020	CLEANED UP SPILL SITE
271	10/29/2020	15:28	N Y	63,200	3854 WEST NANCY CREEK PLACE	ATLANTA	N/A	8	BRK LN/STR	FOUND 8(IN) CREEK CROSSING SPILLING INTO PERIMETER CREEK DUE TO BROKEN CREEK CROSSING/ STRUCTURAL DAMAGE.	PERIMETER CREEK	UNNAMED	10/30/2020 2:00	CONTACTOR'S SETUP BYPASS PUMPS TO STOP THE SPILL UNTIL FINAL REPAIRS ARE COMPLETED.	10/29/2020(11/03/202 0-REVISED)	11/3/2020	CLEANED UP SPILL SITE
272	10/29/2020	15:30(07:15)	N Y	993,720	4557 MEADOW CREEK PATH	LITHONIA	034-\$090	54	I&I	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING MANHOLE #15-034-5090 TO SPILL INTO SNAPFINGER CREEK. THIS INFORMATION WAS RETRIEVED FROM FLOW MONITORING DATA.	SNAPFINGER CREEK	N/A	10/29/2020 13:45	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES. REMOVED ALL DEBRIS AND DISINFECTED THE AREA. POSTED SPILL SIGNS FOR PUBLIC NOTIFICATION.	10/29/2020(11/3/2020- REVISED)	11/3/2020	CLEANED UP SPILL SITE
273	10/30/2020	10:05	N N	600	880 HOUSTON MILL ROAD	ATLANTA	N/A	4	ОТН	FOUND EVIDENCE OF A 4(IN) BYPASS PUMP VALVE HOSE THAT WAS DISCONNECTED BY A FALLEN TREE.	SOUTH FORK PEACHTREE CREEK	N/A	10/30/2020 10:50	CONTRACTOR'S WERE ON SITE AND HAD TO REPAIR THE VALVE, WHICH STOPPED THE SPILL.	10/30/2020	11/4/2020	CLEANED UP SPILL SITE
274	10/31/2020	10:45	N N	300	3854 WEST NANCY CREEK PLACE	ATLANTA	N/A	4	ОТН	FOUND A BYPASS PUMP HOSE SPILLING INTO PERIMETER CREEK DUE TO A HOLE IN THE DISCHARGE HOSE.	PERIMETER CREEK	N/A	10/31/2020 12:30	CONTACTOR'S REPLACED THE DISCHARGE HOSE TO STOP THE SPILL.	10/31/2020	11/4/2020	CLEANED UP SPILL SITE
275	10/31/2020	11:14	N Y	11,560	3557 WALDROP TRAIL	DECATUR	N/A	10	BRK LN/STR	FOUND SEWER SPILLING INTO SOUTH RIVER DUE TO A BROKEN 10(IN) CREEK CROSSING.	SOUTH RIVER	N/A	10/31/2020 20:52	CONTRACTOR'S SETUP BYPASS PUMPS TO STOP THE SPILL UNTIL FINAL REPAIRS WERE COMPLETED.	10/31/2020(11/03/202 0-REVISED)	11/3/2020	CLEANED UP SPILL SITE
276	11/1/2020	9:42	N N	1,060	1656 BELLE ISLE CIRCLE	ATLANTA	158-S084	8	GR	FOUND MANHOLE #18-158-5084 SPILLING INTO NORTH FORK PEACHTREE CREEK DUE TO A GREASE BLOCKAGE.	NORTH FORK PEACHTREE CREEK	UNNAMED	11/1/2020 10:35	PRESSURE WASHED THE 8(IN) SEWER MAIN 213(FT) TO CLEAR THE GREASE BLOCKAGE AT 210(FT), WHICH RESTORED NORMAL FLOW.	11/1/2020	11/6/2020	CCTV AND FOG WORK ORDERS CREATED
277	11/2/2020	8:43	N N	6,850	1430 SKYHAVEN ROAD	ATLANTA	N/A	8	GR	FOUND SEWER SPILLING INTO ENTRENCHMENT CREEK DUE TO A GREASE BLOCKAGE THAT EXISTED FROM A STRUCTURAL DAMAGE IN THE PIPE.	ENTRENCHMENT CREEK	UNNAMED	11/2/2020 11:00	PRESSURE WASHED THE 8(IN) SEWER MAIN 300(FT) TO CLEAR THE GREASE BLOCKAGE AT 80(FT), WHICH RESTORED NORMAL FLOW.	11/2/2020	11/6/2020	CCTV, FOG AND REPAIR WORK ORDERS CREATED
278	11/2/2020(10/24/ 2020)	12:04(19:45)	N Y	13,125	1227 ROWLAND ROAD	STONE MOUNTAIN	N/A	6	I&I	RAIN WATER ENTERED THE SEWER MAIN DURING HEAVY RAIN EVENT CAUSING 6(IN) CLEANOUT TO SPILL INTO SNAPFINGER CREEK.	SNAPFINGER CREEK	N/A	10/24/2020 21:00	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES. REMOVED ALL DEBRIS AND DISINFECTED THE AREA POSTED SPILL SIGNS FOR PUBLIC NOTIFICATION.	11/2/2020(11/4/2020- REVISED)	11/6/2020	CLEANED UP SPILL SITE
279	11/2/2020(11/1/2 020)	16:38(13:15)	N Y	45,049	7607 HAYDEN QUARRY ROAD	LITHONIA	204-S002	8	GR/DB	FOUND MANHOLE 16-204-S002 SPILLING INTO HONEY CREEK DUE TO A GREASE AND DEBRIS BLOCKAGE. THIS INFORMATION WAS DETERMINED BY FLOW MONITORING DATA.	HONEY CREEK	N/A	11/2/2020 19:30	RODDED THE 8(IN) SEWER MAIN 30(FT) TO CLEAR THE GREASE/DEBRIS BLOCKAGE AT 6(FT), WHICH RESTORED NORMAL FLOW.	11/3/2020(11/04/2020- REVISED)	11/6/2020	CCTV AND FOG WORK ORDERS CREATED
280	11/4/2020	16:31	N N	5,800	4459 COLONY EAST DRIVE	STONE MOUNTAIN	194-S209	36	ОТН	FOUND MANHOLE #18-194-S029 SPILLING INTO SNAPFINGER CREEK DUE TO A PUMP MALFUNCTION DURING THE RELINING OF A THE 36(IN) SEWER MAIN.	SNAPFINGER CREEK	N/A	11/4/2020 17:00	CONTRACTORS REPAIRED THE BYPASS PUMP AND STOPPED THE SEWER SPILL.	11/5/2020	11/9/2020	POSTED PUBLIC NOTIFICATIONS
281	11/4/2020	19:49	и и	3,480	1442 CANOOCHEE DRIVE	ATLANTA	238-S029	8	GR	FOUND MANHOLE #18-238-S029 SPILLING INTO NORTH FORK PEACHTREE CREEK DUE TO A GREASE BLOCKAGE.	NORTH FORK PEACHTREE CREEK	А	11/4/2020 21:16	RODDED THE 8(IN) SEWER MAIN FROM MANHOLE #18-238-5029 10(FT) TO CLEAR THE GREASE BLOCKAGE AT 115(FT), WHICH STOP THE SPILL.	11/5/2020	11/9/2020	CCTV AND FOG WORK ORDERS CREATED
282	11/5/2020	8:50	N N	50	3396 CHAMBLEE TUCKER ROAD	CHAMBLEE	284-S001	8	GR	FOUND EVIDENCE THAT MANHOLE 18-284-S001 HAD SPILLED DUE TO A GREASE BLOCKAGE.	WARREN CREEK	UNNAMED	11/5/2020 9:22	RODDED THE 8(IN) SEWER MAIN FROM MANHOLE #18-284-5002 125(FT) TO CLEAR THE GREASE BLOCKAGE AT 115(FT), WHICH STOP THE SPILL.	11/5/2020	11/9/2020	CCTV AND FOG WORK ORDERS CREATED
283	11/5/2020(11/02/ 2020)	15:00(12:00)	N Y	343,700	4509 MEADOW VISTA TRACE	LITHONIA	N/A	10	BRK LN/STR	FOUND 10(IN) CREEK CROSSING BROKEN AND SPILLING INTO SNAPFINGER CREEK.	SNAPFINGER CREEK	N/A	11/5/2020 21:50	CONTRACTOR'S SETUP BYPASS PUMPS TO STOP THE SPILL UNTIL FINAL REPAIRS WERE COMPLETED.	11/6/2020(11/10/2020- REVISED)	11/10/2020	CLEANED UP SPILL SITE
284	11/7/2020(11/5/2 020)	12:58(10:05)	N N	200	152 CANDLER DRIVE	DECATUR	N/A	6	STRUCTURAL LATERAL DEFECT	FOUND 6(IN) LATERAL DAMAGED FROM A PREVIOUS WATER MAIN REPAIR.	SHOAL CREEK	N/A	11/7/2020 13:35	SCHEDULE AN EMERGENCY LATERAL REPAIR.	11/7/2020(11/8/2020- REVISED)	11/12/2020	REPAIR WORK ORDER CREATED
285	11/8/2020	14:24	N N	1,320	3241 ALTON ROAD	CHAMBLEE	284-S049	8	DB	FOUND MANHOLE #18-284-S049 SPILLING INTO WARREN CREEK DUE TO A RAG DEBRIS BLOCKAGE.	WARREN CREEK	N/A	11/8/2020 15:30	PRESSURE WASHED THE 8(IN) SEWER MAIN 200(FT) TO CLEAR THE DEBRIS BLOCKAGE AT 195(FT), WHICH RESTORED NORMAL FLOW.	11/8/2020	11/12/2020	CLEANED UP SPILL SITE. CREATED CCTV WORK ORDER.
286	11/11/2020	9:35	N Y	67,500	2685 MILSCOTT DRIVE	DECATUR	N/A	8	BRK LN/STR	FOUND SEWER SPILLING INTO NORTH FORK PEACHTREE CREEK DUE TO A STRUCTURAL DAMAGE.	NORTH FORK PEACHTREE CREEK	UNNAMED	11/12/2020 11:30	THE EMERGENCY RESPONSE CONTRACTORS SETUP BYPASS PUMPS TO CONTAIN THE SPILL UNTIL THE FINAL REPAIRS WERE COMPLETED.	11/11/2020(11/12/202 0-REVISED)	11/16/2020	CLEANED UP SPILL SITE. POSTED PUBLIC NOTIFICATIONS.
287	11/14/2020	18:16	N N	500	375 NORTH DESHON ROAD	STONE MOUNTAIN	126-S198	8	GR	FOUND MANHOLE #18-026-S198 SPILLING INTO STONE MOUNTAIN CREEK DUE TO A GREASE BLOCKAGE.	STONE MOUNTAIN CREEK	N/A	11/14/2020 20:30	PRESSURE WASHED THE 8(IN) SEWER MAIN 250(FT) TO CLEAR THE GREASE BLOCKAGE AT 250(FT), WHICH RESTORED NORMAL FLOW.	11/15/2020	11/17/2020	CCTV AND FOG WORK ORDERS CREATED. CLEANED UP SPILL SITE COMPLETED.

											DeKalb County Department of Watershed Management	ent Consent Decree :	SSO Tracking Sheet	4th Quarte	r Report 2	2020			
	Date/	Гime		Type & Volu	me	Location		МН/р	ipe		Cause/Source		ter Body			Flow Restoration			Notifications
Spill No.	Date Spill Reported to DWM	Time Spill Reported to DWM	Fish Kill	Major Estin	nated Quantity, gals	Address of Spill	City	Manhole / Structure #	Pipe Size (in)	Cause	Source	Receiving Stream or Waterbody	Tributary	Restoration Date	Restoration Time	Flow Restoration Action	24 hour Notice	5 Day Letter	Additional Follow-up
288	11/17/2020	14:16	N	N	3,960	3037 KAMMEYER LANE	CHAMBLEE	N/A	8	RT	FOUND SEWER LEAKING INTO NORTH FORK PEACHTREE CREEK DUE TO A ROOT BLOCKAGE.	NORTH FORK PEACHTREE CREEK	UNNAMED	11/17/2020	15:22	EXCAVATED AREA TO REMOVE THE TREE STUMP AND ROOT BLOCKAGE IN THE SEWER MAIN. INSTALL 14(FT) OF PVC PIPE TO STOP THE SPILL AND RESTORED NORMAL FLOW.	11/18/2020	11/20/2020	REPAIR WORK ORDER CREATED
289	11/18/2020	19:42(18:10)	N	N	300	2940 CLAIRMONT ROAD	ATLANTA	N/A	48	CRK BRK	DURING THE SETUP OF A BYPASS PUMP BY THE CONTRACTORS THEY DISCOVERED PLUGGED SEWER MAIN CAUSING CREEK CROSSING TO SPILL INTO NORTH FORK PEACHTREE CREEK	NORTH FORK PEACHTREE CREEK	UNNAMED	11/18/2020	18:12	THE CONTRACTORS REMOVED THE PLUG, WHICH STOP THE SPILL AND RESTORED NORMAL FLOW.	11/19/2020	11/23/2020	POSTED PUBLIC NOTIFICATIONS
290	11/22/2020	13:11	N	N	1,220	4103 WESLEY CLUB DRIVE	DECATUR	126-S013	8	GR	FOUND MANHOLE #15-126-S013 SPILLING INTO THE STORM DRAIN THAT LEADS TO FOWLER BRANCH CREEK DUE TO A GREASE BLOCKAGE.	FOWLER BRANCH CREEK	UNNAMED	11/22/2020	14:12	PRESSURE WASHED THE 8(IN) SEWER MAIN 98(FT) TO CLEAR THE GREASE BLOCKAGE AT 70(FT), WHICH RESTORED NORMAL FLOW.	11/23/2020	11/25/2020	CCTV AND FOG WORK ORDERS CREATED. CLEANED UP SPILL SITE COMPLETED.
291	11/23/2020	13:14	N	Υ	27,300	3310 HARVESTER WOODS ROAD	DECATUR	093-S200	8	DB	FOUND MANHOLE #15-093-S200 SPILLING INTO THE STORM DRAIN THAT LEADS TO SHOAL CREEK DUE TO A DEBRIS (RAGS) BLOCKAGE.	SHOAL CREEK	UNNAMED	11/23/2020	16:16	RODDED THE 8(IN) SEWER MAIN 60(FT) TO CLEAR THE DEBRIS BLOCKAGE AT 57(FT), WHICH RESTORED NORMAL FLOW.	11/23/2020	11/25/2020	CCTV WORK ORDER COMPLETED.
292	11/23/2020	14:46	N	N	2,080	7030 CRESTWOOD PLACE	LITHONIA	026-S005	8	GR	FOUND MANHOLE #18-026-S005 SPILLING INTO NORTH CROOKED CREEK DUE TO A GREASE BLOCKAGE.	NORTH CROOKED CREEK	N/A	11/23/2020 16:30		PRESSURE WASHED THE 8(IN) SEWER MAIN 25(FT) TO CLEAR THE GREASE BLOCKAGE AT 20(FT), WHICH RESTORED NORMAL FLOW.	11/23/2020	11/25/2020	CCTV AND FOG WORK ORDERS CREATED. CLEANED UP SPILL SITE COMPLETED.
293	11/24/2020	11:26	N	N	1,180	2427 BRIARCLIFF ROAD	ATLANTA	153-S094	8	RT	FOUND MANHOLE #18-153-S094 SPILLING INTO WILLOW LAKE TRIBUTARY INTO NORTH FORK PEACHTREE CREEK DUE TO A ROOT BLOCKAGE.	NORTH FORK PEACHTREE CREEK	WILLOW LAKE	11/24/2020	12:25	PRESSURE WASHED THE 8(IN) SEWER MAIN 150(FT) TO CLEAR THE ROOT BLOCKAGE AT 100(FT), WHICH RESTORED NORMAL FLOW.	11/24/2020	11/25/2020	CCTV AND CLEANING WORK ORDERS CREATED.
294	11/25/2020	9:34	N	N	5,160	6039 HILLANDALE DRIVE	LITHONIA	088-S002	8	GR	FOUND MANHOLE #16-088-S002 SPILLING INTO UNNAMED TRIBUTARY INTO POLE BRIDGE CREEK DUE TO A GREASE BLOCKAGE.	POLE BRIDGE CREEK	UNNAMED	11/25/2020	11:00	PRESSURE WASHED THE 8(IN) SEWER MAIN 468(FT) TO CLEAR THE GREASE BLOCKAGE AT 350(FT), WHICH RESTORED NORMAL FLOW.	11/25/2020	11/30/2020	CCTV AND FOG WORK ORDERS CREATED. CLEANED UP SPILL SITE COMPLETED.
295	11/29/2020	22:21	N	N	1,845	2089 GARDEN CIRCLE	DECATUR	N/A	4	I&I	RAIN WATER ENTERED THE SEWER SYSTEM DURING HEAVY RAIN EVENT CAUSING 4(IN) PRIVATE CLEANOUT TO SPILL INTO DOOLITTLE CREEK.	DOOLITTLE CREEK	N/A	11/30/2020	4:30	REMOVE DEBRIS AND DISINFECTED THE AREA WITH LEMONEX. POSTED SEWER SPILL SIGNS FOR PUBLIC NOTIFICATION.	11/30/2020	12/2/2020	CLEANED UP SPILL SITE
296	11/30/2020	14:12	N	N	50	554 FORTUNE RIDGE ROAD	STONE MTN	N/A	4	BRK LN/STR	FOUND 4(IN) BROKEN LATERAL SPILLING INTO UNNAMED TRIBUTARY INTO NORTH CROOKED CREEK DUE TO A STRUCTURAL DAMAGE.	NORTH CROOKED CREEK	UNNAMED	11/30/2020	15:00	REPAIRED THE 4(IN) LATERAL TO THE SPILL AND RESTORED NORMAL FLOW.	12/1/2020	12/3/2020	REPAIR WORK ORDER CREATED
297	12/2/2020	11:31	N	N	1,780	7073 KELLY STREET	LITHONIA	152-S016	8	GR	FOUND MANHOLE #16-152-S016 SPILLING INTO PINE MOUNTAIN CREEK DUE TO A GREASE BLOCKAGE.	PINE MOUNTAIN CREEK	N/A	12/2/2020	13:00	PRESSURE WASHED THE 8(IN) SEWER MAIN 370(FT) TO CLEAR THE GREASE BLOCKAGE AT 270(FT), WHICH RESTORED NORMAL FLOW.	12/3/2020	12/4/2020	CCTV AND FOG WORK ORDERS CREATED. CLEANED UP SPILL SITE COMPLETED.
298	12/4/2020	10:36	N	N	1,740	3447 PORTSMOUTH CIRCLE	LITHONIA	012-S061	8	GR	FOUND MANHOLE #16-012-S061 SPILLING INTO UNNAMED TRIBUTARY INTO PANTHERS BRANCH CREEK DUE TO A GREASE BLOCKAGE.	PANTHERS BRANCH CREEK	UNNAMED	12/4/2020	11:05	RODDED THE 8(IN) SEWER MAIN 100(FT) TO CLEAR THE GREASE BLOCKAGE AT 25(FT), WHICH RESTORED NORMAL FLOW.	12/4/2020	12/7/2020	CCTV AND FOG WORK ORDERS CREATED. CLEANED UP SPILL SITE COMPLETED.
299	12/5/2020	10:06	N	N	98	5005 LEESHIRE TRAIL	TUCKER	N/A	4	RT	FOUND 4(IN) PRIVATE CLEANOUT SPILLING INTO TRIBUTARY A INTO CAMP CREEK DUE TO ROOT BLOCKAGE ON ROW.	CAMP CREEK	А	12/5/2020	11:10	RODDED THE 4(IN) LATERAL 21(FT) TO CLEAR THE ROOT BLOCKAGE AT 19(FT), WHICH RESTORED NORMAL FLOW.	12/5/2020	12/8/2020	CCTV WORK ORDER COMPLETED.
300	12/5/2020	10:59	N	N	810	3765 BROWN DRIVE	DECATUR	N/A	4	UNK	FOUND 4(IN) CLEANOUT SPILLING INTO SOUTH RIVER DUE TO UNKNOWN BLOCKAGE.	SOUTH RIVER	UNNAMED	12/5/2020	12:20	PRESSURE WASHED THE 8(IN) SEWER MAIN 180(FT) TO CLEAR THE UNKNOWN BLOCKAGE AT 112(FT), WHICH RESTORED NORMAL FLOW.	12/5/2020	12/8/2020	CCTV WORK ORDER CREATED. CLEANED UP SPILL SITE COMPLETED.
301	12/7/2020	15:37	N	N	50	700 GEORGE LUTHER DRIVE	DECATUR	N/A	6	BRK LN/STR	FOUND EVIDENCE OF A SEWER SPILL FROM A PRIVATE ABANDONED 6(IN) CREEK CROSSING DUE TO A BYPASS PUMP MALFUNCTION DOWNSTREAM SETUP BY THE CONTRACTORS.	INDIAN CREEK	UNNAMED	12/7/2020	15:52	CONTRACTORS ADJUSTED THE BYPASS PUMPS.	12/7/2020	12/10/2020	CLEANED UP SPILL SITE COMPLETED.
302	12/11/2020	14:01	N	Y	13,090	3808 ASHFORD DUNWOODY ROAD	ATLANTA	N/A	10	BRK LN/STR	FOUND MANHOLE #18-327-S070 SURCHARGING AND ENTERING THE STORM DRAIN DUE TO A STRUCTURAL DAMAGE, GREASE AND DEBRIS.	NANCY CREEK	UNNAMED	12/11/2020	19:08	PRESSURE WASHED THE 10(IN) SEWER MAIN 120(FT) TO CLEAR THE UNKNOWN BLOCKAGE AT 40(FT), WHICH RESTORED NORMAL FLOW.	12/11/2020(12/15/202 0-REVISED)	12/16/2020	CCTV AND CLEANED UP WORK ORDERS COMPLETED.
303	12/13/2020	14:47	N	N	5,940	2801 CHANDLER ROAD	DECATUR	120-S048	8	GR	FOUND MANHOLE #15-120-S048 SPILLING INTO DOLES CREEK DUE TO A GREASE BLOCKAGE.	DOLES CREEK	N/A	12/13/2020	16:36	PRESSURE WASHED THE 8(IN) SEWER MAIN 98(FT) TO CLEAR THE GREASE BLOCKAGE AT 70(FT), WHICH RESTORED NORMAL FLOW.	12/16/2020	12/17/2020	CCTV AND FOG WORK ORDERS CREATED. CLEANED UP SPILL SITE COMPLETED.
304	12/17/2020	15:34	N	N	3,960	3731 BUFORD HWY	ATLANTA	203-P050	8	GR	FOUND MANHOLE #18-203-P050 SPILLING INTO NORTH FORK PEACHTREE CREEK DUE TO A GREASE BLOCKAGE.	NORTH FORK PEACHTREE CREEK	А	12/17/2020	16:40	PRESSURE WASHED THE 8(IN) SEWER MAIN 166(FT) TO CLEAR THE GREASE BLOCKAGE AT 125(FT), WHICH RESTORED NORMAL FLOW.	12/17/2020	12/21/2020	CCTV AND FOG WORK ORDERS CREATED. CLEANED UP SPILL SITE COMPLETED.
305	12/22/2020	10:49	N	N	8,100	3200 ATLANTA SILVERBACKS WAY	ATLANTA	N/A	8	BRK LN/STR	FOUND SEWER COMING UP IN NORTH FORK PEACHTREE CREEK DUE TO A POSSIBLE DEFECT IN THE SEWER MAIN.	NORTH FORK PEACHTREE CREEK	N/A	12/22/2020	12:10	PRESSURE WASHED THE 8(IN) SEWER MAIN 127(FT) TO CLEAR THE BLOCKAGE AT 108(FT), WHICH RESTORED NORMAL FLOW.	12/22/2020	12/24/2020	CCTV WORK ORDER CREATED. NO CLEAN UP NEEDED FOR THIS SITE.
306	12/31/2020	11:22	N	N	5,970	299 BELL STREET	DECATUR	N/A	12	BRK LN/STR	FOUND SEWER SPILLING INTO SOUTH FORK PEACHTREE DUE TO A POSSIBLE DEFECT IN THE SEWER MAIN.	SOUTH FORK PEACHTREE CREEK	N/A	12/31/2020	14:41	REPAIRED THE 12(IN) SEWER MAIN TO STOP THE SPILL AND RESTORED NORMAL FLOW.	12/31/2020	1/5/2021	CCTV AND REPAIR WORK ORDERS CREATED.

ACRONYMS

GRRT
GRDB
RTDB
GRRTDB
BRK LN/STR
STORM
OUTSIDE CON
MH
VAND
OTH Grease and Roots
Grease and Debris
Roots and Debris
Grease, Roots and Debris
Broken Main, Broken Line, Broken Structure Broken Main, Broken Line, Broken St Storm Event(s) Caused By Third Party/Contractor Manhole Issue/Damage Vandalism Other County Contractor
Homeowner improvement
Missing Check Valve HO
CV
UNK
CRK BRK
PMP FLR
LFT STN FLR
TREE
I and I (I&I) Unknown Creek crossing break Pump failure
Lift station failure
Tree Fell and Damaged System
Inflow and Infiltration
Not applicable

DeKalb County Department of Watershed Management Consent Decree SSO Tracking Sheet -- 4th Quarter Report 2020

Overflows

	Date/Time	9		Location			Cause/Source		Flow Rest	oration	Results
Overflow No.	Date Overflow Reported to DWM	Overflow Reported to DWM	Quantity in Gallons	Address of Overflow	City	Cause	Source/Additional Description	Restoration Date	Restoration Time	Flow Restoration Action	Additional Follow-up
54	10/6/2020	9:37	2	4000 HENDERSON PARK ROAD	TUCKER	GR	FOUND SEVERAL MANHOLES WITH EVIDENCE OF AN OVERFLOW AT MANHOLE 18-252-S004.	10/6/2020	10:53	PRESSURE WASHED THE 10(IN) SEWER MAIN 800(FT) TO REMOVE THE GREASE BLOCKAGE AT 540(FT) TO RESTORE NORMAL FLOW.	CCTV AND CLEAN-UP WORK ORDERS CREATED.
55	10/12/2020	15:59	4,800	1942 EAST STARMOUNT WAY	DECATUR	I&I	FOUND MANHOLE 15-172-S036, S045 AND A 4(IN) CLEANOUT WITH EVIDENCE OF AN OVERFLOW DUE TO RAIN WATER .	10/12/2020	16:20	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES; MAIN IS CLEAR AND FLOWING. PUT OUT DISINFECTANT AND CLEANUP DEBRIS.	CLEANED UP OVERFLOW SITE
56	10/14/2020	10:33	400	4280 NEWCOMB ROAD	ELLENWOOD	UNK	FOUND MANHOLE 15-031-S003 WITH EVIDENCE OF AN OVERFLOW.	10/14/2020	11:15	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES; MAIN IS CLEAR AND FLOWING. PUT OUT DISINFECTANT AND CLEANUP DEBRIS.	CLEANED UP OVERFLOW SITE
57	10/16/2020	9:31	45	221 NORTH CANDLER STREET	DECATUR	STR	FOUND SEWER ENTERING WATER METER VAULT AND COMING UP FROM THE GROUND WHEN FACILITIES WHERE USED AT THE BUILDING DUE TO AN UNKNOWN BLOCKAGE.	10/16/2020	10:00	VACUUM OUT SEWER FROM METER VAULT AND DITCH TO CONTAIN SEWER UNTIL FURTHER INVESTIGATION.	CLEANED UP OVERFLOW SITE
58	10/22/2020	16:24	17	1755 CECILIA DRIVE	ATLANTA	RT	FOUND EVIDENCE OF AN OVERFLOW AT THE 6(IN) ROW CLEANOUT DUE TO A ROOT BLOCKAGE.	10/22/2020	20:00	PRESSURE WASHED THE 6(IN) ROW CLEANOUT 16(FT) TO REMOVE THE ROOT BLOCKAGE, WHICH RESTORED NORMAL FLOW.	CLEANED UP OVERFLOW SITE
59	10/29/2020	9:35	25	2089 GARDEN CIRCLE	DECATUR	1&1	RAIN WATER ENTERED THE SEWER SYSTEM DURING RAIN EVENT, WHICH CAUSED THE 4(IN) CLEANOUT TO OVERFLOW ONTO THE SURFACE.	10/29/2020	9:40	REMOVED THE DEBRIS AND DISINFECTED THE AREA WITH DILUTED LEMONEX.	CLEANED UP OVERFLOW SITE
60	11/3/2020	17:03	5	2089 GARDEN CIRCLE	DECATUR	OC/U	FOUND EVIDENCE OF AN OVERFLOW AT THE 4(IN) PRIVATE CLEAN CAUSED BY THE OUTSIDE CONTRACTORS.	11/3/2020	17:30	CLEANED AND DISINFECTED AREA. TOOK PHOTOS	CLEANED UP OVERFLOW SITE
61	11/7/2020	10:48	50	3770 FOX GLEN COURT	ATLANTA	GR	FOUND MANHOLE 18-306-S203 AND 4(IN) ROW CLEANOUT WITH EVIDENCE OF AN OVERFLOW DUE TO A GREASE BLOCKAGE.	11/7/2020	11:40	PRESSURE WASHED THE 8(IN) SEWER MAIN 455(FT) TO REMOVE THE GREASE BLOCKAGE, WHICH RESTORED NORMAL FLOW.	CCTV AND CLEAN-UP WORK ORDERS CREATED.
62	11/9/2020	15:09	25	149 NORRIS STREET	DECATUR	UNK	FOUND MANHOLE 18-007-S021 WITH EVIDENCE OF AN OVERFLOW DUE TO A UNKNOWN BLOCKAGE.	11/9/2020	16:40	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES. REMOVED THE DEBRIS AND DISINFECTED THE AREA.	CCTV AND CLEAN-UP WORK ORDERS CREATED.
63	11/9/2020	15:14	20	1161 MCLENDON DRIVE	DECATUR	UNK	FOUND EVIDENCE OF AN OVERFLOW FROM PIPE BETWEEN 18-117-S087 AND 18-117-S088 DUE TO A UNKNOWN BLOCKAGE.	11/9/2020	16:00	CHECKED UPSTREAM AND DOWNSTREAM MANHOLES. REMOVED THE DEBRIS AND DISINFECTED THE AREA.	CCTV AND CLEAN-UP WORK ORDERS CREATED.
64	11/10/20	11:24	5	2089 GARDEN CIRCLE	DECATUR	OC/U	UTILITY CONTRACTOR (MME) CLEANING & PRESSURE WASHING AN 18 INCH SEWER MAIN CAUSING THE 4 INCH PRIVATE C/O TO OVERFLOW ONTO SURFACE	11/10/20	12:00	SPOKE WITH KENNETH ALSOBROOK - CONTRACTOR INSPECTOR GRAHAM & ASSOCIATES AND INFORMED THAT THE SEWER WAS ESCAPING THROUGH THE C/O SO THEY STOPPED PRESSURE WASHING MAIN.	CCTV AND CLEAN-UP WORK ORDERS CREATED.
65	11/23/20	13:19	10	1240 MCLYNN AVENUE	ATLANTA	UNK	FOUND MH 15-055-s090 WITH EVIDENCE OF AN OVERFLOW DUE TO UNKNOWN BLOCKAGE	11/23/20	13:30	UPON ARRIVAL THE MAIN WAS CLEAR AND FLOWING; CLEANED UP DEBRIS AND DISINFECTED AREA	CCTV AND CLEAN-UP WORK ORDERS CREATED.
66	11/24/20	11:21	960	4027 FLAKES MILL ROAD	DECATUR	GR	FOUND MH 15-037-s091 OVERFLOWING ONTO THE SURFACE DUE TO GREASE BLOCKAGE	11/24/20	11:45	PRESSURE WASHED THE 8 IN MAIN FROM MH 15-037-s091 120 FT TOWARDS MH 15-0370s092 AND CLEARED THE BLOCKAGE AT 100 FT WHICH RESTORED FLOW.	CCTV AND CLEAN-UP WORK ORDERS CREATED.
67	11/27/20	14:52	20	213 HIBERNIA AVENUE	DECATUR	UNK	FOUND MH 15-236-s034 SURCHARGING CAUSING SS TO OVERFLOW ONTO THE SURFACE DUE TO UNKNOWN BLOCKAGE	11/27/20	16:30	PRESSURE WASHED 8 IN MAIN FROM MH 15-2360s034 100 FT REMOVING UNKNOWN BLOCKAGE AT 70 FT WHICH RESTORED FLOW	CCTV AND CLEAN-UP WORK ORDERS CREATED.
68	12/5/20	10:54	600	5211 PEACHTREE INDUSTRIAL BLVD	CHAMBLEE	DB	FOUND MH TWO UNMAPPED MH'S OVERFLOWING CAUSED BY DEBRIS BLOCKAGE	12/5/20	0:30	TURNED OVER TO EMERGENCY RESPONSE CONTRACTORS. EMERGENCY CONTRACTORS SET UP BYPASS TO STOP THE MH'S FROM OVERFLOWING.	CCTV AND CLEAN-UP WORK ORDERS CREATED.
69	12/19/20	14:00	250	2102 YOUNG ROAD	LITHONIA	UNK	FOUND MH 16-037-s032 SURCHARGING DUE TO AN UNKNOWN BLOCKAGE CAUSING A PRIVATE 4 IN C/O TO OVERFLOW ONTO THE SURFACE.	12/19/20	15:45	PRESSURE WASHED 8(IN) SEWER MAIN FROM MANHOLE 16-037- s780 TO 16-0370s032 380(FT) REMOVING UNKNOWN BLOCKAGE AT 340(FT) TO RESTORE NORMAL FLOW.	CCTV AND CLEAN-UP WORK ORDERS CREATED.
70	12/31/20	14:43	25	1659 BRIARCLIFF ROAD	ATLANTA	CRK BRK	FOUND EVIDENCE OF AN OVERFLOW FROM A HOLE ON TOP OF THE CREEK CROSSING CASING	12/31/20	15:15	TOOK PICTURES AND DOCUMENTED FINDINGS.	CLEANED UP OVERFLOW SITE

				DeKalb County [Department	t of Wa	ntershed Management Consent Decree SSO Track	ing Sheet -	- 4th Q	uarter Report 2020
							Building Back-ups			
	Date/Ti	me Time		Location			Cause/Source			Flow Restoration
Building Back-up No.	Date Building Back-up Reported to DWM	Building Back-up Report to DWM	Quantity in Gallons (est.)	Address of Building Back-up	City	Cause	Source/Additional Description	Restoration Date	Restorati on Time	Flow Restoration Action
44	10/7/2020	18:30	50	4756 HAMMERMILL ROAD	TUCKER	ОТН	FOUND EVIDENCE OF A BUILDING BACKUP CAUSED BY A MALFUNCTION WITH THE LIFT STATION.	10/7/2020	19:30	LIFT STATION CREW CORRECTED THE ISSUE AND CALLED CONTRACTORS TO CLEAN THE UP SEWER UP.
45	10/9/2020	10:45	5	3486 HIDDEN ACRES DRIVE	DORAVILLE	RT	FOUND MANHOLE 18-292-S058 SURCHARGING DUE TO A ROOT BLOCKAGE CAUSING SEWER TO BACKUP INTO THE HOME.	10/9/2020	44.45	PRESSURE WASHED 8(IN) SEWER MAIN 1 SECTION UPSTREAM FROM MANHOLE 18-292-S021 200(FT) REMOVING ROOT BLOCKAGE AT TO RESTORE.
46	10/10/2020	22:05	30	1422 COBB BRANCH DRIVE	DECATUR		RAIN WATER ENTERED THE SEWER SYSTEM DURING A HEAVY RAIN EVENT CAUSING MANHOLE 15-197-S008 TO SPILL AND SEWER TO BACKUP INTO THE HOME.	10/11/202	0:25	UPON ARRIVAL THE SEWER HAD SUBSIDED FROM ENTERING HOME, TOOK PICTURES OF THE INSIDE OF THE HOME AND REQUEST FOR SERV PRO.
47	10/10/2020	22:48	30	3273 PINEHILL DRIVE	DECATUR	I&I	RAIN WATER ENTERED THE SEWER SYSTEM DURING A HEAVY RAIN EVENT CAUSING MANHOLE 15-199-S024 TO SPILL AND SEWER TO BACKUP INTO THE HOME.	10/10/2020	21:55	UPON ARRIVAL THE SEWER HAD SUBSIDED FROM ENTERING HOME, TOOK PICTURES OF THE INSIDE OF THE HOME AND REQUEST FOR SERV PRO.
48	10/10/2020	23:45	25	3478 PRIMROSE PLACE	DECATUR	I&I	RAIN WATER ENTERED THE SEWER SYSTEM DURING A HEAVY RAIN EVENT CAUSING MANHOLE 15-187-S041 TO SURCHARGE AND SEWER TO BACKUP INTO THE HOME.	10/11/2020	0:25	UPON ARRIVAL THE SEWER HAD SUBSIDED FROM ENTERING HOME, TOOK PICTURES OF THE INSIDE OF THE HOME AND REQUEST FOR SERV PRO.
49	10/11/2020	23:59	25	2183 ROSEWOOD ROAD	DECATUR	I&I	RAIN WATER ENTERED THE SEWER SYSTEM DURING A HEAVY RAIN EVENT CAUSING SEWER TO BACKUP INTO THE HOME.	10/11/2020	0:45	UPON ARRIVAL THE SEWER HAD SUBSIDED FROM ENTERING HOME, TOOK PICTURES OF THE INSIDE OF THE HOME AND REQUEST FOR SERV PRO.
50	10/13/2020	10:42	500	3255 PINEHILL DRIVE	DECATUR	I&I	RAIN WATER ENTERED THE SEWER SYSTEM DURING A HEAVY RAIN EVENT CAUSING SEWER TO BACKUP INTO THE HOME.	10/13/2020	18:00	TOOK PICTURES AND MADE A SERVICE REQUEST FOR A SEWER CLEANUP TO HAVE SERV PRO COME OUT.
51	10/13/2020	22:04	25	1883 LAVISTA ROAD	ATLANTA	RT	FOUND 6(IN) ROW CLEANOUT SURCHARGING CAUSED BY A ROOT BLOCKAGE.	10/13/2020	23:00	RODDED THE 6(IN) ROW CLEANOUT 30(FT) TO REMOVE THE ROOT BLOCKAGE AT 10(FT) TO RESTORE NORMAL FLOW.
52	5/2020(10/10/2	8:36	400	3267 PINEHILL DRIVE	DECATUR	I&I	RAIN WATER ENTERED THE SEWER SYSTEM DURING A HEAVY RAIN EVENT CAUSING SEWER TO BACKUP INTO THE HOME.	10/10/2020	9:15	TOOK PICTURES AND MADE A SERVICE REQUEST FOR A SEWER CLEANUP TO HAVE SERV PRO COME OUT.
53	10/26/2020	19:55	5	1501 DIAMOND HEAD DRIVE	DECATUR	UNK	FOUND SEWER IN THE DOWNSTAIRS BATHROOM DUE TO AN UNKNOWN BLOCKAGE.	10/26/2020	20:30	RODDED THE 4(IN) ROW CLEANOUT 30(FT) TO REMOVE THE UNKNOWN BLOCKAGE AT 10(FT) TO RESTORE NORMAL FLOW.
54	10/26/2020	22:17	25	2805 BATTLE FORREST DRIVE	DECATUR	GR	FOUND SEWER IN THE BASEMENT DUE TO AN UNKNOWN BLOCKAGE.	10/27/2020	0:26	PRESSURE WASHED 8(IN) SEWER MAIN 530(FT) TO REMOVE GREASE BLOCKAGE AT 520(FT) TO RESTORE NORMAL FLOW.
55	11/1/2020	20:21	40	2860 NORGATE COURT	DECATUR	UNK	FOUND SEWER IN THE DOWNSTAIRS BATHROOM DUE TO AN UNKNOWN BLOCKAGE.	11/1/2020	20:40	RODDED THE 6(IN) ROW CLEANOUT 30(FT) TO REMOVE THE UNKNOWN BLOCKAGE AT 15(FT) TO RESTORE NORMAL FLOW.

				DeKalb County [Departmen	t of Wa	ntershed Management Consent Decree SSO Track	ing Sheet -	- 4th Q	uarter Report 2020
							Building Back-ups			
	Date/Ti			Location			Cause/Source			Flow Restoration
Building Back-up No.	Date Building Back-up Reported to DWM	Building Back-up Report to DWM	Quantity in Gallons (est.)	Address of Building Back-up	City	Cause	Source/Additional Description		Restorati on Time	Flow Restoration Action
56	11/7/2020	10:48	10	3770 FOX GLEN COURT	ATLANTA	GR	FOUND MANHOLE 18-306-S203 OVERFLOWING DUE TO A GREASE BLOCKAGE CAUSING SEWER TO BACKUP INTO THE HOME.	11/7/2020	11:40	PRESSURE WASHED 8(IN) SEWER MAIN 455(FT) TO REMOVE GREASE BLOCKAGE AT 350(FT) TO RESTORE NORMAL FLOW.
57	11/22/2020	13:40	5	1781 GARDENSIDE COURT	ATLANTA	TSIDE C	UNITED RESOURCE (DEKALB COUNTY CONTRACTORS) WERE PERFORMING SEWER LINE CLEANING ON AN 8 IN SEWER MAIN PRESSURE WASHING THE LINE CAUSING SEWER TO BACK UP INTO HOME.	11/22/2020	14:30	UPON ARRIVAL THE CONTRACTOR HAD CEASED PRESSURE WASHING WHICH STOPPED SEWER FROM ENTERING THE HOME. SPOKE WITH CUSTOMER AND CONTRACTORS ABOUT RESOLVING THE ISSUE.
58	12/2/2020	14:51	150	4017 ENGLISH OAK DRIVE	DORAVILLE	DB	FOUND SEWER BACKING UP INTO RESIDENCE FROM 10 IN SEWER MAIN CAUSED BY DEBRIS BLOCKAGE (RAGS)	12/2/2020	16:23	PRESSURE WASHED SS MAIN AND REMOVED DEBRIS BLOCKAGE TO RESTORE FLOW.
59	12/19/2020	15:45	20	2070 YOUNG ROAD	LITHONIA	UNK	PRESSURE WASHED 8 IN SEWER MAIN TO REMOVE UNKNOWN BLOCKAGE, AFTER FLOW WAS RESTORED THE VOLUME OF WATER USED TO REMOVE BLOCKAGE CAUSED SEWER TO BACK INTO THE RESIDENCE.	12/19/2020	15:50	WATER RECEDED STOPPING THE SEWER FROM ENTERING THE RESIDENCE. SPOKE WITH CUSTOMER ABOUT ISSUE AND REQUESTED CLEANING SERVICES.
60	12/22/2020	15:55	20	1315 KITTREDGE COURT	ATLANTA	UNK	FOUND 6 IN ROW C/O SURCHARGING CAUSING A BACKUP INTO THE BASEMENT BATHROOM OF THE RESIDENCE	12/22/2020	16:30	RODDED 6 IN ROW C/O 30 FT CLEARING BLOCKAGE AT 18 FT TO RESTORE FLOW.
61	12/23/2020	8:00	15	1477 HOLLY LANE	ATLANTA	RT	FOUND EVIDENCE OF AN OVERFLOW FROM 4 IN ROW C/O CAUSING SEWAGE TO BACK UP INTO RESIDENCE	12/23/2020	9:00	OBTAINED REPAIR CREW TO UNCOVER AND REPAIR LATERAL TO RESTORE FLOW
62	12/27/2020	11:32	20	5439 EFFINGHAM COURT	LITHONIA	RT	FOUND 6(IN) ROW CLEANOUT SURCHARGING DUE TO A ROOT BLOCKAGE.	12/27/2020	12:40	RODDED 6 IN C/O 27 FT REMOVING ROOT BLOCKAGE AT 10 FT TO RESTORE SERVICE TO LATERAL

DeKalb County Department of Watershed Management -- 4th Quarter Report 2020

Lateral Related Issues*

	Date/Tir	me	Location			Cause/Source			Flow Restoration
Lateral Issue No.	Date Reported to DWM	Time Reported to DWM	Address	Is the WCTS main flowing without blockage?	Is there a blockage in the lower lateral?	Source/Additional Description	Restoration Date	Restoration Time	Flow Restoration Actions
471	10/1/2020	06:00	932 ABINGDON COURT, STONE MOUNTAIN	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	10/1/2020	07:15	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
472	10/1/2020	10:46	GREY FOX CHASE , LITHONIA	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	10/1/2020	11:00	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
473	10/2/2020	06:00	1955 SHANNON RIDGE COURT, DECATUR	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	10/2/2020	06:30	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
474	10/2/2020	06:05	2090 WESTOVER PLANTATION, DUNWOODY	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	10/2/2020	06:50	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
475	10/3/2020	10:00	2411 CRANBROOKE DRIVE, DECATUR	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	10/3/2020	11:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
476	10/5/2020	06:00	2813 CHRISTOPHER COURT, DORAVILLE	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	10/5/2020	06:15	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
477	10/6/2020	07:00	3862 CREEKBANK COVE, DECATUR	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	10/6/2020	07:30	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
478	10/7/2020	05:20	1646 RAINIER FALLS DRIVE, ATLANTA	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	10/7/2020	05:35	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
479	10/7/2020	07:30	4756 HAMMERMILL ROAD, TUCKER	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	10/7/2020	08:00	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
480	10/9/2020	02:45	1630 BEACON HILL BOULEVARD, ATLANTA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	10/9/2020	03:45	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
481	10/10/2020	12:30	2150 TRAILWOOD ROAD, DECATUR	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	10/10/2020	01:30	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
482	10/13/2020	10:30	1883 LAVISTA ROAD, ATLANTA	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	10/13/2020	11:00	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
483	10/14/2020	02:45	2254 IDLEWOOD ROAD, TUCKER	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	10/14/2020	03:15	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
484	10/15/2020	01:00	847 MCLENDON DRIVE, SCOTTDALE	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	10/15/2020	02:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
485	10/17/2020	01:30	3672 DIAL DRIVE, STONE MOUNTAIN	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	10/17/2020	01:45	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW

	Date/Tir	me	Location			Cause/Source			Flow Restoration
Lateral Issue No.	Date Reported to DWM	Time Reported to	Address	Is the WCTS main flowing without blockage?	Is there a blockage in the lower lateral?	Source/Additional Description	Restoration Date	Restoration Time	Flow Restoration Actions
	·			3		·			
486	10/19/2020	02:00	4334 AUTUMN HILL DRIVE, STONE MOUNTAIN	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	10/19/2020	03:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
487	10/21/2020	08:20	2406 GLENROCK DRIVE, DECATUR	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	10/21/2020	08:35	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
488	10/22/2020	07:20	1755 CECILIA DRIVE, ATLANTA	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	10/22/2020	08:00	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
489	10/24/2020	10:15	1807 SAMARIA TRAIL, TUCKER	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	10/24/2020	10:45	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
490	10/26/2020	02:00	456 BURLINGTON ROAD, ATLANTA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	10/26/2020	02:15	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
491	10/26/2020	08:15	1501 DIAMOND HEAD DRIVE, DECATUR	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	10/26/2020	08:30	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
492	10/28/2020	03:00	3268 BUFORD HIGHWAY, ATLANTA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	10/28/2020	06:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
493	10/29/2020	03:50	3854 WEST NANCY CREEK PLACE, ATLANTA	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	10/29/2020	04:20	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
494	10/30/2020	05:35	4766 WHITE OAK PATH, STONE MOUNTAIN	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	10/30/2020	05:55	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
495	10/31/2020	07:10	5892 POPLIN COURT, LITHONIA	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	10/31/2020	07:25	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
496	11/1/2020	12:00	2264 OAKAWANA ROAD, ATLANTA	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	11/1/2020	12:30	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
497	11/1/2020	08:25	2860 NORGATE COURT, DECATUR	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	11/1/2020	08:40	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
498	11/2/2020	10:35	1744 WEST NANCY CREEK DRIVE, ATLANTA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/2/2020	10:50	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
499	11/2/2020	05:00	48 BERKELEY ROAD, AVONDALE ESTATES	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/2/2020	06:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
500	11/3/2020	09:30	4714 FELLSRIDGE DRIVE, STONE MOUNTAIN	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/3/2020	10:30	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW

	Date/Ti	me	Location			Cause/Source			Flow Restoration
Lateral	Date Reported to DWM	Time Reported to DWM	Address	Is the WCTS main flowing without blockage?	Is there a blockage in the lower lateral?	Source/Additional Description	Restoration Date	Restoration Time	Flow Restoration Actions
501	11/3/2020	03:50	2744 RAINBOW FOREST DRIVE, DECATUR	No	Yes	THERE WAS AN ISSUE IN BOTH THE WCTS AND THE LATERAL	11/3/2020	05:00	BLOCKAGES REMOVED FROM WCTS AND LATERAL TO RESTORE FLOW
502	11/4/2020	10:35	1755 CECILIA DRIVE, ATLANTA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/4/2020	11:35	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
503	11/4/2020	12:00	4599 ROCKBRIDGE ROAD, STONE MOUNTAIN	No	Yes	THERE WAS AN ISSUE IN BOTH THE WCTS AND THE LATERAL	11/4/2020	12:30	BLOCKAGES REMOVED FROM WCTS AND LATERAL TO RESTORE FLOW
504	11/7/2020	10:45	2224 2ND AVENUE, DECATUR	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	11/7/2020	10:55	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
505	11/7/2020	01:10	152 CANDLER DR, DECATUR	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	11/7/2020	01:35	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
506	11/7/2020	02:35	723 DENSLEY DRIVE, DECATUR	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/7/2020	03:35	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
507	11/8/2020	02:30	3241 ALTON ROAD, CHAMBLEE	No	Yes	THERE WAS AN ISSUE IN BOTH THE WCTS AND THE LATERAL	11/8/2020	03:00	BLOCKAGES REMOVED FROM WCTS AND LATERAL TO RESTORE FLOW
508	11/8/2020	03:30	3730 MARLBOROUGH DRIVE, TUCKER	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	11/8/2020	04:00	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
509	11/9/2020	02:00	2555 BRUCE STREET, LITHONIA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/9/2020	03:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
510	11/9/2020	01:00	4121 LAVISTA ROAD, TUCKER	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/9/2020	02:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
511	11/9/2020	03:30	1161 MCLENDON DRIVE, DECATUR	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	11/9/2020	04:00	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
512	11/9/2020	07:00	6427 CASTLE DOWNS TRACE, LITHONIA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/9/2020	08:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
513	11/14/2020	12:00	1823 RAVENWOOD WAY, ATLANTA	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	11/14/2020	12:10	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
514	11/14/2020	04:45	3305 LAVISTA ROAD, DECATUR	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/14/2020	05:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
515	11/15/2020	12:30	5281 BRIDGEWATER TRACE, STONE MOUNTAIN	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	11/15/2020	12:50	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED

	Date/Tir	me	Location			Lateral Related Issues" Cause/Source			Flow Restoration
	Date/ III	TIC .	Eocation	Is the WCTS		vause/ source			1 low Restoration
Lateral	Data Danastad ta DIMA	Time Reported to	Address	main flowing without	Is there a blockage in the	Course / Additional Description	Destauation Data	Destaustion Times	Flour Dephasetion Astions
Issue No.	Date Reported to DWM	DWM	Address	blockage?	lower lateral?	Source/Additional Description	Restoration Date	Restoration Time	Flow Restoration Actions
516	11/15/2020	03:50	2019 CHESTNUT HILL CIRCLE, DECATUR	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/15/2020	04:40	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
517	11/16/2020	01:30	2869 RAMBLING WAY, LITHONIA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/16/2020	03:30	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
518	11/18/2020	12:00	1815 WESTMINSTER WAY, ATLANTA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/18/2020	01:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
519	11/20/2020	02:30	3367 MISTY VALLEY ROAD, DECATUR	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/20/2020	03:30	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
520	11/21/2020	04:30	874 SHEPPARD WAY, STONE MOUNTAIN	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	11/21/2020	04:45	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
521	11/24/2020	10:00	3510 RAYMOND DRIVE, DORAVILLE	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/24/2020	10:20	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
522	11/24/2020	12:10	3632 RAYMOND DRIVE, DORAVILLE	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/24/2020	12:30	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
523	11/25/2020	12:30	4427 COLONY EAST DRIVE, STONE MOUNTAIN	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/25/2020	02:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
524	11/25/2020	07:30	6039 HILLANDALE DRIVE, LITHONIA	No	Yes	THERE WAS AN ISSUE IN BOTH THE WCTS AND THE LATERAL	11/25/2020	10:00	BLOCKAGES REMOVED FROM WCTS AND LATERAL TO RESTORE FLOW
525	11/25/2020	07:30	2157 BROCKETT ROAD, TUCKER	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/25/2020	10:30	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
526	11/25/2020	10:30	2981 UMBERLAND DRIVE, DORAVILLE	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/25/2020	11:30	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
527	11/25/2020	10:30	1504 KNIGHTS TRAIL, STONE MOUNTAIN	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/25/2020	12:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
528	11/26/2020	01:30	2627 VARNER DRIVE, ATLANTA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/26/2020	02:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
529	11/27/2020	10:00	2990 JUDYLYN DRIVE, DECATUR	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/27/2020	11:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
530	11/27/2020	11:00	5141 HIDDEN HILLS TRACE, STONE MOUNTAIN	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/27/2020	12:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW

DeKalb County Department of Watershed Management -- 4th Quarter Report 2020

					Lateral Related Issues*				
	Date/Tir	me	Location			Cause/Source			Flow Restoration
Lateral Issue No	. Date Reported to DWM	Time Reported to DWM	Address	Is the WCTS main flowing without blockage?	Is there a blockage in the lower lateral?	Source/Additional Description	Restoration Date	Restoration Time	Flow Restoration Actions
531	11/28/2020	04:30	2157 BROCKETT ROAD, TUCKER	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	11/28/2020	04:40	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
532	11/30/2020	11:50	2442 LAVISTA ROAD, ATLANTA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	11/30/2020	12:05	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
533	11/30/2020	03:00	554 FORTUNE RIDGE ROAD, STONE MOUNTAIN	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	11/30/2020	03:20	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
534	12/1/2020	01:30	4958 LAVISTA ROAD, TUCKER	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/1/2020	02:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
535	12/1/2020	07:45	3576 RAYMOND DRIVE, DORAVILLE	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/1/2020	09:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
536	12/3/2020	10:30	1158 ROGERETTA DRIVE, ATLANTA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/3/2020	11:30	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
537	12/3/2020	11:30	48 BERKELEY ROAD, AVONDALE ESTATES	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/3/2020	12:30	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
538	12/3/2020	12:20	3510 RAYMOND DRIVE, DORAVILLE	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/3/2020	12:45	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
539	12/3/2020	01:00	442 SHERWOOD GREENS, STONE MOUNTAIN	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/3/2020	01:30	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
540	12/4/2020	09:40	1712 ALDERBROOK ROAD, ATLANTA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/4/2020	12:40	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
541	12/4/2020	05:30	2599 CRAVEY DRIVE, ATLANTA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/4/2020	07:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
542	12/5/2020	9:14	415 DIAL WAY, STONE MOUNTAIN	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/5/2020	9:30	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
543	12/5/2020	10:45	5005 LEESHIRE TRAIL, TUCKER	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/5/2020	11:15	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
544	12/6/2020	11:20	748 STRATFORD GREEN, AVONDALE ESTATES	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/6/2020	12:30	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
545	12/6/2020	05:25	127 GREENWOOD PLACE, DECATUR	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/6/2020	05:55	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED

	Date/Time		Location		Cause/Source		Flow Restoration		
Lateral Issue No.	Date Reported to DWM	Time Reported to DWM	Address	Is the WCTS main flowing without blockage?	Is there a blockage in the lower lateral?	Source/Additional Description	Restoration Date	Restoration Time	Flow Restoration Actions
546	12/7/2020	05:45	4377 HICKORY WOOD LANE, DORAVILLE	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/7/2020	06:45	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
547	12/8/2020	10:05	890 PINE ROC DRIVE, STONE MOUNTAIN	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/8/2020	10:35	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
548	12/9/2020	12:00	4377 HICKORY WOOD LANE, DORAVILLE	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/9/2020	01:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
549	12/9/2020	03:30	1477 HOLLY LANE, DECATUR	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/9/2020	04:30	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
550	12/11/2020	07:00	2034 CHERRYBROOK DRIVE, ATLANTA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/11/2020	08:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
551	12/11/2020	05:15	3228 CALDWELL ROAD, AVONDALE ESTATES	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/11/2020	06:25	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
552	12/11/2020	08:20	3285 KENSINGTON ROAD, STONE MOUNTAIN	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/11/2020	09:10	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
553	12/12/2020	07:30	7420 WOODRUFF WAY, DECATUR	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/12/2020	09:30	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
554	12/13/2020	11:50	140 SUPERIOR AVENUE, STONE MOUNTAIN	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/13/2020	01:05	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
555	12/13/2020	01:05	5759 MANASSAS RUN, STONE MOUNTAIN	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/13/2020	02:40	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
556	12/13/2020	06:25	4657 GARDEN HILLS DRIVE, DECATUR	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/13/2020	06:55	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
557	12/14/2020	09:20	2651 RIVER OAK DRIVE, DECATUR	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/14/2020	09:50	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
558	12/14/2020	02:15	2813 SANTA BARBARA DRIVE, DECATUR	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/14/2020	03:15	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED
559	12/14/2020	03:30	2034 CHERRYBROOK DRIVE, ATLANTA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/14/2020	04:15	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW
560	12/14/2020	03:00	1441 SOUTHLAND VISTA COURT, LITHONIA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/14/2020	04:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW

	Date/Time Location				Lateral Related Issues" Cause/Source			Flow Restoration		
	Date/ III	lle lle	Location	Is the WCTS		Cause/ Source			Flow Restoration	
Lateral Issue No.	Date Reported to DWM	Time Reported to DWM	Address	main flowing without blockage?	Is there a blockage in the lower lateral?	Source/Additional Description	Restoration Date	Restoration Time	Flow Restoration Actions	
561	12/14/2020	06:25	5439 EFFINGHAM COURT, ELLENWOOD	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/14/2020	07:05	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW	
562	12/14/2020	10:20	4160 MOORE ROAD, STONE MOUNTAIN	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/14/2020	10:35	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED	
563	12/15/2020	03:00	6134 POMERANIA TRAIL, DECATUR	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/15/2020	03:30	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED	
564	12/16/2020	11:30	2463 HUNTING VALLEY DRIVE, LITHONIA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/16/2020	12:30	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW	
565	12/16/2020	12:30	3006 HIGHLAND PARK LANE, DECATUR	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/16/2020	01:30	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW	
566	12/16/20	16:59	415 DIAL WAY, STONE MOUNTAIN	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/16/20	17:25	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED	
567	12/17/2020	03:30	497 EASTLAND DRIVE, ATLANTA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/17/2020	05:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW	
568	12/17/2020	04:10	3731 BUFORD HIGHWAY, STONE MOUNTAIN	No	Yes	THERE WAS AN ISSUE IN BOTH THE WCTS AND THE LATERAL	12/17/2020	04:30	BLOCKAGES REMOVED FROM WCTS AND LATERAL TO RESTORE FLOW	
569	12/17/2020	05:00	415 DIAL WAY, ATLANTA	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/17/2020	05:30	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED	
570	12/17/2020	10:15	1158 HOUSTON MILL ROAD, DECATUR	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/17/2020	11:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW	
571	12/18/2020	01:50	2651 RIVER OAK DRIVE, TUCKER	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/18/2020	03:20	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW	
572	12/21/2020	08:20	2157 BROCKETT ROAD, DECATUR	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/21/2020	09:50	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW	
573	12/21/2020	01:00	127 GREENWOOD PLACE, DECATUR	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/21/2020	02:00	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED	
574	12/22/2020	11:00	982 FORREST BOULEVARD, ATLANTA	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/22/2020	11:30	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED	
575	12/22/2020	11:15	3200 ATLANTA SILVERBACKS WAY, ATLANTA	No	Yes	THERE WAS AN ISSUE IN BOTH THE WCTS AND THE LATERAL	12/22/2020	11:30	BLOCKAGES REMOVED FROM WCTS AND LATERAL TO RESTORE FLOW	

	Date/Time Location				Cauca/Source			Flow Postaration		
	Date/ Time		Location Is the WCTS		Cause/Source		Flow Restoration			
Lateral Issue No.	Date Reported to DWM	Time Reported to DWM	Address	main flowing without blockage?	Is there a blockage in the lower lateral?	Source/Additional Description	Restoration Date	Restoration Time	Flow Restoration Actions	
576	12/22/2020	04:00	1315 KITTREDGE COURT, TUCKER	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/22/2020	04:30	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED	
577	12/22/2020	04:20	2254 IDLEWOOD ROAD, CHAMBLEE	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/22/2020	04:23	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED	
578	12/22/2020	06:20	1920 DYER CIRCLE, DUNWOODY	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/22/2020	07:35	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW	
579	12/22/2020	07:35	1689 MANHASSET PLACE, ATLANTA	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/22/2020	07:50	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED	
580	12/23/2020	07:30	1477 HOLLY LANE, DORAVILLE	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/23/2020	09:00	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED	
581	12/23/2020	10:00	2972 UMBERLAND DRIVE, DUNWOODY	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/23/2020	10:20	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED	
582	12/23/2020	03:00	1742 DUNRIDGE COURT, DECATUR	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/23/2020	03:30	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED	
583	12/23/2020	03:00	128 5TH AVENUE, DECATUR	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/23/2020	04:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW	
584	12/23/2020	07:00	401 SOUTH COLUMBIA DRIVE, LITHONIA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/23/2020	08:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW	
585	12/24/2020	04:00	1824 GINGHAM COURT, LITHONIA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/24/2020	04:45	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW	
586	12/27/2020	11:40	5439 EFFINGHAM COURT, ATLANTA	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/27/2020	12:40	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED	
587	12/28/2020	11:00	2647 WINDING LANE, DECATUR	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/28/2020	11:25	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED	
588	12/28/2020	11:00	2399 CRANBROOKE DRIVE, ATLANTA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/28/2020	12:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW	
589	12/29/2020	02:00	1362 CARTECAY DRIVE, STONE MOUNTAIN	No	Yes	THERE WAS AN ISSUE IN BOTH THE WCTS AND THE LATERAL	12/29/2020	04:30	BLOCKAGES REMOVED FROM WCTS AND LATERAL TO RESTORE FLOW	
590	12/29/2020	03:30	4311 ROCKING CHAIR LANE, DECATUR	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/29/2020	04:00	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED	

DeKalb County Department of Watershed Management 4th Quarter Report 2020										
Lateral Related Issues*										
	Date/Time Location					Cause/Source	Flow Restoration			
Lateral Issue No	Date Reported to DWM	Time Reported to DWM	Address	Is the WCTS main flowing without blockage?	Is there a blockage in the lower lateral?	Source/Additional Description	Restoration Date	Restoration Time	Flow Restoration Actions	
591	12/30/2020	12:30	3748 STANFORD CIRCLE, DECATUR	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/30/2020	01:15	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW	
592	12/30/2020	03:00	925 SYCAMORE DRIVE, DECATUR	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/30/2020	04:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW	
593	12/31/2020	09:00	3742 STANFORD CIRCLE, ATLANTA	Yes	Yes	OVERFLOW CAUSED BY LOWER LATERAL MAINTENANCE RELATED BLOCKAGE	12/31/2020	09:30	FLOW RESTORED TO LATERAL AND OVERFLOW AREA CLEANED	
594	12/31/2020	12:00	1842 NORTH AKIN DRIVE, ATLANTA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/31/2020	01:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW	
595	12/31/2020	02:00	3187 SAYBROOK DRIVE, ATLANTA	Yes	Yes	MAINTENANCE RELATED BLOCKAGE IN PRIVATE LATERAL	12/31/2020	03:00	BLOCKAGE REMOVED FROM PRIVATE LATERAL TO RESTORE FLOW	

^{*}The County was asked at our meeting of April 14, 2016 to begin tracking SSO's that appear to be caused by blockages or other issues located in that section of a private service lateral that is in the County's right-of-way. This report reflects the County's best efforts to track this information.