

404.371.2155 (o) 404.371.4556 (f) DeKalbCountyGa.gov Clark Harrison Building 330 W. Ponce de Leon Ave Decatur, GA 30030

Chief Executive Officer

DEPARTMENT OF PLANNING & SUSTAINABILITY

Application for Certificate of Appropriateness

Application No.:

Director

Michael Thurmond

Date Received: ___

Andrew A. Baker, AICP

Address of Subject Property: 11/6 Lullwater Road A	tlanta, GA 30307
Applicant: Dave Price - Price Residential Design	E-Mail: dave@priceresidentialdesign.com
Applicant Mailing Address: 1595 Nottingham Way A	tlanta, Georgia 30309
Applicant Phone(s): 404-245-4244	Fax: 404-245-4244
Applicant's relationship to the owner: Owner □ Architect: □ Contract	
Owner(s): David Martin	
Clizabath Cianarty Martin	E-Mail:
Owner(s) Telephone Number:	
Approximate age or date of construction of the primary structure on the project:vacant lot	e property and any secondary structures affected by this
Nature of work (check all that apply):	
New construction ☐ Demolition ☐ Addition ☐ Moving a built New accessory building ☐ Landscaping ☐ Fence/Wall ☐ Gign installation or replacement ☐ Other ☐	ding □ Other building changes □ Other environmental changes □
Description of Work:	Salaman arran Larra and Standard Larra and an
Build new two-story brick Colonial Revival res	
previously vacant lot with front terrace, side po	
driveway to 12' wide front-facing garage door provided with minimal grading / tree loss. A s	
front yard turnaround will be required, due to	
	<u> </u>

This form must be completed in its entirety and be accompanied by supporting documents, such as plans, list of materials, color samples, photographs, etc. All documents should be in PDF format, except for photographs, which may be in JPEG format. Email the application and supporting material to plansustain@dekalbcountyga.gov An incomplete application will not be accepted.

Signature of Applicant/Date

Revised 10/5/2020

404.371.2155 (o) 404.371.4556 (f) DeKalbCountyGa.gov Clark Harrison Building 330 W. Ponce de Leon Ave Decatur, GA 30030

DEPARTMENT OF PLANNING & SUSTAINABILITY

Authorization of a Second Party to Apply for a Certificate of Appropriateness

This form is required if the individual making the request is **not** the owner of the property.

being owner(s) of the property at 1176 Lullwater Road Atlanta, GA 30307

hereby delegate authority to Dave Price - Price Residential Design

to file an application for a certificate of appropriateness in my/our behalf.

Docusigned by:

David Martin

AF6ADF3457684B0...

Docusigned by:

Hirabelle Financty Martin

E1FEDDF46A854EE...

Signature of Owner(s)

6/22/2021 | 12:07 P


Please review the following information

Approval of this Certificate of Appropriateness does not release the recipient from compliance with all other pertinent county, state, and federal regulations.

Before making any changes to your approved plans, contact the preservation planner (404/371- 2155). Some changes may fall within the scope of the existing approval, but others will require review by the preservation commission. If work is performed which is not in accordance with your certificate, a Stop Work Order may be issued.

If your project requires that the county issue a Certificate of Occupancy at the end of construction, an inspection may be made to verify that the work has been completed in accord with the Certificate of Appropriateness. If the work as completed is not the same as that approved in the Certificate of Appropriateness you will not receive a Certificate of Occupancy. You may also be subject to other penalties including fines and/or required demolition of the non-conforming work.

If you do not commence construction within twelve months of the date of approval, your Certificate of Appropriateness will become void and you will need to apply for a new certificate if you still intend to do the work.



DATE: OCTOBER 25, 2016		ISSUE			
SCALE: 1" = 30'	NO.	DESCRIPTION	DATE		
ACREAGE: 0.4165	R-1	REVISE TREES	6/29/21		
LAND LOT(S): 2					
DISTRICT: 18th					
CITY:					
COUNTY: DEKALB STATE: GEORGIA					
SURVEYED: MAF DRAWN: MWR					
CHECKED: WGH APPROVED: CAM					
PROJECT #: 16-257					

BOUNDARY, TOPOGRAPHIC, AND TREE SURVEY FOR:

1176 LULLWATER ROAD


PART OF LOT 27C, BLOCK 13, DRUID HILLS S/D LAND LOT 2, 18th DISTRICT, DEKALB COUNTY, GEORGIA TAX PARCEL No. 18 054 06 001






GA LAND SURVEYOR, LLC

3355 ANNANDALE LANE, STE 1 SUWANEE, GA 30024







SIMPLE BLACK IRON 36" HIGH GUARDRAIL / HANDRAIL W/ MODEST FLOURISH AT NEWELS. NO FLOURISH ON INDIVIDUAL SPINDLES FOR US ALTHOUGH THAT IS SHOWN IN THIS EXAMPLE.


LULLWATER RESIDENCE 1176 LULLWATER RD ATLANTA, GEORGIA

> EXTERIOR ELEVATIONS

JUNE 25, 2021











1136

1146

GRADE CALCULATED USING DEKALB GIS MAP INFORMATION

FRONT WALL BRICK HEIGHT: 17'-1" (FROM MAIN FLOOR)



1156 NO WAY TO TAKE A STRAIGHT PHOTO

FRONT WALL BRICK HEIGHT: 17'-10"

WHILE WIDTHS ARE CORRECT, ROOF HEIGHT LOOKS MUCH SHORTER THAN IN A DRAWING. THIS RIDGE IS OVER 10' ABOVE EAVE, CALCULATED BY COUNTING BRICKS.



1166

FRONT WALL BRICK HEIGHT: 17'-4"



1176


FRONT WALL BRICK HEIGHT: 18'-4"

Price Residential Design
1176 Lullwater Road photo documentation





Both adjacent houses (this is the rear of the house on North Decatur that faces the project) have two full floors with large attics and basement below because of the extreme topography.



This massive mature (camelia?) hedge will be retained for a visual buffer, though it will be pruned back.



This is one of many examples of Colonial Revival houses along this side of Lullwater Road with dormers on the roof. None of the Colonials nearby the project have a dormer, as we propose, but dormers are nonetheless common. There are only Colonial Revivals in the area of influence so we will continue that style in order to retain the directional emphasis, shape, massing, proportion, rhythm, scale/height, and the architectural features that are prevalent nearby.

1125 Oak Brook Way, Atlanta, Georgia 30319 404-444-5824


Tree Evaluation Report

1176 Lullwater Road, DeKalb County July 6, 2021

Description of property:

This is a vacant undeveloped lot with proposed new construction. Twenty-eight trees exist on the site with three boundary trees noted. There are eight specimen-sized trees on the property and one off site.

Observations: All observations were visual and made from the ground. No invasive tests, underground or aerial inspections were performed. The site visits were conducted on July 1, 2021. Diameters were measured at breast height, 4½ feet above the ground (DBH) and current conditions noted.



1125 Oak Brook Way, Atlanta, Georgia 30319 404-444-5824

PAGE 2 1176 Lullwater Road, DeKalb County

Tree #	Species	Actual DBH	Condition	Specimen	Dead	Buffer	Boundary	Target
1	Water Oak	37"	Bifurcated upper trunk, Covered in vines	Υ	N	N	N	Υ
2	Water Oak	24"	Covered in vines	N	N	N	N	Υ
3	Ash	24"	Covered in vines	N	N	N	N	Υ
4	Ash	18"	Covered in vines	N	N	N	N	Υ
5	Yellow-poplar	18"	Appears Healthy	N	N	N	N	Υ
6	Yellow-poplar	25"	Appears Healthy	N	N	N	N	N
7	Sweetgum	15"	Appears Healthy	N	N	N	N	N
8	Ash	19"	Appears Healthy	N	N	Υ	N	N
9	Loblolly Pine	30"	Appears Healthy	Y	N	Υ	N	N
10	Yellow-poplar	25"	Appears Healthy	N	N	N	N	N
11	Yellow-poplar	12"	Appears Healthy	N	N	N	N	N
12	Loblolly Pine	33"	Termites at the base, <20% LCR	Υ	N	Υ	N	N
13	Beech	41"	1 broken limb, Appears Healthy	Υ	N	N	N	Υ
14	Hardwood	12"	Appears Healthy	N	N	N	N	N
15	Hardwood	15"	Appears Healthy	N	N	N	N	N
16	Loblolly Pine	33"	Appears Healthy	Υ	N	Υ	N	N
17	Yellow-poplar	13"	Appears Healthy	N	N	Υ	N	N
18	Hardwood	12"	Lean >20 degrees, decay in main trunk	N	N	Υ	N	N
19	Yellow-poplar	31"	Appears Healthy	Υ	N	N	N	N
20	Yellow-poplar	28"	Appears Healthy	N	N	N	N	N
21	Tupelo	24"	Appears Healthy	N	N	Υ	N	N
22	Loblolly Pine	28"	Appears Healthy	N	N	N	N	Υ
23	Yellow-poplar	15"	Appears Healthy	N	N	N	N	Υ
24	Yellow-poplar	53"	Appears Healthy	Υ	N	Υ	N	N
25	Pecan	8"	Appears Healthy	N	N	Υ	N	N
26	Yellow-poplar	24"	Roots starting to become eroded, Appears Healthy	N	N	Y	N	N
27	Yellow-poplar	30"	Appears Healthy	Υ	N	Υ	N	Υ
28	Hardwood	10"	Appears Healthy	N	N	Υ	N	N
29	Sweetgum	~18"	Appears Healthy	N	N	Υ	Υ	Υ
30	Hardwood	12"	Appears Healthy	N	N	N	Υ	Υ
31	Post Oak	27"	Appears Healthy	N	N	N	Υ	Υ

Highlighted trees are of specimen size for DeKalb County

1125 Oak Brook Way, Atlanta, Georgia 30319 404-444-5824

PAGE 3 1176 Lullwater Road, DeKalb County

Pictures (not in good condition):



Tree 12



Tree 18







1125 Oak Brook Way, Atlanta, Georgia 30319 404-444-5824

PAGE 4 1176 Lullwater Road, DeKalb County

Final Notes:

Consult with the International Society of Arboriculture for specific guidelines on tree removal, pruning and planting, www.isa-arbor.com.

This letter serves as an assessment of the specified trees. I certify that all the statements in this letter are true, complete, and correct to the best of my knowledge and belief, and that they are made in good faith. All trees will fail. No arborist can state exactly when, where, or how a tree will fail. Live trees that appear healthy may fall as an "act of God" or with significant weather or environmental conditions that cannot be controlled. All recommendations made in this letter are the sole responsibility of the homeowner to address, thus assuming any risk associated with not performing such recommendations.

This information was generated by Heidi Rieckermann Harrington, Certified Arborist (ISA #NY-1074A), Certified Forester (SAF #2756), HRH Trees, LLC.



Clark Harrison Building 330 W. Ponce de Leon Ave Decatur, GA 30030



Chief Executive Officer

DEPARTMENT OF PLANNING & SUSTAINABILITY

STATE WATER DETERMINATION FORM

Director


Michael Thurmond

Andrew A. Baker, AICP

AP#

			FEE PAID:	YES 🗆 NO 🗆 NO FEE APPLIED
Parcel I.D. Number:		Date:		
Site Address:				
Property Owner/Requested	d By:			
Name/Title of Agent:				
IF NOT OWNER, Requested	Ву:			
Phone #:		Fax:		
Address:				
Type of Water Feature:				
□ River □ Stream □ Creel	k □ Branch □ Lak	e 🗆 Reservoir 🗆 Po	nd 🗆 Drainage Sys	stem □ Spring □ Well
Is there flow?		□ Yes □ No (i	f yes)	□ Subsurface
Is there wrested edge vege	tation?	□ Yes □ No		
Is there a defined channel?		□ Yes □ No		
Is it confined entirely on ov	vner's property?	□ Yes □ No		
Are hyrdric soils present?		□ Yes □ No		
Is wetland vegetation preson	ent?	□ Yes □ No _		
Final Determination:	□ State Wat			
	□ Buffers Re□ No State V	Vater observed		
Comments:				

**This form is only good for 12 months from Date Site Visited. Date Site Visited must be within 6 months of any Land Disturbing Activity Permit Application



1 of 1 5/15/2021, 12:08 AM