

404.371.2155 (o) 404.371.4556 (f) DeKalbCountyGa.gov Clark Harrison Building 330 W. Ponce de Leon Ave Decatur, GA 30030

Chief Executive Officer
Michael Thurmond

DEPARTMENT OF PLANNING & SUSTAINABILITY

Application for Certificate of Appropriateness

Director

Andrew A. Baker, AICP

Date Received: Application No.:
Address of Subject Property: 1325 Emory Road Atlanta, Georgia 30306
Applicant: Dave Price - Price Residential Design E-Mail: dave@priceresidentialdesign.co
Applicant Mailing Address: 1595 Nottingham Way Atlanta, Georgia 30309
Applicant Phone(s): 404-245-4244 Fax: 404-245-4244
Applicant's relationship to the owner: Owner □ Architect: □ Contractor/Builder □ Other 💢 <u>Designer</u>
Dwner(s): David Howe E-Mail: davelh206@gmail.com
E-Mail:
Owner(s) Mailing Address: 1325 Emory Road Atlanta, Georgia 30306
Dwner(s) Telephone Number: 404-391-4319
approximate age or date of construction of the primary structure on the property and any secondary structures affected by this project:1947
lature of work (check all that apply):
lew construction □ Demolition M Addition X Moving a building □ Other building changes □

Description of Work:

New accessory building □ Landscaping □

Sign installation or replacement □

Demolish existing underground garage and driveway with retaining walls. Add new garage wing in side corner yard with garage door facing courtyard driveway. Add new primary suite to main floor w two additional bedrooms above and ADU in basement. Also add rear porch and deck with stairs down to new plunge pool in rear yard with max 4' high interlocking block retaining walls in rear. New guest parking pad with gravel driveway off Briarcliff Road. One specimen tree and some small trees to be removed with four new overstory replacements to join heavily wooded front yard.

Other environmental changes

This form must be completed in its entirety and be accompanied by supporting documents, such as plans, list of materials, color samples, photographs, etc. All documents should be in PDF format, except for photographs, which may be in JPEG format. Email the application and supporting material to plansustain@dekalbcountyga.gov An incomplete application will not be accepted.

Fence/Wall

Other

Signature of Applicant/Date



DEPARTMENT OF PLANNING & SUSTAINABILITY

Authorization of a Second Party to Apply for a Certificate of Appropriateness

This form is required if the individual making the request is **not** the owner of the property.

I/ We,	David Howe	F.		
being ow	ner(s) of the property at 1325 E	mory Road	Atlanta, GA	30306,
hereby d	lelegate authority to Dave Pric	e - Price Res	sidential Desig	n
to file an	application for a certificate of app	propriateness in	my/our behalf.	
			Gus Ula	Signature of Owner(s)
				11-17-22

Please review the following information

Approval of this Certificate of Appropriateness does not release the recipient from compliance with all other pertinent county, state, and federal regulations.

Before making any changes to your approved plans, contact the preservation planner (404/371- 2155). Some changes may fall within the scope of the existing approval, but others will require review by the preservation commission. If work is performed which is not in accordance with your certificate, a Stop Work Order may be issued.

If your project requires that the county issue a Certificate of Occupancy at the end of construction, an inspection may be made to verify that the work has been completed in accord with the Certificate of Appropriateness. If the work as completed is not the same as that approved in the Certificate of Appropriateness you will not receive a Certificate of Occupancy. You may also be subject to other penalties including fines and/or required demolition of the non-conforming work.

If you do not commence construction within twelve months of the date of approval, your Certificate of Appropriateness will become void and you will need to apply for a new certificate if you still intend to do the work.

Price Residential Design Photos at 1325 Emory Road






































Price Residential Design Photos at 1325 Emory Road



This photo shows the fully wooded area to the west that will be preserved by utilizing an unnecessary grass lawn area for the new garage rather than extending the house and driveway into the wooded area. The existing front entry gable will be highlighted as a focal point in the current, more compact design rather than being demphasized in design that stretches out in one plane to the east, particularly a design with a street facing garage. The higher existing grade to the east will require extensive regrading for a garage addition in that area, while the current design works with the existing topography to partially bury the front edge of the garage, making it clearly secondary to the much larger and taller existing primary mass.

DeKalb County Parcel Viewer





1325Emory Road Tree Assessment

For:

By: Ben Kent, PLA ISA Certified Arborist SO-7070A PO Box 1354 Oxford, Georgia 30054

February 19, 2023

Assignment

Survey, tag and record the following data for all trees indicated on the supplied plan: tree number, diameter, species, vitality, and other comments relative to condition.

Methods

Information for the following parameters was recorded for each tree and provided in the following survey.

Term	Description		
Tree No.	All trees were tagged on the side of the trunk with an aluminum tag, bearing a unique number to identify trees, at about 2 feet.		
DBH	Diameter of trunk in inches, measured at 4.5' feet above average soil level. Measurements were taken using a forestry diameter tape.		
Species	Listed as the North American common name.		
Condition	Good Tree has excellent vigor and is actively growing without any serious pathogenic problems. Tree exhibits a structural form that is safe and typical of the species.		
	FairTree is in moderate health, but may have a minor pathogenic problem. Some insects and disease could be present. Tree may have minor structural defects, but does not exhibit optimal form for the species in an urban environment. A tree in fair condition may not react favorably to site developments or additional stress.		
	Poor Tree's vigor is low to moderate. It may also have moderate to severe structural defects or a form that is undesirable for the species. Some trees in poor condition are not recoverable and could degrade into a state of advanced decline leading to death.		
	DeadTree is dead.		
	Invasive Trees that are non-indigenous to the Atlanta area, Piedmont region.		
	Hazardous Tree with uncorrectable defects severe enough to pose present danger to people or buildings under normal conditions, as determined by a County Arborist or County Forester.		
Comments	Additional information regarding health and condition of the trees.		


Tree Assessment Data

Tag	DBH	Species	Condition	Notes
1	44	Tulip Poplar	GOOD	
2	6	Burford Holly	POOR	
3	9	Burford Holly	POOR	
4	8	Chinese Privet	INVASIVE	
5	6	Cherry Laurel	INVASIVE	
6	6	Cherry Laurel	INVASIVE	
7	8	Burford Holly	GOOD	
8	6	Cherry Laurel	INVASIVE	
9	41	Northern Red Oak	GOOD	Few large dead limbs, included rock wall
10	6, 8	Tulip Poplar	POOR	Included chain link fence, multi-stem at root crown
11	6	Cherry Laurel	INVASIVE	
12	9	Mulberry	INVASIVE	
13	11	Tulip Poplar	GOOD	
14	9	Cherry Laurel	INVASIVE	
15	6	Cherry Laurel	INVASIVE	
16	9	Ailanthus	INVASIVE	
17	8	Ailanthus	INVASIVE	
18	41	Southern Red Oak	GOOD	Phototrophic lean, few large dead limbs

Tag	DBH	Species	Condition	Notes	
19	36	Southern Red Oak	GOOD	Few large dead limbs	
20	7	Tulip Poplar	GOOD		
21	26	Loblolly Pine	FAIR	Leaning	
22	17	Loblolly Pine	POOR	Fusiform canker at ~ 10'	
23	16	Loblolly Pine	POOR	Contorted, no central lead	
24	23	Loblolly Pine	FAIR	Thin canopy, leaning	
25	18	Loblolly Pine	FAIR	Significant lean	
26	15	Loblolly Pine	FAIR	Contorted central lead	
27	7	Northern Red Oak	GOOD	Asymmetrical canopy	
28	22	Loblolly Pine	GOOD		
29	11	Tulip Poplar	POOR	Rot and decay present at root crown	
30	10	Tulip Poplar	GOOD		
31	10	Tulip Poplar	GOOD		
32	7	Cherry Laurel	INVASIVE		
33	8, 8	Mimosa	INVASIVE		

Supporting Images


Tree # 10 - Included chain link fence.



Tree # 2 and 3 - Burford hollies.




Tree # 22 - Fusiform canker.



Tree # 29 - Rot and decay present at root crown.





96,0 59 Ö

THIS SURVEY PLAT OF EXISTING CONDITIONS ON THE PROPERTY MUST BE USED AS A SINGLE STAND ALONE DOCUMENT. CAN NOT BE SCANNED AND ALTERED, CROPPED OUT COPY/PASTE OR MODIFIED WITH SURVEY LAND EXPRESS TITLE BLOCK, SURVEYOR'S STAMP AND SIGNATURE. THIS SURVEY PLAT CAN BE ONLY ATTACHED AS A SEPARATE DOCUMENT BY ITSELF TO DEVELOPMENT PROJECTS AND SITEPLANS AND CAN NOT BE INSERTED WITH SURVEY LAND EXPRESS TITLE BLOCK, SURVEYOR'S STAMP AND SIGNATURE TO SOME OTHER DEVELOPMENT PROJECTS PREPARED BY ANY OTHER PARTY WITHOUT WRITTEN APPROVAL

VERTICAL DATUM NAVD88

TOP=959.74 INV OUT=950.04 SSMH2 TOP=943.29 INV IN=1032.89 INV OUT=1032.79



IF YOU DIG GEORGIA.
CALL US FIRST 1-800-282-7411 770-623-4344 (METRO ATLANTA ONLY) UTILITY PROTECTION CENTER
IT'S THE LAW

FLOOD NOTE:

I HAVE THIS DATE, EXAMINED THE "FIA_FLOOD HAZARD MAP" AND FOUND IN MY OPINION REFERENCED PARCEL () (IS NOT) IN AN AREA HAVING SPECIAL FLOOD HAZARDS, WITHOUT AN ELEVATION CERTIFICATION SURVEYOR IS NOT RESPONSIBLE FOR ANY DAMAGE DUE ITS OPINION FOR SAID PARCEL MAP ID 13089C0062K EFFECTIVE DATE: 08/15/2019

THE FLOOD INFORMATION ON THIS PLAT HAS BEEN DETERMINED AFTER REVIEW OF MAPS WHICH ONLY APPROXIMATE THE LOCATION OF THE APPLICABLE FLOOD HAZARD AREA A SECOND OPINION OR COMPREHENSIVE FLOOD EVALUATION STUDY IS SUGGESTED FOR MORE ACCURATE INFORMATION. FOR FURTHER INFORMATION CONTACT THE LOCAL DRAINAGE DEPARTMENT, CORPS OF ENGINEERS AND INSURANCE COMPANY OR AN APPRAISER.

THIS PLAT WAS PREPARED TO SHOWN THE APPROXIMATE LOCATION OF THE IMPROVEMENTS AND IS NOT RECORDABLE. FENCES SHOULD NOT BE PLACED USING SIDE DIMENSIONS FROM HOUSE. ALL MATTERS OF TITLE ARE EXCEPTED. THIS PLAT IS SUBJECT TO ALL

LEGAL EASEMENTS AND RIGHT-OF-WAY PUBLIC OR PRIVATE.

24 LENOX POINTE


ATLANTA, GA 30324 FAX 404-601-0941

TEL 404-252-5747

INFO@SURVEYLANDEXPRESS.COM

SURVEY LAND EXPRESS, INC

LAND SURVEYING SERVICES



COORD #20161498

DWG <u>#20161</u>498

ISSUING AUTHORITY. 6. THIS PLAT WAS PREPARED FOR THE EXCLUSIVE USE OF THE PERSON, PERSONS OR ENTITY NAMED HEREON. THIS PLAT DOES NOT EXTEND TO ANY UNNAMED PERSON, PERSONS, OR ENTITY WITHOUT THE EXPRESS

INDICATES GAS LINE

INDICATES FENCE LINE

INDICATES DRAINAGE LINE

WATER METER

JUNCTION BOX

GAS MARKER

LAMP POST

METAL POST

WATER VALVE

HEADWALL

DRAINAGE INLET

FIRE HYDRANT

STAIRS

SURVEY NOTES:

STORM MANHOLE

TRAFFIC/INFO SIGN

GAS METER

AIR CONDITIONER

* SYMBOLS *

ELECTRIC PANEL/METER

SANITARY SEWER MANHOLE

1. STORM SEWER, SANITARY SEWER AND OTHER BURIED UTILITIES MAY HAVE BEEN PAVED OR COVERED OVER. THE LOCATION OF UNDERGROUND

UNDERGROUND MAY VARY FROM LOCATIONS SHOWN HEREON. ADDITIONAL BURIED UTILITIES MAY BE ENCOUNTERED. NO EXCAVATIONS WERE MADE DURING THE PROCESS OF THIS SURVEY TO LOCATE BURIED UTILITIES. BEFORE EXCAVATIONS ARE BEGUN, TELEPHONE, ELECTRIC, WATER AND SEWER, GAS COMPANIES SHOULD BE CONTACTED FOR VERIFICATION OF UTILITY TYPE AND FOR FIELD LOCATIONS.

2. THIS PLAT WAS PREPARED TO SHOW THE APPROXIMATE LOCATION OF THE IMPROVEMENTS AND IS NOT RECORDABLE. FENCES SHOULD NOT BE

EASEMENTS OF RECORD RECORDED AND NOT RECORDED, ENCUMBRANCES,

COMMITMENT, EASEMENTS AND ENCUMBRANCES MAY EXIST WHICH BENEFIT

CLOSING ATTORNEY OR TITLE COMPANY FOR A FULL TITLE SEARCH AND

WARRANT THE ZONING INFORMATION AND INTERPRETATION AS PROVIDED

HEREIN. THIS INFORMATION IS OBTAINED USING ON-LINE SOURCES, TELEPHONE CONVERSATION WITH ZONING OFFICE AT THE COUNTY OR CITY, ETC. AND CANNOT GUARANTEE ITS ACCURACY. IT IS RECOMMENDED THAT

THE CLIENT OR USER OF THIS DATA VERIFY THIS INFORMATION WITH THE

RECERTIFICATION OF THE SURVEYOR NAMING SUCH PERSON, PERSONS,

COMMITMENT INCLUDING ALL THE EXCEPTION.
5. SURVEY LAND EXPRESS, INC IS NOT RESPONSIBLE FOR AND DOES NOT

RESTRICTIVE COVENANTS, OWNERSHIP TITLE EVIDENCE, OR ANY OTHER FACTS THAT AN ACCURATE AND CURRENT TITLE SEARCH MAY DISCLOSE.
4. THIS SURVEY WAS MADE WITHOUT THE BENEFIT OF CURRENT TITLE